SAN JUAN REGIONAL PLANNING COMMISSION AGENDA

September 16, 2025 San Juan County Courthouse

San Juan Regional Planning Commission Meetings shall be conducted in a hybrid virtual/in-person format. All persons including Board Members, Staff, Applicants and interested Public may meet in person or via Zoom. The information necessary to connect to the public meeting is listed below.

7:00 PM Roll Call of Members and Minutes

Minutes of August 19, 2025

7:10 PM Joy Global Underground Mining LLC

Improvement Permit Application for the Demolition of the Lead Carbonate

Mill, Lead Carbonate Mill Site USMS 20726

7:30 PM Cascade Meadows LLC

Subdivision Application for the Construction of up to 72 units on Tract A1

and B1 Cascade Village

8:00 PM Lloyd and Ester Swartz

Overland Estates Preliminary Subdivision Application

OTHER:

Times listed above are approximate.

Discussion of an agenda item may occur before or after the assigned time.

ADJOURN: Next Regular Meeting – 7:00 PM, Tuesday August 19, 2025

Join Zoom Meeting

https://zoom.us/j/92136473203

Meeting ID: 921 3647 3203

One tap mobile

+16699006833,,92136473203# US (San Jose)

+12532158782,,92136473203# US (Tacoma)

Dial by your location

+1 669 900 6833 US (San Jose)

+1 253 215 8782 US (Tacoma)

Meeting ID: 921 3647 3203

The San Juan Regional Planning Commission met virtually via zoom and in the Commissioner meeting room on Aug 19, 2025, at 7:03 PM with roll call showing the following attendance

Bev Rich X Ken Safranski X
Jim Weller X Melissa Childs Absent
Lindsey Halvorson X Austin Lashley X
Jim Harper X

Present via Zoom were Bev Rich, Lindsey Halvorson, Jim Harper, Christopher Langford, Amanda. Present in the San Juan County Meeting Room were William Tookey, Land Use Administrator and Chris Tookey, Secretary, along with Jim Weller, Ken Safranski, Austin Lashley, Lisa Adair, Bill Jones, Mike Luther, Joel and Emily Stalo, Seth Weber and Steve Leisle.

MINUTES: July 15, 2025

Ken Safranski moved to approve the minutes. Austin Lashley seconded the motion. The motion passed unanimously with a show of hands.

COUNTY IMPROVEMENT PERMIT PRELIMINARY/FINAL PLAN APPLICATION TO CONSTRUCT AND OPERATE A 3-SITE CAMPGROUND WITH ASSOCIATED UTILITIES AND IMPROVEMENTS LOCATED AT 1208 LIME CREEK ROAD. ACCESS TO THE SITE WILL BE FROM LIME CREEK ROAD CR1.

The applicant Christopher Langford was present via Zoom.

After presentations from William Tookey, Land Use Administrator, and the background of the project, a period of Public Hearing was called with no comments. After the Public Hearing closed, the Planning Commission members talked about their concerns. Ken Safranski then made a motion to recommend to the San Juan County Commissioners that you approve the proposed County Improvement Permit Application Preliminary/Final Plan with the 10 conditions. Jim Harper seconded the motion; A roll call vote was called and the motion passed unanimously with a yes vote.

A letter was sent to the San Juan County Commissioners for their meeting on September 10.

COUNTY IMPROVEMENT PERMIT AMENDMENT, SKETCH PLAN FOR THE DEVELOPMENT OF A DRIVEWAY EXTENSION. THE PROPERTY IS LOCATED AT 1301 COUNTY ROAD 2 AND WILL BE ACCESSEDBY CR2.

The property is currently owned by Joel and Emily Stalo, who were present in the Commissioner's Room to answer questions.

After discussion of the driveway project from William Tookey, Land Use Administrator and the applicant. A period of Public Hearing was called with no comments. After the

San Juan Regional Planning Commission August 19, 2025

Public Hearing closed, Ken Safranski made a motion to recommend to the San Juan County Commissioners that you approve the proposed County Improvement Permit Application Sketch Plan with the 11 conditions as recommended in the staff report. Jim Harper seconded the motion. A roll call vote was called and the motion passed A letter was sent to the San Juan County Commissioners for their meeting on September 10.

COUNTY IMPROVEMENT PERMIT APPLICATION SKETCH PLAN FOR DEVELOPMENT OF A HYDROELECTRIC SYSTEM AND TURBINE SHED NEAR ARRASTRA CREEK TO PROVIDE ELECTRICITY TO MIKE LUTHER'S CURRENT CABIN. THE PROPERTY IS LOCATED IN ARRASTRA GULCH AND WILL BE ACCESSED BY CR 55.

Mike Luther the applicant and owner was present in the Commissioners Room to answer questions.

After discussion and background of the hydroelectric system and presentations project was presented by William Tookey, Land Use Administrator and the applicant. A period of Public Hearing was called with a comment in favor of how effective small hydroelectric plants are. After the Public Hearing closed, the Planning Commission members talked about their support for this proposed improvement. Jim Harper made a motion to recommend to the San Juan County Commissioners that you approve the proposed County Improvement Permit Application Sketch Plan with the 9 conditions as recommended in the staff report. Lyndsey Halvorson seconded the motion. A roll call vote was called and the motion passed unanimously with a yes vote.

A letter was sent to the San Juan County Commissioners for their meeting on August 13.

COUNTY IMPROVEMENT PERMIT APPLICATION SKETCH PLAN FOR THE HISTORIC PRESERVATION AND RESIDENTIAL USE OF THE TRAM HOUSE LOCATED ON THE BIG GIANT 1156A AND THE CONTENTION 14320. THE PROPERTY IS LOCATED NEAR GOLD LAKE IN LITTLE GIANT BASIN AND WILL BE ASSESSED BY COUNTY ROAD 21A.

The property is currently owned by Larry Zastrow ZLMLLC. The applicant has a contract to purchase the property. Discussion and background of the project from William Tookey, Land Use Administrator and the applicant. A Public Hearing was called with lengthy comments in favor of how effective preservation of historic structures. After the Public Hearing closed, the Planning Commission members talked about their support for this proposed preservation improvement. Ken Safranski then made a motion to recommend to the San Juan County Commissioners that you approve the County proposed Improvement Permit Sketch Plan Application with the 13 conditions. Jim Harper seconded the motion. The roll call vote passed unanimously. The motion passed.

A letter was sent to the San Juan County Commissioners for their meeting on August 13.

San Juan Regional Planning Commission August 19, 2025

The meeting was adjourned at 9:12 PM.

Respectfully Submitted,

Christine M. Tookey, Secretary

		=
¥		

MEMORANDUM

September 16, 2025

TO: San Juan Regional Planning Commission

FR: William A. Tookey

RE: Lead Carbonate Mill Claim USMS 20726

Joy Global Underground Mining LLC f/k/a Joy Manufacturing Company has submitted an Improvement Permit application for the demolition of the Lead Carbonate Mill structure. The property is located in Gladstone and will be accessed by Country Road 110.

The applicant plans to demolish the structure due to liability concerns.

Section 2-102 APPLICABILITY states that the demolition or dismantling of any structure requires a Use Permit or Improvement permit.

San Juan County Master Plan, Chapter 9 Vision states that:

Heritage. Thanks to the continued efforts to conserve historic sites, structures, and resources in town, the county, and in the backcountry, San Juan County and Silverton are national role models for preserving historic structures, landscapes, archives and icons. Goal HA-3 Support and promote the efforts of the San Juan County Historical Society and other entities and individuals to preserve historic/cultural resources

The property is currently owned by Joy Global Underground Mining, and the taxes are current.

The application fees have been paid.

The adjacent landowners have been notified via US Mail of the proposed Improvement Permit application. The list of adjacent property owners and copy of the letter are included.

The property is located in the **Mountain Zoning District and Historic Preservation Overlay District.** requires a minimum parcel or lot area of 5 acres with a setback of 20 feet from public lands and 30 feet from private property lines. The property is 9.43 acres. It appears that the improvements exceed the setback requirements.

The applicant has substantially met the requirements for application submittals as required by 3-102 Requirements for Uses and Improvements.

The proposed improvements should have minimal impact on the adjoining properties. Adjoining property owners have been notified and at this time I have not received any comments from them.

As reflected in the Master Plan, San Juan County has strongly supported the preservation of historic structures and our mining heritage. Recognizing that the remains of the building is in poor condition, it still provides a glimpse to the past.

While it may not be practical for the applicant to preserve the structure they could explore strategies with the San Juan Historical Society for the stabilization and preservation of the structure. This could include grant funding and possibly donation of property to an organization that would be capable of preserving the structure.

The applicant could also preserve the history of the structure by contracting with a firm to provide a archaeological study and report of the site.

Additionally the applicant could install a sign with pictures of the Lead Carbonate and a short history.

The Planning Commission has the option to recommend approval of the application as submitted, approval with conditions, denial of the application or to table the decision until additional information is provided.

Should the Planning Commission choose to recommend approval they should do so with the conditions listed below:

- 1. All work on the Lead Carbonate Mill Sites shall fully and completely comply with, and strictly conform to, all terms, conditions and restrictions contained in the San Juan County Zoning and Land Use Regulation, all permits issued, and all applicable State and Federal rules and regulations.
- 2. That the applicant consults with the San Juan County Historical Society concerning possible alternatives to demolition.
- 3. That the applicant contract with an archeologist to provide and report to preserve the history of the structure.
- 4. That an archeologist is on site during the demolition and that any historic artifacts discovered during the demolition be donated to the Historical Society.
- 5. That the applicant install an informational sign about the history of the Lead Carbonate Mill that is reviewed and approved by the Historical Society.
- **6.** Any other conditions that the Planning Commission deem necessary.

Should the Planning Commission recommend denial they should do so on the grounds that it is located in the Historic Overlay District and that it is contrary to the San Juan County Master Plan.

September 16, 2025

To: San Juan Regional Planning Commission Fr: William A. Tookey, Land Use Administrator Re: Cascade Meadows Subdivision Sketch Plan

Cascade Meadows LLC, 665 Glacier Drive, Unit 5, Durango, CO 81301 has submitted a Subdivision Sketch Plan Application for the development of the Cascade Meadow Subdivision located on Tract A1 and B1.

Tract A1 is owned by Cascade Meadows LLC and Tract B1is owned by Cascade Hospitality, LLC.

The applicant plans to construct up to 72 units on Tract A1 and B1 of Cascade Village Subdivision. The Master Plan approval allowed for 170 units to be constructed in Tract A1. There was no development approved for Tract B1 in part because it is primarily a wetland. The applicant has provided a Wetlands Report from SME they are working with the Army Corps of Engineers for permitting. They likely use a wetlands bank to replace any disturbed wetlands.

The proposed units will be three-story town homes similar to the units being constructed across from Purgatory. They will be approximately 2000 sq. ft. with a garage and driveway.

They plan to use colors and textures so that the units blend with the current units at Cascade Village. They are developing them to be in compliance with the new Wildfire Resilience Code that the State has adopted.

Trautner Geotech LL C has provided a Geologic Hazards Assessment for the property. There is the potential for rockfall and debris flow off the hillside behind the units and plan on constructing a rock fence.

The Durango Fire Protection District has reviewed the plans and has provided comments to the applicant. The applicant will be required to comply with the comments of the DFPD.

Access to the site will be from US Highway 550 using the current access to Cascade Village and developing a secondary access from the southern end of Cascade Village. A State Highway Access Permit Application has been submitted.

When the Master Plan was approved it was determined that the School District would be paid a fee rather than dedicating 10% of the land for public purpose. The applicant has recognized that they will need to enter into an agreement with the School District to include a per unit fee.

The Subdivision Regulations require that a Residential Subdivision designate 10% of the housing units constructed to be permanently affordable to and occupied by low and moderate income households. For purposes of this Section, a low to moderate income is defined as a household with an income not exceeding eighty percent (80%) of the San Juan County median income, adjusted by family size. Affordable housing units are required to be located within the approved subdivision unless approved by the County.

In lieu of providing the affordable housing on site the applicant, with County approval, may meet these requirements with a housing assistance fee sufficient to defray the cost of providing permanent low and moderate income housing off site. For a 72 unit subdivision the applicant would be required to develop 7 affordable units. The applicant has stated that they would prefer to pay a fee in lieu of. Based upon or most recent subdivision that would require a fee of 10% of the sale price for each Town home sold. The fee would be paid to the County at closing and would be earmarked to be used only for workforce and affordable housing.

An Improvement Permit for Road and Utility extensions has been previously submitted to the Planner as part of the original Master Plan approval.

The Planning Commission may recommend to the Board of County Commissioners that the application be approved as submitted, approved with conditions, delayed for additional information of denied. If the Planning Commission chooses to recommend approval the should do so with the following conditions:

- 1. All improvements to the Cascade Meadows Subdivision shall fully and completely comply with, and strictly conform to, all terms, conditions and restrictions contained in the San Juan County Zoning and Land Use Regulation and all permits issued.
- 2. All improvements to the Cascade Meadows Subdivision shall fully and completely comply with and strictly conform to all applicable State and Federal rules and regulations including wetlands.
- 3. That the applicant receives a Colorado Department of Transportation Access Permit.
- 4. That any disturbance to wetlands be properly permitted and adequately remedied.
- 5. The applicant shall fully and completely comply with the San Juan County Zoning and Land Use Regulation 4-110 Design and Development Standards for all Improvement and Use Permits.
- 6. That the subdivision is in compliance with Section 7-120 Air Quality as it pertains to wood burning devices. That the applicant acknowledges that emergency services will not be available in a timely manner and perhaps not at all.
- 7. That the applicant negotiate a per unit fee with the Silverton Public School District.

8.	That the applicant enter into an agreement with San Juan County for a Fee in Lieu of for Affordable Housing

	ā		
		W.	



Division of the Fire Marshal

103 Sheppard Drive • Durango, Colorado 81303 • (970)382-6001 • Fax (970)382-6028

Status: General Comment set by KakavasSE on 4/12/2025 at

11:30:13 AM

Subject: Access - Grade Author: KakavasSE

Date: 4/12/2025 11:26:57 AM

Page Label: [1] 2-1 Emergency Access Road

Color: Layer: Space: The grade for required fire apparatus access road shall not exceed 10% unless approved by the fire code official per IFC

503.2.7, D103.2

Status: General Comment set by KakavasSE on 4/12/2025 at

11:30:16 AM

Subject: Access - Radius **Author:** KakavasSE

Date: 4/12/2025 11:27:06 AM

Page Label: [1] 2-1 Emergency Access Road

Color: E Layer: Space: The turning radius for emergency apparatus roads is 30-feet inside radius as approved by the fire code official. IFC 503,2.4,

Note: Fire District will provide turning templates upon request.

D103.3

Status: General Comment set by KakavasSE on 4/12/2025 at

11:30:21 AM

Subject: Access - Templates

Author: KakavasSE

Date: 4/12/2025 11:27:22 AM

Page Label: [1] 2-1 Emergency Access Road

Color: E Layer: Space:

Status: General Comment set by KakavasSE on 4/12/2025 at

11:30:29 AM

Subject: Access - Width and Clearance

Author: KakavasSE

Date: 4/12/2025 11:27:43 AM

Page Label: [1] 2-1 Emergency Access Road

Color: E Layer: Space: The minimum dimensions for unobstructed access road width not less than 20 feet and a vertical clearance of not less than 13 feet 6

inches as approved by the fire code official. IFC 503.2

Status: General Comment set by KakavasSE on 4/12/2025 at

11:30:32 AM

Subject: Access road - front of hydrant

Author: KakavasSE

Date: 4/12/2025 11:27:54 AM

Page Label: [1] 2-1 Emergency Access Road

Color: **III** Layer: Space: Access road width with a hydrant shall be 26 ft wide exclusive of shoulders. When an approved access road is 20-feet wide there shall be a pullout section adjacent to the fire hydrant. At that point the access road shall be 26-feet wide for 30-feet on both sides of the hydrant for an overall distance of 60-feet. IFC D103.1



Division of the Fire Marshal

103 Sheppard Drive • Durango, Colorado 81303 • (970)382-6001 • Fax (970)382-6028

Fire dept comments_Meadowview Rd 4-12-2025

General Comment (17)

Status: General Comment set by KakavasSE on 4/12/2025 at

11:30:00 AM

Subject: 1-Major SIte Review - County

Author: KakavasSE

Date: 4/12/2025 11:25:56 AM

Page Label: 1
Color: Layer:
Space:

A major site review has been conducted. The major site review of the preliminary plat is for planning, boundaries, access roads, and easements.

Any questions or comments regarding the review please contact me at 970-382-6026 or shane.kakavas@durangofire.org

We look forward to working with everyone on this project

Status: General Comment set by KakavasSE on 4/12/2025 at

11:30:36 AM

Subject: Access - All Weather

Author: KakavasSE

Date: 4/12/2025 11:28:24 AM

Page Label: [1] 2-1 Emergency Access Road

Color: Layer: Space:

Required fire apparatus access road(s) shall be an all-weather driving surface such as asphalt, concrete, chip seal, or similar materials and be able to support 75,000 lbs. IFC D102.1

Status: General Comment set by KakavasSE on 4/12/2025 at

11:30:24 AM

Subject: Access - Cul-de-sac

Author: KakavasSE **Date:** 4/12/2025 11:27:33 AM

Page Label: [1] 2-1 Emergency Access Road

Color: Layer: Space: The turn-around cul-de-sac shall have a minimum 30-foot inside radius and 96-feet in diameter. Hammerheads, Y or other designs shall be approved by the fire code official, IFC 503.2.4

,

Status: General Comment set by KakavasSE on 4/12/2025 at

11:30:41 AM

Subject: Access - Culvert Author: KakavasSE

Date: 4/12/2025 11:28:51 AM

Page Label: [1] 2-1 Emergency Access Road

Color: Layer: Space:

Any culverts crossing under access roads shall support 75,000 lbs

Status: General Comment set by KakavasSE on 4/12/2025 at

11:30:09 AM

Subject: Access - Dead-end **Author**: KakavasSE

Date: 4/12/2025 11:26:49 AM

Page Label: [1] 2-1 Emergency Access Road

Color: Layer: Space: Dead-end fire apparatus access road(s) more than 150 feet in length require a turn-around approved by the fire code official. IFC D103.4



Division of the Fire Marshal

103 Sheppard Drive • Durango, Colorado 81303 • (970)382-6001 • Fax (970)382-6028



Status: General Comment set by KakavasSE on 4/12/2025 at

9:58:55 AM

Subject: Knox Padlock Model 3781

Author: KakavasSE

Date: 4/12/2025 9:57:30 AM

Page Label: [1] 2-1 Emergency Access Road

Layer: Space:



Status: General Comment set by KakavasSE on 4/12/2025 at

Subject: Secondary access

Author: KakavasSE

Date: 4/12/2025 9:58:38 AM

Page Label: [1] 2-1 Emergency Access Road

Color: Layer: Space:

Secondary access road to be maintained year-round. Do not pile snow in front of the gate. Secondary access gate to be equipped with property manager's lock to ensure road is clear, the other shackle lock, Model 3781 can be purchased from Knox.com for

fire department use.



Division of the Fire Marshal

103 Sheppard Drive • Durango, Colorado 81303 • (970)382-6001 • Fax (970)382-6028

Status: General Comment set by KakavasSE on 4/12/2025 at

11:31:09 AM

Subject: Existing hydrants Author: KakavasSE

Date: 4/12/2025 11:31:04 AM

Page Label: [3] 2-3 Meadowview North Plan and Profile

Color: Layer: Space:

From what our office has been told this fire hydrant is currently our of service and has been for some time.

Please repair summer 2025, thank you.

Status: General Comment set by KakavasSE on 4/12/2025 at

11:31:17 AM

Subject: Fire Flow - Hydrants

Author: KakavasSE

Date: 4/12/2025 10:12:15 AM

Page Label: [3] 2-3 Meadowview North Plan and Profile

Color: Layer: Space:

Fire flow is required per the adopted fire code for structures and is determined by overall size and construction type of structures. Fire flow to be provided with the required amount of fire hydrants including duration as indicated within the International Fire Code.

Actual location(s) of hydrant(s) have not been finalized as part of this review.

Hydrants to be supplied with a minimum 6 inch central water supply line.

Status: General Comment set by KakavasSE on 4/12/2025 at

11:31:23 AM

Subject: Hydrant - Fire Flow Author: KakavasSE Date: 4/12/2025 10:12:23 AM

Page Label: [3] 2-3 Meadowview North Plan and Profile

Color: Layer: Space:

A fire flow test and report to be provided to our office of the new and surrounding fire hydrants to ensure the fire flow requirement is available prior to arrival of any combustible materials for the site including vertical construction. IFC 507 and 507.1

Status: General Comment set by KakavasSE on 4/12/2025 at

11:30:46 AM

Subject: Hydrant-Proposed Author: KakavasSE Date: 4/12/2025 10:01:19 AM

Page Label: [2] 2-2 Meadowview North Plan and Profile

Color: Layer: Space:

Hydrants to be "RED" and equipped with a 5" Storz and (2) 2-1/2" NHT connections and in-line with with the local water purveyor's equipment requirements. Preferred hydrants, Mueller-Super Centurion or Kennedy as it meets the fire departments

requirements.

Status: General Comment set by KakavasSE on 4/12/2025 at

11:31:13 AM

Subject: Hydrants at or above 7,000 feet

Author: KakavasSE Date: 4/12/2025 10:12:35 AM

Page Label: [3] 2-3 Meadowview North Plan and Profile

Color: Layer: Space:

Hydrants located at or above 7,000 feet requires an eighteen inch(18") extension and hydrant flag.



Division of the Fire Marshal

103 Sheppard Drive · Durango, Colorado 81303 · (970)382-6001 · Fax (970)382-6028

Fire dept comments #2 Meadowview Rd 8-4-2025

KakavasSE (4)

Status: General Comments set by KakavasSE on 8/4/2025 at

2:25:36 PM

Subject: 1 - Preliminary Development Review

Author: KakavasSE Date: 8/4/2025 2:25:22 PM

Page Label: [1] 1-1 Overall Grading Plan

Color: E Layer: Space: This preliminary development review does not include a complete fire code plan review for construction as the information is limited.

Any questions or comments regarding the review please contact me at 970-382-6026 or shane.kakavas@durangofire.org

We look forward to working with everyone on this project

Status: Required Element set by KakavasSE on 8/4/2025 at

2:25:40 PM

Subject: Hydrant - Fire Flow

Author: KakavasSE Date: 8/4/2025 2:24:34 PM

Page Label: [1] 1-1 Overall Grading Plan

Color: **=** Layer: Space: A fire flow test and report to be provided to our office of the new and surrounding fire hydrants to ensure the fire flow requirement is available prior to arrival of any combustible materials for the site including vertical construction. IFC 507 and 507.1

Contact our office as the fire hydrants are installed so we witness the flow tests and verify actual locations of each fire hydrant.

Status: Required Element set by KakavasSE on 8/4/2025 at

2:25:44 PM

Subject: Secondary access Author: KakavasSE Date: 8/4/2025 2:24:39 PM

Page Label: [1] 1-1 Overall Grading Plan

Color: Layer: Space:

Secondary access road to be maintained year-round. Do not pile snow in front of the gate. Secondary access gate to be equipped with property manager's lock to ensure road is clear, the other shackle lock, Model 3781 can be purchased from Knox.com for fire department use.

Contact our office to inspect the gate location. Also contact our office when the Knox padlock arrives and is ready to be installed on the access gate.

Status: General Comments set by KakavasSE on 8/4/2025 at

2:06:40 PM

Subject: Occupancy Author: KakavasSE Date: 8/4/2025 2:15:36 PM

Page Label: A-102 - FLOOR PLAN

Color: Layer: Space:

The following conceptual architectural, sectional, and site plans were not reviewed or approved for construction. Should the Building Code Official determine the structure(s) are multi-family units then the structure shall be equipped with a fire suppression system.

Sheets AS-101, A-101, A-102, A-401, and A-402 only viewed, not reviewed.

			-



Division of the Fire Marshal

103 Sheppard Drive · Durango, Colorado 81303 · (970)382-6001 · Fax (970)382-6028

Fire dept comments #2 Meadowview Rd 8-4-2025

KakavasSE (4)

116.00

Status: General Comments set by KakavasSE on 8/4/2025 at

2:25:36 PM

Subject: 1 - Preliminary Development Review

Author: KakavasSE Date: 8/4/2025 2:25:22 PM

Page Label: [1] 1-1 Overall Grading Plan

Color: Layer: Space:

This preliminary development review does not include a complete fire code plan review for construction as the information is limited.

Any questions or comments regarding the review please contact me at 970-382-6026 or shane.kakavas@durangofire.org

We look forward to working with everyone on this project

Status: Required Element set by KakavasSE on 8/4/2025 at

2:25:40 PM

Subject: Hydrant - Fire Flow Author: KakavasSE Date: 8/4/2025 2:24:34 PM

Page Label: [1] 1-1 Overall Grading Plan

Color: Layer: Space:

A fire flow test and report to be provided to our office of the new and surrounding fire hydrants to ensure the fire flow requirement is available prior to arrival of any combustible materials for the site including vertical construction. IFC 507 and 507.1

Contact our office as the fire hydrants are installed so we witness the flow tests and verify actual locations of each fire hydrant.



Status: Required Element set by KakavasSE on 8/4/2025 at

2·25·44 PM

Subject: Secondary access Author: KakavasSE Date: 8/4/2025 2:24:39 PM

Page Label: [1] 1-1 Overall Grading Plan

Color: Layer: Space:

Secondary access road to be maintained year-round. Do not pile snow in front of the gate. Secondary access gate to be equipped with property manager's lock to ensure road is clear, the other shackle lock, Model 3781 can be purchased from Knox.com for fire department use.

.............

Contact our office to inspect the gate location. Also contact our office when the Knox padlock arrives and is ready to be installed on the access gate.

.....



Status: General Comments set by KakavasSE on 8/4/2025 at

2:06:40 PM

Subject: Occupancy Author: KakavasSE Date: 8/4/2025 2:15:36 PM

Page Label: A-102 - FLOOR PLAN

Color: Layer: Space:

The following conceptual architectural, sectional, and site plans were not reviewed or approved for construction. Should the Building Code Official determine the structure(s) are multi-family units then the structure shall be equipped with a fire suppression system.

Sheets AS-101, A-101, A-102, A-401, and A-402 only viewed, not reviewed.



ARCHITECTURE & ENGINEERING

08-07-2025

CASCADE MEADOWS SUBDIVISION

To: Shane Kakavasse Durango Fire Protection District

Shane,

See our responses to the comments in the 08-04-2025 Review of the Cascade Meadows Submittal. overall for Cascade Village, which is required per IFC and DFPD.

- Noted.
- 2. Fire flow test will be performed once fire line is installed.
- 3. Maintenance of the road will be provided year round.
- 4. Noted. All residential units will be sprinklered.

Please review and let us know if you have any questions.

Thank you,

Lauren Davis, AIA, AICP

San Joan County, Colorado

Application for Improvement Permit

Num	E Lauron Davis Architoct	-	APPROVAL CHECKLIST	Initial	Date
Lauren Davis, Architect			Land Use Administrator		
504 E. Zilu Ave. Suite 201		Ownership of Surface	1		
Name		-	Ownership of Minerals	LD	
	Cascade Meadows LLC	-	Vicinity Map	1.5	+
Addi	ress 665 Glacier Drive, Unit 5 Durango, CO 81301 704-362-2400	Phone	Certified Survey Plat	LD	
-		HOHE	Monumentation	LD	
Nam					
Addr			Basic Plan Map	LD	
		hone	Plans and Drawings	LD	
Legal Description of Property:		Road System Relationship	LD	_	
			Zoning Compatibility	LD	
See	attached survey and map. A-1 and Tract B-1to be updated with a new parcel		State Mining Permit	NA	
and b	build out.	[Owner Notification	LD	
	T39N, R9W N.M.P.M. Juan County Colorado		Avalanche Hazard	NA	
		Ī	Geologic Hazard	NA	
		Ì	Floodplain Hazard	NA	
		Ì	Wildfire Hazard	NA	
Tov	wiship N, Range W, Section		Mineral Resource Impact	NA	
Nature	of Improvement Planned:		Wildlife Impact	NA	
Pron	osed updated subdivision		Historic Site Impact	NA	
		Ì	Watershed Gearance	NA	
		Ì	Building Permit	NA	
		1	State Electrical Inspector		
Land U	se Zone: PD		Electrical Permit		
Applica	int Signature Lauren Davis, RA+A		San Juan Basin Health Unit		
	Eddion Davis, 144.74	ı	Sewage Disposal: Test	1	-1
		-	Design		
Date A	pplication Requested	_	Central Sewage Collection	LD	
	abmitted for Permit	-	State Division of Water Resources		
	ermit Issued	_	Adequate Water Source	LD	
	ermit Denied		Well Permit	- 100	_
			. Central Water Distribution	_	+
Reason for Denial		L.S. Forest Service/BLM			
			Access Approval	INA	
			. recess typicorai		+
			State Division of Highways		
Receipt	FEE PAYMENT Amount Date		Driveway Permit	LD, IP	
	Application	-		1 -	
	Building Permit				
_	Subdivision/PUD		Subdivision Variance	-	
	Hearing Notice		Subdivision Approval	LD, IP	
	1 1	- 8	PUD Approval		+



ARCHITECTURE & ENGINEERING

07-20-2025

CASCADE MEADOWS SUBDIVISION

For Application for Improvement Permit

To: Willy Tookey San Juan County Administrator 970-387-5766 San Juan County, Colorado

Willy,

Reynolds Ash and Associates (RAA) is pleased to submit a subdivision package for your review for the proposed Cascade Meadows Subdivision.

Completed Application (RAA)

Project Narrative (RAA)

Proposed Layout of Residential Units, driveways and overall improvements (RAA)

Proposed Grading Plan and Design (CHC)

Drainage Plan - pending (CHC)

Survey (Moreno)

Preliminary Plat (Moreno)

Geohazards including avalanche map and rock fall and debris flow report (CHC/Trautner)

Soils Report (Trautner)

Ownership Info (Cascade Meadows, LLC)

Statement of Utility Capacity (Dave Marsa, Grizzly Peak Water Sales and Distribution, LLC)

Wetlands Statement (SME)

Project Overview

The proposed subdivision is for the development of a maximum of 72 dwelling units along Meadow View Road. The proposed development is part of the original Master Plan for Cascade Village. The original master plan proposed approximately 170 units for Tract A1/Tract B1 on the southern end of the site.



The design team and owner have analyzed topography, wetlands, soil conditions, traffic and overall market conditions. The site presents numerous challenges with the soil conditions of the wetlands, the steep slope to the west. The proposed package will reduce overall density with a simpler layout of townhomes. The townhomes will line Meadowview Drive. Most of the units will be built on the west side of the road and into the hillside. The others will line the wetlands where the impact is minimal.

The proposed products will be three story townhomes. The design takes advantage of views across the highway and to the mountains on the east. The scale will be similar to the existing townhomes constructed across from Purgatory Resort. Each townhome is approximately 2,000 square feet with a garage and small driveway in front of the unit. The building envelope will include a mix of metal and wood siding. Overhangs, covered decks and awnings will add interest and protection to the buildings. The rooflines will be broken up to help with snow removal, but also to add interest to the envelope.

The proposed project will line the bottom of the tree line and edge of the wetlands. The colors and materials will be darker and contextual to help the proposed subdivision tie into the rest of Cascade Village. The development will not negatively impact the scenic view corridor and will be similar in scale, color and material palette to the rest of the development in this part of the Highway 550 corridor.

The required utilities for the townhomes has been designed and incorporated into the civil package. Water and sewer service lines will serve each unit and tie into an overall main line that runs along Meadowview Dr. Power to each footprint will be provided by LPEA and also run in the utility easement. Communications and fiber will also run along the street and serve each building. The design team has coordinated with the local utility provider to ensure that sewer and water capacity is adequate.

Landscaping for each dwelling unit will be required and help to soften the edges of the buildings and tie into the existing landscape. Landscaping will also include sidewalks that will connect the development back to the south and other trails in the area.

Due to the analysis of rock fall and debris flow, a rock fence is proposed along the backside of the units. The final design of the rock fence will be a deferred submittal but will protect the new townhomes and be integrated into an attractive landscape design. The rock fall fence will also help in defining defensible space on the back side of the units to further protect them and meet the new Wildfire Resilience Code.

The project will trigger a new turn lane on the highway, which will be part of the improvements. The new turn lane is currently being reviewed by CDOT and being designed by SEH Engineers. The highway work will begin when the build out triggers the threshold of trips. An easement has been established between the owner of Cascade Meadows and the adjacent property owner to the south (Ozone Cubed). This agreement was presented in the previous land use improvement application to begin the extension of Meadowview Drive. This easement and new entry off the highway will serve as the main entry to this proposed development. This will provide a second exit overall for Cascade Village, which is required per IFC and DFPD.

General Notes and Considerations for the proposed development:


- 1. DFPD has reviewed the plans. Comments Pending
- 2. Addressing for the parcels will be approved by DFPD and SJC.
- 3. All improvements will comply with the design and construction recommendations of DFPD.
- 4. The project will comply with the Wildfire Resiliency Code, per the State of Colorado.
- 5. A recent survey has been provided and includes all boundary, easements, etc.
- 6. A map showing Wetlands has been provided. Full impact of wetlands has been calculated and an application has been submitted to the Army Corps of Engineers for Approval. The developer is proposing to mitigate the impact by land banking with the Animas River Wetlands.

- 7. All work will be completed within the property lines as shown. No work will occur outside of the property lines.
- 8. There is not an HOA as part of this development at this time. The developer is working on a Special District. Currently, the public utility will maintain all parts of the development until the Special District is formed.
- 9. As part of the Building permit application, the applicant shall submit to the County Building Department, a copy of the storm water management plan/permit (SWMP), processed according to the current CDPHE regulations, and shall utilize BMP's specified on the SWMP Plan and or in compliance with CDPHE regulations.
- 10. A preliminary plat is included in the submittal. A licensed surveyor (Moreno) will file a final as-built plat with San Juan County once construction is complete.
- 11. The developer and project consultants shall comply with all Conditions of Approval including but not limited to CDPHE, OSHA, UNCC, COOT, San Juan County Land Use Regulations and the Army Corpse of Engineers.
- 12. The project will coordinate with LPEA for all power to the development.
- 13. The Applicant shall prepare/submit an agreement for County review regarding the required school fees.
- 14. Owner agrees to provide fee in lieu for workforce housing

Please review and let us know if you have any questions. We look forward to working with San Juan County on this project.

Thank you,

Lauren Davis, AIA, AICP




Site Plan





THERE IS STRUCTION





FLOOR PLAN





ROOF

3 UPPER LEVEL

FLORGO FRECHOS




CASCADE VILLAGE TOWNHOMES


A-102


TBD

JOB NO 24029 ISSUE DATE: 7/2/2025



SECTIONS





EXAMPLE 1 SITE CONTEXT

OLLORO OS ERLOSION



CASCADE VILLAGE TOWNHOMES

A-402

TB

JOB NO. 24029 ISSUE DATE: 7/2/2025

SCENIC COKKIDOK NIEMS






CASCADE VILLAGE TOWNHOMES SD 100


+ PSSOCIATES





EQUATE IVITEDSIVOS


10B NO 24029























TABLE A

		LE	NGT	H RES	STRAIN	ED (L)	
Ì					ARGE		
\neg		3*	4**	6"	8"	10"	12*
	3"	\sim	20'	40'	50'	70'	80'
7	4**	\times	$>\!\!<$	30'	50'	60'	80°
SMALI	6*	\times	> <	> <	30'	50'	70'
0,	8*	\sim	> <	\sim	><	30'	50'
	10"		>	$\overline{\mathbf{x}}$	\sim	$\overline{}$	50

TABLE A NOTES:

1) FLOW FROM LARGE SIZE TO SMALL SIZE PIPE.

TABLE C


		LEN	IGTH	REST	RAIN	ED (L))
			BRANCI	H (RES	STRAIN	ED)	
		3"	4*	6*	8*	10"	12"
	3"	5*	10'	30'	50'	70'	80'
-	4**	5'	10'	30'	50'	70'	80,
RUN	6"	5"	10'	20'	40'	60'	70'
"	8"	5'	10'	10'	30'	50'	70'
	10"	5'	10'	10'	30'	50'	60'
	12"	5'	5*	5*	20'	40'	60'

TABLE C NOTES:

- SHORTEST DISTANCE ALLOWABLE BETWEEN TEE END AND FIRST PIPE JOINT ON MAIN RUN IS 5 FEET.
- FLOW DIRECTION THROUGH TEE DOES NOT AFFECT LENGTH OR JOINT TO BE RESTRAINED.

TABLE B

				LENGTH	I TO BE RESTRA	INED (L)		
	90°	45° HORIZ ELBOW	22½* HORIZ ELBOW	11¼° HORIZ_ELBOW	45° VERT. OFFSET 3.5° TO 5.0°	22½" VERT. OFFSET 3.5" TO 5.0"	11¼° VERT. OFFSET 3,5' TO 5.0'	DEAD END/ IN-LINE VALVE
3"	10'	5'	5*	5'	UPPER - 20' LOWER - 10'	UPPER - 10' LOWER - 5'	UPPER - 10' LOWER - 5'	30'
4=	20'	10'	5*/	5'	UPPER - 20' LOWER - 10'	UPPER - 10' LOWER - 5'	UPPER - 10" LOWER - 5"	40'
6**	20'	10'	5"	5"	UPPER - 30' LOWER - 10'	UPPER - 20' LOWER - 10'	UPPER - 10' LOWER - 5'	50'
В*	30'	10'	10'	5'	UPPER - 40' LOWER - 10'	UPPER - 20' LOWER - 10'	UPPER - 10* LOWER - 5*	70*
10"	30'	20'	10'	5*	UPPER - 50' LOWER - 20'	UPPER - 30' LOWER - 10'	UPPER - 10' LOWER - 5'	80'
12"	30'	20'	10'	5	UPPER - 50' LOWER - 25'	UPPER - 30' LOWER - 15'	UPPER - 15' LOWER - 10'	90'



MECHANICAL JOINT RESTRAINT DETAIL

NOT TO SCALE

TYPICAL TRENCH SECTION
UNSURFACED AREAS
NOT TO SCALE

NOTE: EXISTING GRADE FOR TOP OF TRENCH IS GROUNDLINE AT TRENCH OR THE ADJACENT ROADWAY WHICH EVER IS LOWER

24" MIN.

EXISTING GRADE -

INITIAL BACKFILL ZONE -

PIPE BEDDING ZONE

FINAL BACKFILL ZONE -

NEW CONCRETE TO MATCH EXISTING
PAVEMENT, SIDEWALK OR CURB AND
GUTTER DAMAGED OR REMOVED

12" MIN.

FINAL BACKFILL ZONE

PIPE BEDDING ZONE

WHERE PAVEMENT IS OTHER THAN
CONCRETE, BASE COURSE DEPTH SHALL
MATCH EXISTING AND WEARING SURFACE
SHALL MATCH ORIGINAL

EXISTING PAVEMENT
SAWCUT PAVEMENT

NOTE: EXISTING GRADE FOR TOP OF TRENCH IS GROUNDLINE AT TRENCH OR THE ADJACENT ROADWAY WHICH EVER IS LOWER

TYPICAL TRENCH SECTION PAVED AREAS

Chic Engineers . W

Project Date: 2025-07-22

DRIVE

DETAILS

for review only

Draft

Document


Not For


Construction


not for construction


Proj: 23028


NOT TO SCALE

















Document Draft for review only DRIVE 01 U A U 10 -

Project Date: 2025-07-22 Proj: 23028


50 Valley Court Durango, CO 970-387-8765


CAC Engineers, LLC

upriconvisuos voi 100

Construction

Not For






SAN JUAN COUNTY, COLORADO TRACT A-1 & TRACT B-1 S13, T39N, R9W, N.M.P.M. CASCADE MEADOWS CASCADE VILLAGE Subdivision

Land Use Table

Lot Acres (R) Acres (M)

Tract A-1 & B-1 79.35 Acres (M)
13.47 Acres
62.22 Acres
3.664 Acres



at Cascade Meadows, LLC, whose addruss is 665 Glacter Cluib Drive A6 Durango, CO 81301, being the Ugal und record comners of Android cland located within S1/2 of Section 12, T39N, R9W, NM.P.M., in San Juan County, Colorado more particularly described Android

ed May 7, 1981 in Book 222 at Payes 125, 126 and 127. at Cascade Village Plat recorded August 6, 1985 in Book 230

commonly known as Tracts "A-1" and "B-1" of the Cas ding to the plat thereof file

THIS PLAT IS HEREBY EXECUTED BY THE FOLLOWING PARTIES

BOARD OF COUNTY COMMISSIONERS OF SAN JUAN COUNTY, COLORADO

This plat is hereby approved by the Board of

checking, and that, in my professional opinion, they are true and ofessional Land Surveyors in the State of Colorado. I also state I hereby state that this survey and plat was prepared by me or under my direct responsibility, superviet to the best of my forowledge belief and information based on the applicable standards of practivits extress and plat is not a guaranty or warranty, either expressed or implied. CERTIFICATE OF SURVEYOR

PRELIMINARY

Joshua J. Casselberry, P.L.S. Colorado Registration No. 37903


Notice Title Research - Title, essement and Kight-of-Way research was conducted by Colorado Title & Closing Services, LLC, order No. 5/22103593-4 effective December 5, 2021 at 5:00 K hi and not form research conducted by Normon Sarveying & Geographics, Inc. Any and all parties having interest in subject tracts of land are hereby referred to said vittle commitments and may the policies issued at a later date.

Notice: According to Colorado law you must commence any legal action based upon any defect in this survey within three (3) years after you first di event may any action based upon any defect in this survey be commenced more than ten (10) years from the date of the certification shown hereon

CASCADE MEADOWS
SUBDIVISION
CASCADE VILLAGE
TRACT A-1 & TRACT B-1
SI3, T39N, R9W, N.M.P.M.
SAN ILIAN COUNTY, COLORADO

SURVEYING GEOGRAPHICS

VN BY: IMICHECKED BY: IL. 10B NO; 2024




12	1	5	E6	7	5	5	17		
	(M)	Te (W)	(M)	L4 (M)	(M)	L2 (M)	T1 (M)	L#	
	L7 (M) N 19.12.22" W 205.27" L15 (R) N 84.58,11" E 172	N 9.38,29, €	L5 (M) N 76'36'22" E	N 76'36'22" E	L3 (M) S 76.01,49" E	N 5'24'34" E	N 89"58'53" E	Direction	Line Table
	205 27'	76,52'	13,85	13,85'	144.57	70,51	16,73'	Length	
	L15 (R)	L14 (R)	L13 (R)	L12 (R)	L11 (R)	L10 (R)	L9 (R)	L#1	
	N 84'58'11" E	S 9'38'59" W	L13 (R) S 76'36'22" W	L12 (R) S 17'17'17" W	S 43'34'59" E	L10 (R) S 76'01'49" E	N 5'24'34" E	Direction	Line Table
	17:	76.5	13.8	39.1	74 C	144	70,5	Leng	

		2	Chine lable		
C#	Length	Radius	Detta	Chord	Chord Bearing
C1 (M)	78.20'	69,05'	64.53'27"	74,09'	N 43"34"59" W
C2 (M)	41.57'	35.00'	68"03"08"	39_17'	N 17'17'17" E
C6 (M)	151,49'	700,00	12'24'00"	151.20'	S 1'22'12" E
C7 (M)	314.02	721.94	24.55'17" 311.55'		S 20:01'51" E
C8 (M)	46_16	300,00'	8'49'00"	46,12'	S 28'25'42" E
C9 (M)	118.65	321,38'	21.09.11" 117.98'	117,98'	S 16'45'42" E
C10 (M)	137.95'	350,00	22'35'00"	137.06'	N 21.32'42" W
241 (11) -222		******	*E0 00' 11:08'30" 60 07'	60.07	W 1.50,03.1 W

SAN JUAN COUNTY, COLORADO TRACT A-1 & TRACT B-1 CASCADE MEADOWS T39N, R9W, N.M.P.M. CASCADE VILLAGE SUBDIVISION





- m cap stamped "PLS 16399" m cap stamped "PLS 22574" m cap stamped "PLS 29026" m cap stamped "PLS 25968" m cap stamped "CASSELBERI

SURVEYOR STATEMENT:
This tengeraphic survey of a pertion of Cascade Village, Tracts A1 & P-1 as shown on the Cascade Village Results of Survey plat recorded on October 19, 2005 at Reception No This tengeraphic survey of a pertion of Cascade Village, Tracts A1 & P-1 as shown on the Cascade Village Results of Survey plat recorded on October 19, 2005 at Reception No 191 in the San Jean County Surveyor's Land Survey Plats was atrial surveyed by Geospatial Applications, LLC on May 19, 2024 under the direct responsibility, supervision and checking of Joshua J Cascaderry, of Moreno Surveying and Geographics, Inc., being a Colorado Licensed Surveyor. It does not constitute a Land Survey Plat or Improvement survey Plat as defined by section 3.6.51.102 C.R.S.

PRELIMINARY


SUBDIVISION
CASCADE VILLAGE
TRACT A-1 & TRACT B-1

SI3, T39N, R9W, N.M.P.M. SAN ILIAN COLINTY, COLORADO

CASCADE MEADOWS

SHEET 2 OF 2

DRAWN BY: MI CHECKED BY: 1





STVLOL 148.44 Ac. 3.27 UNITS/Ac. 6.35 Ac. COMMERCIAL/RECREATION Ð WYINLENVNCE/SEMEK .5A 88.4 OPEN SPACE RESIDEALIVE .0A\ZTINU 81.8 .0A 71.9 TODGE/COMMERCIVT 4.91 Ac. 19.55 UNITS/Ac. BHVZE S RESIDENTIAL 2.25 Ac. V-I JSVHd COMMERCIVI OBEN SBVCE I ISVHd .5A\ZTINU 33.3 .5A 73.31 IIIRESIDENTIAL/COMMERCIAL KEZIDENLIVT 14.22 Ac. 1.83 UNITS/Ac. LIMITICHI MEYDOM KEZIDENLIVT 29.26 Ac. 6.05 UNITS/Ac. TRACT B (AND FOTOME PRACES) OPEN SPACE .58.91 Ac. TRACT A NALLS VEEV TAAAT DEDICATION DENZILL OBICINAL MASTER PLAN

1774 0001 = "1 :3TVOS

MICINILL WAP

SYSCADE VILLAGE

STVLOL 148.44 Ac. 3.27 UNITS/Ac. COMMERCIAL/RECREATION .35 Ac. Ð .5A 62.4 WAINTENANCE/SEWER OPEN SPACE .0A EB.4 RESIDENTIAL 0.17 Ac. 8.18 UNITS/Ac. TODGE/COMMERCIVE 3.48 Ac. S JSVHA 4.91 Ac. 19.55 UNITS/Ac. KEZIDENLIVI V-I ∃SVHd COMMERCIAL/OPEN SPACE .28 Ac. BESIDENLIVT\COMMERCIVT 16.67 Ac. 6.66 UNITS/Ac. I ISVHA RESIDENTIAL 14.22 Ac. 1.83 UNITS/Ac. LIMITICHL MEVDOM 10.48 Ac. I-A TOART OPEN SPACE UM KESIDENLIVT 71.69 Ac. 2.47 UNITS/Ac. 221 I-A TOART DENSILL NAITS AREA TRACT WEINDED WYZLEK BIYN

555 SOUTH CAMINO DEL RIO (303) 247-1705 (303) 247-1705

ENCINEERING & SURVEYING

This project was reviewed and approved by the Board of County Commissioner


CALE: 1" = 200 FEET DATE: OCTOBER 26, 195 PREPARED BY: D. COSTER CHECKED BY: T. WHITE

NWZLEK PLAN

CASCADE VILLAGE

 $\Gamma C = 2 \frac{13378}{2410.00}$ E E = 103100. $\nabla = 03.238$. 3 90,01,00 S 1019,80 112'20. E -038 YAWHDIH . S.U.

TYND OSE LVBIE



9021-277 (026) DURANGO, COLORADO 81302 26 XOE 'O'd COLL ENCINEERING VAD SORVEYING, INC. ENCINEER AND SURVEYOR: 0098-698 (026) DURANGO, COLORADO

OSS YAWHDIH .S.U 72803 CYSCYDE AITTYCE INAESLWEAL AEALOBE DEARTOLED BX:

> SYN INYN CONNIK' COTOBYDO TOCYLED IN SECLION 13' L 38 N' H 8 M' N'W'B'W'

NYTA HILSYN GIGNIWY EVERYDE AITTYCE

		E
		.=
	*	



Traffic Impact Study – Draft Report Cascade Village

Durango, Colorado January 20, 2025





Contents

Title Page Contents

1	Intro	oduction	1
2	Proj 2.1 2.2 2.3	Proposed Development	.3
3	3.1 3.2 3.3 3.4 3.5	Roadway Network Existing Background Traffic Volumes Existing Background Conditions Level of Service. Trip Generation. Trip Distribution and Assignment.	.6 .6
4	Sho 4.1 4.2	ort-Term (Year 2026) Background Analysis	12
5		ort-Term (Year 2026) Background plus Site nerated Traffic Analysis	14
6	Lon 6.1 6.2	g-Term (Year 2046) Background Analysis 1 Long-Term Background Traffic Volumes	16
7		g-Term (Year 2046) Background plus Site nerated Traffic Analysis	8

Contents (continued)

8	Add	ditional Roadway Analysis	20
	8.1	Auxiliary Lane Analysis	20
	8.2	Sight Distance Analysis	20
9	Coi	nclusions and Mitigation Considerations	21

List of Tables

Table 1 – LOS Results – Cascade Village TIS
Table 2 – Trip Generation Estimate – Cascade Village TIS

List of Figures

Figure 1 - Vicinity Map

Figure 2 - Site One (Tract C) Site Plan

Figure 3 - Site 2 (Tract A & B) Site Plan

Figure 4 - Existing Conditions

Figure 5 – Site Generated Traffic and Distribution

Figure 6 - Short-Term (Year 2026) Background Traffic Conditions

Figure 7 - Short-Term (Year 2026) Background + Site Generated Traffic Conditions

Figure 8 - Long-Term (Year 2046) Background Traffic Conditions

Figure 9 - Long-Term (Year 2046) Background + Site Generated Traffic Conditions

List of Appendices

Appendix A - Traffic Count Data

Appendix B - LOS Calculation Worksheets


Traffic Impact Study – Draft Report

Prepared for Reynolds Ash & Associates

1 Introduction

Short Elliott Hendrickson Inc. (SEH) is pleased to provide this traffic impact study for the proposed Cascade Village development in Durango, Colorado at 50827 US 550. The development is located adjacent to the existing Cascade Village development approximately a mile north of Purgatory Ski Resort.

The purpose of this study is to identify traffic impacts and recommend mitigation measures associated with the proposed development of the site. This study examines intersection operations for existing, short-term (Year 2026), and long-term (Year 2046) traffic conditions. Typical weekday morning and evening peak periods were analyzed for site-specific impacts. A vicinity map showing the site location in relation to the surrounding roadway network is provided in **Figure 1**.



2 Project Description

2.1 Proposed Development

The proposed Cascade Village is located on two separate sites. The first site (Site 1) includes Tract C and is located directly across the existing entrance to Cascade Village along US 550. Tract C is proposed to include 24 townhomes. **Figure 2** displays the proposed site plan.

The second site (Site 2) includes Tracts A and B and is displayed in the attached site plan. The site plan calls out 92 townhomes, 9 cabins, 5 single family homes, 10 condos townhomes, and two commercial properties that will include a small deli and retail space. **Figure 3** displays the proposed site plan.


2.2 Site Access


Two site accesses to the Cascade Village development are proposed. The first is a full movement access to US 550 at Site 1. The access will be adding an east leg onto the existing intersection that currently serves the existing Cascade Village property. **Figure 2** displays the proposed access point for Site 1.

The second proposed site access is located at Site 2 that includes Tracts A and B. The proposed access is approximately 3,000 feet south of the existing Cascade Village intersection. **Figure 3** displays the proposed access point for Site 2.

2.3 Study Area and Evaluation Parameters

The project study area includes the two site accesses. Per the direction of the client, the anticipated opening date for the development is 2026. Average weekday morning and evening peak hour operations were evaluated for the existing year, short-term (Year 2026), and long-term (Year 2046) scenarios.





3 Existing Background Conditions

3.1 Roadway Network

US 550

US 550 is a two-lane highway with a posted speed limit of 45 miles per hour (mph) near the existing Cascade Village intersection and 55 mph near the proposed access to Site 2. The CDOT highway classification is R-A: Regional Highway.

3.2 Existing Background Traffic Volumes


Existing traffic counts were collected by SEH at the existing intersection at US 550 and Cascade Village on Wednesday, December 4, 2024 during the morning and evening peak hours. A seasonal adjustment factor was applied to the traffic volumes to account for the lower traffic observed during time of year traffic volumes were collected. The nearest continuous count station to the site is Station 104809 along US 160 between mile marker 83 and 84 in Durango. A seasonal factor of 1.07 was calculated for the month of December and applied to the collected traffic counts. **Appendix A** contains the turning movement count data and **Figure 4** displays the existing traffic volumes. Average Daily Traffic (ADT) for US 550 near the project site is approximately 2,000 vehicles per day (vpd) displayed in CDOT's Online Transportation Information System (OTIS).

3.3 Existing Background Conditions Level of Service

Level of Service (LOS) was calculated using Synchro 11 software to evaluate the performance of the intersections within the study area. This software package utilizes criteria described in the <u>Highway Capacity Manual</u>¹. LOS is a measure used to describe operational conditions at an intersection. LOS categories ranging from A to F are assigned based on the predicted delay in seconds per vehicle for the intersection overall, as well as for individual turning movements. LOS A indicates very good operations, while LOS F indicates poor, congested operations. Overall intersection LOS D is considered acceptable by CDOT and most municipalities.

A summarization of the results of the intersection LOS calculations is displayed in **Table 1**. The analysis indicates that the intersection at US 550 / Cascade Village currently operates at LOS A with all movements also operating at LOS A. **Appendix B** contains the LOS analysis worksheets for reference.

¹ HCM 6th: Highway Capacity Manual 6th Edition: A Guide for Multimodal Mobility Analysis Washington, D.C.: Transportation Research Board, 2016. Print.



Delay (sec) LOS Delay (sec) LOS ⋖ ⋖ 44 2046 Background + Site Generated Traffic PM Peak Hour 7.3 3.3 10.0 8.8 7.5 0.0 2.0 9.6 9.0 9.7 8.8 8.5 7.6 0.0 AM Peak Hour

<b ⋖ 44444 Year 2046 Traffic Delay (sec) LOS Delay (sec) LOS < |< 4 4 PM Peak Hour 44 2046 Background Traffic 1.9 9.4 7.5 8.8 0.0 ⋖ ∢ ∢ AM Peak Hour < < 44 **2.8** 8.6 0.0 7.4 0.0 Delay (sec) LOS <a 2026 Background + Site Generated Traffic 4 < < < < < PM Peak Hour 3.5 9.9 8.8 7.4 0.0 2.0 9.4 0.0 9.6 9.5 8.5 7.5 7.5 7.3 0.0 0.0 Delay (sec) LOS AM Peak Hour Year 2026 Traffic Delay (sec) LOS Delay (sec) LOS ∢ ∢ < < 44 PM Peak Hour ⋖ 2026 Background Traffic **1.9** 8.7 7.5 0.0 < ∢ ∢ AM Peak Hour ∢ < 44 Southbound Through + Right

Note: Site 2 Access not analyzed for Background Traffic scenarios due to the traffic being through movements only **2.8** 8.6 0.0 7.4 0.0 Delay (sec) LOS Delay (sec) LOS 4 × AK **4** PM Peak Hour **Existing Background Traffic 1.9** 7.5 0.0 Year 2024 Traffic 8.7 AM Peak Hour < < 4 44 4 4 **2.8** 0.0 7.4 0.0 Table 1. LOS Results - Cascade Village TIS US 550 / Cascade Village Main Access US 550 / Cascade Village Site 2 Access Intersection and Critical Movements STOP CONTROL Eastbound Left
Eastbound Through
Eastbound Through
Eastbound Left
Westbound Through + Right
Northbound Through
Northbound Through
Northbound Right
Southbound Through
Southbound Through
Southbound Right
Southbound Right
Southbound Right
Southbound Right Northbound Through Eastbound Left Eastbound Right Northbound Left

3.4 Trip Generation

To determine the traffic impacts associated with the Cascade Village development, the amount of traffic generated by the proposed development was estimated using trip generation rates contained in the <u>Trip Generation Manual</u>². For Site 1, 24 townhomes are proposed. ITE Code 215-Single-Family Attached determine trip generation rates for Site 1 during the morning and evening peak hour. Site 1 is projected to generate 172 total vpd with 12 vehicles per hour (vph) in the morning peak hour and 14 vph in the evening peak hour.

For Site 2, 5 single family homes, 9 cabins, 92 townhomes, 10 condos, a small deli, and retail store are proposed.

- ITE Code 210-Single-Family Detached Housing was used for the single family homes and cabins
- ITE Code 215-Single-Family Attached Housing was used for the townhomes
- ITE Code 220-Multifamily Housing (Low-Rise) was used for the condos
- ITE Code 932-High-Turnover (Sit-Down) Restaurant was used for the deli
- ITE Code 875-Department Store was used for the retail property.

Site 2 is projected to generate 542 total vpd with 72 vehicles per hour (vph) in the morning peak hour and 89 vph in the evening peak hour.

The estimated weekday, morning peak hour, and evening peak trip generation for the proposed development is contained in **Table 2**.

3.5 Trip Distribution and Assignment

Trip distribution percentages for site generated traffic are based on current traffic patterns in the study area and how traffic will access the site. 90% of the traffic is projected to access the site from the south and 10% from the north. The overall distribution of trips to and from the site are illustrated in **Figure 5**.

Traffic Impact Study - Cascade Village

Trip Generation. Institute of Transportation Engineers. 11th Edition. 2021.

Table 2. Weekday Trip Generation Estimate - Cascade Village

					Macket	. Trino			A RA Dool, 1	AM Dook Hour Tring			DM Dook Hom Tring	T.	
	빌				weekuay iiips	sdiii k			AIN FEAN	edill inor			LIN LEAN	edili inor	
Land Use	Code	Size	Onit	Rate	Total	드	Out	Rate	Total	≘	Out	Rate	Total	<u>=</u>	Out
Townhomes ²	215	24	Dwelling Units	7.20	172	86	98	0.48	12	3	6	0.57	14	8	9
Site 1 (Tract C) Total Trips	C) Total	Trips			172	86	98		12	3	6		14	8	9
Single Family Homes ¹	210	5	Dwelling Units	9.43	48	24	24	02'0	4	1	3	0.94	5	3	2
Cabins ¹	210	6	Dwelling Units	9.43	85	43	43	0.70	7	2	5	0.94	8	5	3
Townhomes ²	215	85	Dwelling Units	7.20	662	331	331	0.48	44	11	33	0.57	52	31	21
Condos ³	220	10	Dwelling Units	6.74	29	34	34	0.40	4	_	4	0.51	5	က	2
Small Restaurant/Deli ⁴	932	-	1000 Sq. Ft GFA	107.20	108	54	54	9.57	10	9	4	9.05	6	2	4
Retail Store ⁵	875	5	1000 Sq. Ft GFA	22.88	114	57	57	0.58	3	2	-	1.95	10	5	5
Site 2 (Tract A & B) Total Trips	& B) To	tal Trip	Sc		1,084	542	542		72	23	50		89	52	37
Total	Total Trips				1,256	628	628		84	26	59		103	09	43


Trip Generation estimates are based on average rates for 210 -Single-Family Detached Housing contained in Trip Generation, 11th Edition (Institute of Transportation Engineers, 2021).

² Trip Generation estimates are based on average rates for 215 - Single-Family Attached Housing contained in Trip Generation, 11th Edition (Institute of Transportation Engineers, 2021).

³ Trip Generation estimates are based on average rates for 220 - Multifamily Housing (Low-Rise) contained in Trip Generation, 11th Edition (Institute of Transportation Engineers, 2021).

⁴ Trip Generation estimates are based on average rates for 932 - High-Turnover (Sit-Down) Restaurant contained in Trip Generation, 11th Edition (Institute of Transportation Engineers,

⁵ Trip Generation estimates are based on average rates for 875 - Department Store contained in Trip Generation, 11th Edition (Institute of Transportation Engineers, 2021).




4 Short-Term (Year 2026) Background Analysis

4.1 Short-Term Background Traffic Volumes

Year 2026 is identified as the "open year" for the Cascade Village development and is used as the short-term scenario. OTIS reports a 20-factor of 1.16 near the project site corresponding to 0.8% growth per year. Existing volumes were grown by 1.6 to grow to year 2026 background volumes. The projected short-term background traffic volumes are contained in **Figure 6**.

4.2 Short-Term Background Level of Service

Year 2026 background traffic volumes were analyzed to determine future operations and capacity constraints. A summarization of the results of the intersection LOS calculations is displayed in **Table 1**. The analysis indicates that the intersection at US 550 / Cascade Village currently operates at LOS A with all movements also operating at LOS A. **Appendix B** contains the LOS analysis worksheets for reference.



5 Short-Term (Year 2026) Background plus Site Generated Traffic Analysis


5.1 Short-Term Background plus Site Generated Traffic Volumes

The Cascade Village site generated traffic volumes (**Table 2**) were combined with the short-term background volumes to produce the total short-term traffic volumes. The resulting total traffic volumes are presented in **Figure 7**.

5.2 Short-Term Background plus Site Generated Traffic Level of Service

The Year 2026 background plus site generated traffic volumes were analyzed to determine short-term operations and potential capacity constraints caused by the addition of site traffic from the Cascade Village development.

The analysis of the intersections US 550 / Cascade Village and US 550 / Cascade Village Site 2 Access indicates that the addition of the site generated traffic is projected to have a minimal impact on overall intersection operations and travel time delay with no impact to either overall intersection LOS or LOS by movement. A summarization of the results of the intersection LOS calculations is displayed in **Table 1**. The analysis indicates that the intersection at US 550 / Cascade Village and US 550 / Cascade Village Site 2 Access is projected to continue operating at LOS A with all movements also operating at LOS A. **Appendix B** contains the LOS analysis worksheets for reference.




6 Long-Term (Year 2046) Background Analysis

6.1 Long-Term Background Traffic Volumes

Year 2046 is identified as the long-term horizon year for this study and is 20 years post "open year". Similar to the short-term, background traffic volumes were grown using a 20-factor of 1.16 (0.8% per year growth) outlined in OTIS for the station nearest the site. The projected long-term background traffic volumes are contained in **Figure 8**.

6.2 Long-Term Background Level of Service

Year 2046 background traffic volumes were analyzed to determine future operations and capacity constraints. A summarization of the results of the intersection LOS calculations is displayed in **Table 1**. The analysis indicates that the intersection at US 550 / Cascade Village currently operates at LOS A with all movements also operating at LOS A. **Appendix B** contains the LOS analysis worksheets for reference.



7 Long-Term (Year 2046) Background plus Site Generated Traffic Analysis


7.1 Long-Term Background plus Site Generated Traffic Volumes

The Cascade Village site generated traffic volumes (**Table 2**) were combined with the long-term background volumes to produce the total long-term traffic volumes. The resulting total traffic volumes are presented in **Figure 9**.

7.2 Long-Term Background plus Site Generated Traffic Level of Service

The Year 2046 background plus site generated traffic volumes were analyzed to determine long-term operations and potential capacity constraints caused by the addition of site traffic from the Cascade Village development.

The analysis of the intersections US 550 / Cascade Village and US 550 / Cascade Village Site 2 Access indicates that the addition of the site generated traffic is projected to have a minimal impact on overall intersection operations and travel time delay with no impact to either overall intersection LOS or LOS by movement. A summarization of the results of the intersection LOS calculations is displayed in **Table 1**. The analysis indicates that the intersection at US 550 / Cascade Village and US 550 / Cascade Village Site 2 Access is projected to continue operating at LOS A with all movements also operating at LOS A. **Appendix B** contains the LOS analysis worksheets for reference.



8 Additional Roadway Analysis

8.1 Auxiliary Lane Analysis

US 550 is classified as R-A: Regional Highway and has a speed limit of 45 mph posted near the existing US 550 / Cascade Village Access / Site 1 Access intersection and 55 mph near the intersection US 550 / Site 2 Access. According to section 3.8 of the State of Colorado State Highway Access Code, (Volume 2, March 2002), the following criteria require the construction of auxiliary lanes:

Left turn deceleration lane: 10 vph

Right turn deceleration lane: 25 vph

Right turn acceleration lane: 50 vph

An auxiliary lane analysis was conducted for both proposed accesses to the Cascade Village development. The evening peak hour represents the largest amount of site generated traffic with 14 vph at Site 1 (8 vph entering and 6 mph out) and 89 vph at Site 2 (52 vph entering and 37 vph exiting). The proposed development includes a full movement access to/from US 550 at both Site 1 and Site 2. **Figure 5** displays the trip generation.

According to the criteria outlined in the Access Code, a left turn deceleration lane is warranted for the intersection at US 550 / Site 2. According to section 4.8 of the Access Code, a deceleration length of 600' is required for a 55 mph roadway and a storage length of 50' is required for the turn lane resulting in an effective length of 650'. No other auxiliary lanes are warranted along US 550 at either of the sites.

8.2 Sight Distance Analysis

According to section 4.3 of the Access Code entering sight distance for a two-lane 45 mph roadway is 450 feet and 550 feet for a 55 mph roadway. SEH conducted a site visit to confirm the sight distance at the proposed Site 1 and Site 2 access. Approximate sight distances measured were:

- US 550 / Site 1 Access (Southbound, looking right): 1,100'
- US 550 / Site 1 Access (Northbound, looking left): 1,320'
- US 550 / Site 2 Access (Southbound, looking left): 840'
- US 550 / Site 2 Access (Northbound, looking right): 1,110'

Sight distance is sufficient for both proposed accesses, exceeding the criteria outlined in section 4.3 of the Access Code.

9 Conclusions and Mitigation Considerations

Based on the analysis described in the sections above, the following conclusions have been drawn regarding the traffic impacts resulting from the Cascade Village development:

- The anticipated traffic volume generated by the Cascade Village development is not expected to significantly impact the surrounding roadway network.
- Traffic analysis results for the Short-Term and Long-Term scenarios are
 projected to be similar to the Existing Conditions with very minor changes in
 travel time delay. Both study intersections are projected to operate at overall
 LOS A all movements projected to operate at LOS A.
- A left-turn deceleration lane is warranted for the US 550 / Site 2 Access intersection. No auxiliary lanes are required US 550 to accommodate the site generated traffic.
- Sight distance is sufficient in all directions at both Site 1 and Site 2 accesses.
- Due to the minimal projected impact of site generated traffic to the study intersections, no additional mitigation measures for the site or surrounding area are proposed at this time.

Tables Table 1 – LOS Results – Cascade Village TIS (In Report) Table 2 – Trip Generation Estimate – Cascade Village TIS (In Report)

Figures

Figure 1 – Vicinity Map (In Report)

Figure 2 – Site One (Tract C) Site Plan (In Report)

Figure 3 – Site 2 (Tract A & B) Site Plan (In Report)

Figure 4 – Existing Conditions (In Report)

Figure 5 – Site Generated Traffic and Distribution (In Report)

Figure 6 - Short-Term (Year 2026) Background Traffic Conditions (In Report)

Figure 7 – Short-Term (Year 2026) Background + Site Generated Traffic Conditions (In Report)

Figure 8 - Long-Term (Year 2046) Background Traffic Conditions (In Report)

Figure 9 - Long-Term (Year 2046) Background + Site Generated Traffic Conditions (In Report)

Appendix A

Traffic Count Data

US 550 & Meadowview Dr. Durango, CO near Purgatory Ski Resort 0 0

		VEHICLE TOTAL	0	0 0	0 0	0	0	0	0	0	0	0	0	0 0	00	9		. 0	0	0	0	0	00	0	0	0 0	0	0	0 (.	0	0	ъ (2 0 2	33
		Vehicle Approach Total	0	0 0	0 0	0	0	٥	0	0	0	0	0	00	0	c	٥	0	0	a	0	0	0	0	0	0	0	0	0	0 0	0	0	0 (o ≁ c	m
		Crossings	0	0 0	0 0	0	0	0	0	0	0	0	0	0 0	0		0 0	0	0	0	0	0	0 0	0	0	0 0	0	0	0	0 0	0	o	0	000	0
	믿	# £	0	0 (0 0	0	0	0	0	0	0	0	0	00	0		o c	, 0	0	0	0	0	00	0	0	0 0	0	5	0	0 0	0	0	0	o + c	e m
	Eastbound	Straight Through	0	0	0 0	0	0	0	0	0	0	0	0	00	0		.	0	0	0	0	0	0 0	0	0	0 0	0	0	0	000	0	0	0	000	0
		Left Turns 1	0	0	0 0	0	0	0	0	0	0	0	0	00	00	8 10	3 0	0	0	0	0	0	00	o	0	0 0	0	0	0	0 0	0	0	0		0
		Turns	0	0		0	0	. 0	0	0	0	0	0	00	0		0 0	0 0	0	o	0	0	00	0	0	00	0 0	0	0	0 0	0	0	0	000	0
		Vehicle Approach U	0	0	00	0	0	0	0	0	0	0	0	00	0	6 30	5 0	0 0	0	0	0	0	00	. 0	0	00	0 0	0	0	0 0	0	0	9	n es u	22
		Crosswalk Ap		0 (0 6	0	0	0	0	0	0	0	0	0 0	0	Fi (0 0	0	Q	0	0	0 0	0	0	0 0	. 0	0	0	0 0	0	0	0	000	
	9		0	0	0 0	0	0		0	0	0	0	0	00	00	8 8	0 0	2 0	0	0	0	0	0 0	0	0	0 0	00	0	0	00	0	0	0	000	0
	Northbound	Straight R Through To	0	0 0	0 0		0	0	0	0	0	0	0	0 0		0 ()	0 0			0	0	0	00	0	0	0 0	. 0	0	0	0 6	. 0	0		י פו ס	
		Left Turns Than			0 0				0		0			0.0									00					0			0			- 0 0	
Wednesday, December 4, 2024		U Turns Left			0 0				0	222				0.0						0			00	0		0.0		0	20						200
ecemp	_		-			-	14.57	-125																	1211		CONTR								
day, D		walk Vehicle ings Total			00				0		0			0 0					0				00				0 0				0			000	
ednes		it Crosswalk			0 0				0			٥	٥	0 0	0 0				0		٥	0	00	0	8	0 (9 0	0	0	Φ 6	0	0	٥	000	0
Š	Westbound	u ht Right gh Turns	0	0	00	0	0	0	0	0	0	0	a	0 0	0		2 0	5 0	0	0	o	0	00	0	0	0 0	0	0	0	0 0	9 0	0	0	000	
	3	8 €	0	0	00	0	0	0 0	0	0	0	0	0	0 0	0		0 0	9 6	0	0	0	0	00	0	0	00	0	0	0	00	0	0	0	000	0
		ss Left Turns	0	0	0.0	0	0	0	0	0	0	٥	0	0 0	0	7	0.0	0 0	0	0	0	0	00	0	0	0	0 0	o	0	0 0	0	0	0	000	0
	_	ch U Turns		0	00	0	0	0	0	0	0	0	0	0.0	0		0 0	0 0	0	0	0	0	00	0	0	0	0	٥	0	0 0	0	0	0	000	0
		Vehicle SS Total	0	0	0 0	0	0	9 9	0	0	0	0	0	90	0		00	0 0	0	0	0	0	00	0	0	0 0	00	0	0	0 0	00	0	*	m (v)	2
		Crosswalk	0	0	0 0	0	C	0	0	0	0	0	0	0	0		0 0	o c	0	0	0	0	00	0	0	0	0	0	0	0	0	0	0	000	0
	Southbound	Right Turns	0	0	0 6	0	¢	0 0	0	0	0	0	0	0	0		0 0	0 0	0	0	0	0	00	0	0	0 (00	0	0	0 0	0	0	0	000	0
	Sout	Straight Through	0	0	0 6		Ç	0	0	0	0	0	0	0	0	ij.	0.9	0 0	0	0	0	0	00	0	0	0	00	0	0	0 0	0	0	4	m n .	2
		U Turns Left Turns	0	0	0 6	0	_	0	0	0	۵	0	0	0 0	0		0 0	o c	0	0	0	0	0 0	0	0	0	00	0	0	0 0	0 0	0	0	00	0
	_	U Turns	0	0	0 0	0	c	0	0	0	0	0	0	0.0	0	,	0 0	0 0	0	٥	0	0	00	0	0	0	0 0	0	0	0 0	0 0	0	0	00	0
		ТІте	12:00 AM	12:15 AM	12:30 AM	Hourly Total	1.00 00.1	1.15 AM	1:30 AM	1:45 AM	Hourly Total	2:00 AM	2:15 AM	2:30 AM	Hourly Total		3 00 AM	3:15 AM	3.45 AM	Hourly Total	4:00 AM	4:15 AM	4:30 AM	Hourly Total	5:00 AM	5:15 AM	5:30 AM	Hourly Total	6:00 AM	6:15 AM	6.45 AM	Hourly Total	7:00 AM	7:15 AM 7:30 AM	Hourly Total

US 550 & Meadowview Dr. Durango, CO near Purgatory Ski Resort 0 0

		VEHICLE TOTAL	20	16	6 ;	55		0	0 0	0	0	0	0	0 6			. 0	0	0	0	0	0 0		0	0	0 (0	0	0 0		0	0	0 0	0 0	0
		Vehicle Approach Total	ın	ı		N G	6 3	0	0 0	0	0	a	0	9 0	0	s c	0	0	0	0	0	0 0	0	0	0	0	0 0	0	0	00	0 0	0	0	00	0	0
		Crosswalk	0	0	0 1	0 0	7 a	0 1	0 0	. 0	0	0	0	0 0	0		0	0	٥	٥	0	0 0	0 0	0	0	0 0	0 0	o	0	0 0	00	0	0	0 0	0	0
	pun	# 2	2	-	← (7 6	8 9	0 0	0 0	. 0	0	0	0	۵ د	> 0	> 0	0	0	0	D	0	0 0	0 0	0	0	0 0	0 0	0	0	0 0	0	0	0	00	00	0
	Eastbound	Straight Through	0	0	0	00		0 0	o c	0	0	0	0	0 0		o c	0	0	0	0	0	0 0	0 0	0	0	0 :	00	0	0	0.0	00	o	0	0 0	. 0	0
		Left Turns	0	0	0	0		0 0	5 C	0	0	0	0	0 0	0	, ,	0	0	0	0	0	0 0	0 0	0	0	0 0	0 0	0	0	0 0		0	0	00	0 0	0
		U Turns L	0	0	0	00	0 8	0 (0 0	٥	0	o	0	0 0		2 (5	0	0	٥	0	0	0 0	0	0	0	0 0	0 0	0	0	0 0	0 0	0	0	0 0	0	0
		Vehicle Approach Total	10	11	4 (27	- 8	0 (9 0	. 0	0	0	0	0 0	0		0	0	0	0	0	0 0	00	0	0	0 0	00	0	0	0	0 0	0	0	0 0	0 0	0
		Crosswalk Crossings	0	0	0 (0		0 0	0 0	. 0	0	0	٥	0 0	3 0		0	0	0	0	0	0 0	0	0	0	0 (00	o	0	0 0	00	0	0	00	. 0	o
	pun	Right C	0	0	0	0	n H	0 (D C	0	0	o	0	0 0			0	0	0	0	0	0 0	0 0	0	0	0 0	0 0	0	0	0 0	0	o	0	00	0 0	0
	Northbound	Straight Through	89	10	4 (24		0 0	0 0	0 0	0	0	0	00	0		0	0	0	0	0	0 0	0 0	0	0	0 0	00	0	0	0 0	00	0	0	0 0	. 0	0
2024		Left Turns	8	_	0 1	a e		0 1	0 0	. 0	0	a	0	0 0		: :	. 0	0	٥	0	0	0 0	0	٥	0	0	0 0	0	0	0 0	0	0	0	00	0	0
nber 4,		U Turns Le	0	0	0 (00		0 (0 0	0	0	0	0	0 0		, ,	0	0	0	0	0	0 0	0 0	0	P	0 0	0 0	0	0	00	0 0	0	0	00	. 0	0
Decer	_	Vehicle Approach Total	0	0	0	00		0	0 0	0	0	0	0	0 0			0	0	0	0	0	0 0	00	0	0	0 0	0 0	0	0	0 0	0 0	0	0	00	0 0	0
Wednesday, December 4, 2024	i	Crosswalk A	0	0	0	0 0		0	0 0	. 0	0	0	0	0 0		> <	0	0	0	0	0	0 0	0 0	0	0	0	0 0	0	0	0 0	0	0	0	00	00	o
Wedn	pun	Right C Turns C	0	0	0 (0		0 1	0 0	. 0	0	0	0	0 0	0		. 0	0	0	0	0	0 0	0 0	0	0	0 0	0 0	0	0	0 0	0 0	0	0	0 0	0	0
	Westbound	Straight Through	0	0	0:	00		0	0 0	. 0	0	0	0	00	0		. 0	0	0	0	0	0 0	0	0	0	0	0 0	0	0	0 0	0 0	0	0	00	0	0
		Left Turns	0	0	0	00		0	0 0	. 0	0	0	0	0 0	0	· (c	0	0	0	0	٥	0.0	0 0	0	0	0 1	0 0	0	0	0 0	0 0	0	0	0 0	0 0	0
		U Turms L	0	0	0	00		0	0 0	. 0	0	0	0	0 0	0		0	0	0	0	0	0 0	0 0	0	0	0	0 0	0	0	0 0	0 0	0	0	00	00	0
	=	Vehicle Approach	200	*	*	19	39	0	0.0	0	0	0	0	0 0		> <	0	0	0	0	0	0	0 0	0	0	0	00	0	0	0 0	0 0	0	0	00	0 0	0
		Crosswalk A	0	0	0	00		0	0 0	0	0	0	0	0 0	0		0	0	0	0	0	0 0	0 0	0	0	0 1	0 0	0	0	0 (0 0	0	0	0 0	0 0	0
	pun	Right C	0	0	0	0 0		0	0 0	0	0	0	0	0 0			0	0	0	0	0	0 0	o a	0	0	0	00	О	0	0 0	o 0	0	0	00	00	0
	Southbound	Straight Through	ιΩ	4	4	19 6		0 (D C	0	0	0	0	0 0	0 0	o c	0 0	0	0	0	0	0 0	0 0	0	0	0	0 0	0	0	0 0	0	0	0	0 0	00	0
			0	0	0	0 0		0	0 0	, 0	0	0	0	0 0	9		, 0	0	0	0	0	0 0	0 0	0	0	0	0 0	0	0	0 0	00	0	0	0 0	. 0	0
		U Turns Left Turns	0	0	0	0 0	8 8	0	0.0	0	0	0	0	0 0	0 0		0	0	0	Q	0	0 0	0	0	0	0	0 0	0	0	0	o 0	0	0	0 6	0	0
	_	Ting	8:00 AM	8:15 AM	8:30 AM	Hourly Total		9:00 AM	9:15 AM	9:45 AM	Hourly Total	10:00 AM	10:15 AM	10:30 AM	10.45 AW	IBIOL WILLIAM	11:15 AM	11:30 AM	11:45 AM	Hourly Total	12:00 PM	12:15 PM	12:45 PM	Hourly Total	1:00 PM	1:15 PM	1:30 PM 1:45 PM	Hourly Total	2:00 PM	2:15 PM	2:45 PM	Hourly Total	3:00 PM	3:15 PM	3:45 PM	Hourly Total

US 550 & Meadowview Dr. Durango, CO near Purgatory Ski Resort 0 0

	1	VEHICLE TOTAL	24	78	14	98	10	17	4 5	83	0	0	00	0	0	0 0	0 0	0	0 0	. 0	٥	o	00		0	0	0 0	0	0	0 0	0	0	0	233	18 7.73%
		Vehicle Approach Total	210	1 1-	0	9		0	- 0	9	0	0	00	0	0	0 0	0	0	00	0	0	0	00	000	00	0	00	0	0	0 0	0 0	0	0	23	2 8.70%
		Crosswalk	0 0	0	0	٥	0	0	0 0	0	0	0	0 0	0	0	0 0	0	o	0 0	00	0	0	0.0	00	0	0	0 0	0	0	0.0	0 0	0	0	00	0.00%
	puno	Right	2 +		0	4	Ŧ	2	- 0	9	0	0	0 0	0	0	0 0	0	0	0	0	0	0	00		00	0	0 0	0	0	0 0	0 0	0	0	32	2 9.09%
	Eastbound	Straight Through	00	0	0	0	0	0	0 0	0	0	0	00	0	0	0 0	0	0	00	00	٥	φ	00	000	0	0	00	0	0	0 0	0	0	0	9 0	0.00%
		Left Turns	٥.	. 0	0	-	0	0	00	0	0	0	00	0	0	00	0 0	0	50	2 0	0	0	00	00	0	0	00	0	0	0	0	0	0		%00 ^{.0}
		U Turns	0 0	0	0	0	0	0	00	0	o	0	0 0	0	0	0.0	0	0	00	0	0	0	00	0	00	0	00	0	0	0 0	0 0	0	0	00	0.00%
,		Vehicle Approach Total	60 1	10	7	32	5	9	۶ ۲	23	0	0	00	0	0	0 0	0 0	0	00	0 0	0	0	00	000	0	٥	0 0	0	0	0 0	0 0	0	0	104	8
		Crosswalk	0 0	0	0	0	0	0	00	0	0	0	0 0	0	0	0 0	0	0	0 0		٥	0	0	0 0	0	0	00	0	0	0 0	0 0	0	0	0 0	%00:0 0
	Northbound 0	Right	0 0	00	0	0	0	0	0 0	9	0	0	00	0	0	0 0	00	a	0 0	0	0	0	00		0	0	00	0	0	0	0 0	0	0	0	%00 <u>:0</u>
	North	Straight Through		۸ د	7	27	4	9	ω 4	20	0	0	0 0	0	0	0 0	0 0	0	0 0	0	0	0	00		0 0	0	00	0	0	0 0	0 0	0	0	8 2	6.67%
Wednesday, December 4, 2024		Left Turns	535	· "	0	ю	***	0		_د	0	0	00	o	0	0.0	0	0	00	0	0	0	0 0	00	0	0	00	0	0	0	0 0	0	0	4 2	2 14.29%
mber		U Turns	00	0	0	0	0	0	0 0	0	0	0	0 0	0	0	0 0	0	0	00	00	0	0	00	000	0	0	00	0	0	0 0	0	0	0	00	0.00%
y, Dec		Vehicle Approach Total	00	0 0	0	0	0	0	00	0	0	0	00	0	0	0 0	00	0	0 0	0 0	0	0	00	000	00	0	0 0	0	0	0	0 0	0	0	0	0.00%
nesda		Crossings	0.0	0	0	0	0	0	0 0	0	0	0	o o	0	0	0 0	0	0	00	0	0	0	00	000	0	0	00	0	0	0 (0 0	0	0	0 0	%00 0 0
Wed	Westbound 0	Right	0 0	0	0	0	0	0	00	0	0	0	0 0	0	0	0 0	0	0	00	0 0	0	0	0 0	00	٥	0	0 0	0	0	0 (> C	0	0	00	%00 ^{.0}
	Wes	3. T	0 0	0	O	0	0	0	0 0	0	0	0	0 0	0	0	0 0	00	0	0 0	00	0	0	00	0	00	0	00	0	0	0	0 0	0	Q	00	0.00%
		Left Turns	٥٥	0	0	٥	0	0	00	0	0	0	00	o	0	0 0	00	o	0 0	0 0	0	0	0 0	00	0	0	0 0	0	0	0 0	0 0	0	0	0	%00 ⁰ 0
	_	U Tums	0 0	9 0	0	0	0	0	00	0	0	0	0 0	D	0	0 0	, 0	0	0 0	9 0	0	0	00	000	0	0	0 0	0	0	0 (-	0	0	00	0.00%
		Approach Total	4 4	17	7	48	4	6	O 40	24	0	0	00	0	0	0 0	0	0	00	0	0	0	00	00	0 0	0	00	0	0	0 (0	0	0	98	8 7 55%
		Crosswalk	0 0	0	0	0	0	0	00	0	0	0	00	0	0	0 0	0	0	0 0	0	0	0	0 0	00	0	0	0 0	0	0	0	0 0	0	0	• 0	%00 0
	Southbound 0		- 0	- c	0	2		0	00	-	0	0	00	٥	0	0 0	0	0	0 0	0	0	0	00	00	0	0	00	0	0	0	0 0	0	0	69 69	%00 O
	Sout	Straight Through	13	- 91	7	47	3	တ	60 ru	23	0	0	0 0	0	0	0 0	0	0	0 0	o	0	0	00	000	0 0	0	00	0	0	0 0	0 0	0	0	103 95	8 7.77%
		UTurns Left Turns	0 0	0 0	0	٥	0	0	00	0	0	0	0 0	0	0	0 0	00	0	00	0	0	0	00	00	0	٥	00	0	0	0	00	0	0	00	%00°0
		UTurns	0.0	0 0	0	D	0	0	0 0	0	o	0	0 0	0	0	0 0	0 0	o	D	0	0	P	00	0 0	0	0	0 0	0	0	0 0	0 0	0	0	00	0 00%
		Time	4:00 PM	4:30 PM	4:45 PM	Hourly Total	5:00 PM	5:15 PM	5:30 PM	Hourly Total	6:00 PM	6:15 PM	6:30 PM 6:45 PM	Hourly Total	7:00 PM	7:15 PM	7.45 PM	Hourly Total	8:00 PM	8:30 PM	8.45 PM	Hourly Total	9:00 PM	M4 05:6	Hourly Total	10:00 PM	10:15 PM	10:45 PM	Hourly Total	11:00 PM	11:15 PM	11 45 PM	Hourly Total	DAILY TOTAL Cars	Heavy Vehicles Heavy Vehicle %

US 550 & Meadowview Dr. Durango, CO near Purgatory Ski Resort 0 0

			Veh	Δημι	1
			Vehicle cerainte Dinte Gerainte Dinte Crescuale Vehicle Gerainte Dinte Crescuale Veh	Closeren	Crossings
		puno	Dight	night.	Turns
		Eastbound	Chraight	ari digiri	Through
				ft Turns	
				Tirens les	
		_	cle	TII date	
			II. Vehic	Annro	S
			Croscord	CIOSSAG	Crossing
		Northbound	Diahr	Men.	Turns
		North	Ceraight	angle ne	Through
, 2024				oft Turns	
Wednesday, December 4, 2024	5			Turns le	1
Jecem	AM Peak Hour		hicle	-	
day, I	AM		No.	Walls And	sauis
ednes			Contra	-	S Cros
Š		Westbound	4 Diah	1911	th Turr
		We	Chroinh	Jung.	Throug
				Loft Turn	
				II Turns	
			Vehicle	Sparroach	in a second
			Contractor	Crosswalk	Crossings
		punoq	diah.	LIP III	Turns
		Southbound	Charles	Sugar	Through Turns
				ofe Turne	
				II Turne Loft Turne	
	8				

		VEHICLE TOTAL	12	20	16	G	2.5	0.713			VEHICLE TOTAL	24	20	28	14	98	0.768
53		Vehicle Approach Total	N	'n	-		Ø,	0.450	,		Vehicle Approach Total	O.	2		0	5	0.625
		Crosswalk Crossings	0	0	0	0	0	0.000			Crosswalk Crossings '	0	0	0	0	0	0.000
	pun	Right (2	'n	-		6	0.450		pun	Right Turns	O	-	-	0	10	0,500
	Eastbound	Straight Through	0	0	0	0	0	0000		Eastbound	Straight	0	0	0	0	0	0000
		eft Turns	0	0	0	0	o	0.000			eft Turns	0	-	0	0	(d)	0,250
		U Turns L	0	0	0	0	0	0000			U Turns L	0	0	0	0	0	0000
2		Vehicle Approach Total	5	10	11		30	0.682	-		Vehicle Approach Total	8	7	10	7	32	0.800
		Crossings A	0	0	0	0	O	0.000			crosswalk Crossings	O	0	0	0	0	0.000
	pund	Right C Turns C	0	0	0	0	0	0.00		pund	Right C Turns (0	0	0	0	0	0000
	Northbound	Straight Through	2	80	10	45	27	0.675		Northbound	Straight	1	9	1	1	27	0,964
		eft Turns	0	2		0	3	0.375			eft Turns			es	0	so	0.417
'n		U Turns L	0	0	0	0	0	0 000	'n		U Turns L	0	0	0	0	0	0000
AM Peak Ho		Vehicle pproach Total	0	0	0	0	0	0.000	PM Peak Ho		Vehicle Ipproach Total	0	0	0	0	0	0.000
¥		rosswalk	0	0	0	0	0	0 000	A.		crossings	0	0	0	0	0	0000
	nuq	Right C	0	0	0	0	0	0 000		pund	Right C Turns	0	0	0	0	0	0000
	Westbound	Straight Through	0	0	0	0	0	0000		Westbound	Straight Through	D	0	0	0	0	0 000
		eft Turns	0	0	0	0	0	0 000			eft Turns	0	0	0	0	0	0.000
		U Turms Le	0	0	0	0	0	0000			U Turns Le	0	0	0	0	0	000'0
5	_	Vehicle Approach Total	co	5	4	7	18	0.900			Vehicle Approach Total	4	11	17	7	49	0,721
		Crosswalk A	0	0	0	0	0	0000			Crosswalk Crossings	0	0	0	0	0	0000
	punc	Right C Turns (0	0	0	0	0	0000		punc	Right C Turns	-	0	-	0	c	0.500
	Southbound	Straight	\$	9	¥	¥	18	0.900		Southbound	Straight Through	13	1	16	7	47	0.734
		eft Turns	0	o	0	o	0	0.000			eft Turns	0	0	0	0	0	00000
		UTurns LeftTurns	0	0	0	0	0	0.000			UTurns Left Turns	0	0	0	0	0	0 000
		Тіте	7:45 AM	8 00 AM	8 15 AM	B 30 AM	Peak Hour Total	PHF			Time	4:00 PM	4:15 PM	4:30 PM	4 45 PM	Peak Hour Total	PHF

							Ļ	1	Ļ	b	£°\$
91		0	0	0	₹ \$						
		a	0	0	ڪ)			us		
Vehicles Exiling Intersection	puno	0	0	0	Ĵ				Daily Volumes		
106	Southbound	98	80	103	→				Da		
Vehicles Entering 106 Intersection		3	0	3	7						
Vehicle	100	Cars	Heavy	Total			\$\$.	ๆ	7	1	r
	_	_		_		Total	0	0	-	0	22
						Heavy	0	0	0	0	2
						Cars	0	0	-	0	20
							4	puno	dtes3		
						Verbrolon	Vancies Entering Intersection	23	Vohurlos	Exting	17
							Tolal	Vehicles on Leg	40		

Vehebes Eintering Intersection O Vehebs Eximg Frances France Frances F
Westbound
Total 0 0 0 0 0 0
Heavy 0 0 0 0
Cars

í ← C	0 12 84 0	0 2 6 0	0 14 90 0	Northbound	Vehicles Exiting 125 Intersection	On Leg 229
£35	Cars 0	Heavy 0	Total 0		Vehicles Entering 104 Intersection	Total Vehicles On Leg

Appendix B LOS Calculation Worksheets

_						
Intersection						
Int Delay, s/veh	2.8					
Movement	EBL	EBR	NBL	NBT	SBT	SBR
Lane Configurations	T	EDIN.	NOL.	↑	1	JOEK
Traffic Vol, veh/h	0	10	4	29	20	0
Future Vol, veh/h	0	10	4	29	20	0
Conflicting Peds, #/hr	0	0	0	0	0	0
Sign Control	Stop	Stop	Free	Free	Free	Free
RT Channelized	Stop -	Stop	-		-	
Storage Length	25	0	420	-		280
Veh in Median Storage		1/2	420	0	0	200
Grade, %	0	12		0	0	
	92	45	38	68	90	92
Peak Hour Factor		9	14			
Heavy Vehicles, %	0			7	8	2
Mvmt Flow	0	22	11	43	22	0
Major/Minor 1	Minor2	1981	Major1	3113	Major2	
Conflicting Flow All	87	22	22	0		0
Stage 1	22			-		11.5
Stage 2	65	-				
Critical Hdwy	6.4	6.29	4.24		-	
Critical Hdwy Stg 1	5.4	-	-		-	-
Critical Hdwy Stg 2	5.4	g = 31				100
Follow-up Hdwy		3.381	2 326			-
Pot Cap-1 Maneuver	919	1035	1519			
Stage 1	1006	1000	1013	-	-	
Stage 2	963					
	903	•	- 3		-	
Platoon blocked, %	042	4005	4540			
Mov Cap-1 Maneuver	913	1035	1519		7.	100
Mov Cap-2 Maneuver	913		-	•		3
Stage 1	999	100	21.00	obec à		
Stage 2	963	-	-	•	۰	
The second second						
Approach	EB		NB	Sev.	SB	-
HCM Control Delay, s	8.6	7/10	1.5		0	
HCM LOS	A		1.0			
HISTORY ECO	^					
N 100 100 100 100 100 100 100 100 100 10						
Minor Lane/Major Mvm	t	NBL	NBT	EBLn1		SBT
Capacity (veh/h)	1	1519			1035	11
HCM Lane V/C Ratio		0.007	:=	_	0.021	
HCM Control Delay (s)		7.4	of the	0	8.6	200
HCM Lane LOS		Α	:=	Α	Α	(=).
HCM 95th %tile Q(veh		0			0.1	-

Intersection	1,34				Fine		
Int Delay, s/veh	1.9						
Movement	EBL	EBR	NBL	NBT	SBT	SBR	
Lane Configurations	*	7	ሻ	1	1	JUN T	
Traffic Vol, veh/h	2	5	6	29	51	3	
Future Vol, veh/h	2	5	6	29	51	3	
Conflicting Peds, #/hr	0	0	0	0	0	0	
Sign Control	Stop	Stop	Free	Free	Free	Free	
RT Channelized	Otop	Stop	-		-		
Storage Length	25	0	420	NOITE		280	
Veh in Median Storage,		-		0	0		
Grade, %	0	=	40	0	0	-	
Peak Hour Factor	25	50	42	96	73	50	
Heavy Vehicles, %	0	9	14	7	8	2	
Mvmt Flow	8	10	14	30	70	6	
Major/Minor N	Ainor2	VI II S	Major1		Major2		
Conflicting Flow All	128	70	76	0		0	
Stage 1	70			-	*	(9)	
Stage 2	58	0.00				(-	
Critical Hdwy	6.4	6.29	4.24	- (5)	- :	1 35	
Critical Hdwy Stg 1	5.4	:=0	7.		ē	850	
Critical Hdwy Stg 2	5.4	-	mic is			150	
Follow-up Hdwy	3.5	3.381	2.326			5.00	
Pot Cap-1 Maneuver	871	974	1450			155	
Stage 1	958	-	Ξ.	275	z	054	
Stage 2	970	-		- 3		II III	
Platoon blocked, %						.=	
Mov Cap-1 Maneuver	862	974	1450		- 3	N II E	
Mov Cap-2 Maneuver	862	014	. 100				
Stage 1	948					V75	
Stage 2	970				2	-	
Staye Z	310	-					
Approach	EB	180 E.	NB		SB	- Tyrux	
HCM Control Delay, s	8.9	125 - 10	2.4		0	N. Par	
HCM LOS	Α						
HI MILES	ينج				EX.		
		MEL	Mare	EDI	mml - c	000	
Minor Lane/Major Mvm	ķ.	NBL	NBT	EBLn1 6		SBT	
Capacity (veh/h)		1450		002	974		
HCM Lane V/C Ratio		0.01	-	0.009	0.01	10 0	
HCM Control Delay (s)		7.5		9.2	8.7	1 10-1	
HCM Lane LOS		Α	-	Α	Α	(- :	
HCM 95th %tile Q(veh)		0	41	0	0	23.5	
				-			

*							
Intersection				W	The same		
Int Delay, s/veh	2.8						
	COL	COD	MDI	NOT	SBT	SBR	U.O. N
Movement	EBL	EBR	NBL	NBT			
Lane Configurations	7	10	7	70	† 20	0	
Traffic Vol, veh/h	0		4	29			
Future Vol, veh/h	0	10	4	29	20	0	
Conflicting Peds, #/hr		0	0	0	0	0	-
Sign Control	Stop	Stop	Free	Free	Free	Free	
RT Channelized	-	Stop	400	None		None	
Storage Length	25	0	420	-	-	280	
Veh in Median Storag		-	-	0	0	-	
Grade, %	0	-	2	0	0	-	
Peak Hour Factor	92	45	38	68	90	92	
Heavy Vehicles, %	0	9	14	7	8	2	
Mvmt Flow	0	22	11	43	22	0	
Major/Minor	Minor2	To CAI	Major1	THE P	Major2	T Val	Tu.
Conflicting Flow All	87	22	22	0	viajoiz	0	
Stage 1	22	-	-	-		-	
Stage 2	65					•	
Critical Hdwy	6.4	6.29	4.24	-	1,50	95 4	
Critical Hdwy Stg 1	5.4	0.29	4.24	V 15			
	5.4			S IISI			
Critical Hdwy Stg 2		3.381	2 226				
Follow-up Hdwy	3.5			_			
Pot Cap-1 Maneuver	919	1035	1519				
Stage 1	1006	1.71	.77				
Stage 2	963	di v					
Platoon blocked, %	010	1605	4540	•	•	•	
Mov Cap-1 Maneuver		1035	1519		•		
Mov Cap-2 Maneuver		-	-	•	•	-	
Stage 1	999	er 13			-	Vinit	
Stage 2	963	-		-	12	2	
Approach	EB	R 8 :	NB		SB	1/2 52	-Y jus
HCM Control Delay, s	_	_	1.5	4,4	0	H, III,	
HCM LOS	Α		1.0		U		
TIOIVI LOG	^						
Minor Lane/Major Mvr	nt	NBL	NBT	EBLn1	EBLn2	SBT	SBR
Capacity (veh/h)	Esval a	1519	TC I		1035		(*)
HCM Lane V/C Ratio		0.007			0.021		
HCM Control Delay (s) =	7.4		0	8.6	17.	-
HCM Lane LOS		Α		A	Α		
HCM 95th %tile Q(veh	1)	0			0.1		
TOTAL COME TOTAL OCT VOI		•			V. 1		

Intersection	IÇ-LE	7017	Asir	1104	S 2"		150				
Int Delay, s/veh	1.9										
Movement	EBL	EBR	NBL	NBT	SBT	SBR	, 5 800	1	90.51	1	
Lane Configurations	7	7	7	†	†	7					
Traffic Vol, veh/h	2	5	6	29	52	3					
Future Vol, veh/h	2	5	6	29	52	3					
Conflicting Peds, #/hr	0	0	0	0	0	0					
Sign Control	Stop	Stop	Free	Free	Free	Free					
RT Channelized		Stop	- *	None	1						
Storage Length	25	0	420	-	-	280					
Veh in Median Storage	e,# 0			0	0						
Grade, %	0			0	0	-					
Peak Hour Factor	25	50	42	96	73	50					
Heavy Vehicles, %	0	9	14	7	8	2					
Mvmt Flow	8	10	14	30	71	6					
Major/Minor	Miner2		Major1		Major2		AL.	10.1			A. A.
Conflicting Flow All	129	71	77	0	-	0					
Stage 1	71	16									
Stage 2	58			-	-	-					
Critical Hdwy	6.4	6.29	4.24								
Critical Hdwy Stg 1	5.4										
Critical Hdwy Stg 2	5.4										
Follow-up Hdwy	3.5	3.381	2.326	٠		-					
Pot Cap-1 Maneuver	870	972	1449	- 3							
Stage 1	957	4	1	- 4	4						
Stage 2	970	1 4	- 10		32	7.3					
Platoon blocked, %				12		2					
Mov Cap-1 Maneuver	861	972	1449								
Mov Cap-2 Maneuver	861	-		-	-	-					
Stage 1	947				745						
Stage 2	970	-		2	923	-					
Barone Total										4	
Approach	EB		NB		SB	100	30	Tr.			
HCM Control Delay, s	8.9		2.4	100	0			2.5	211	NII)	
HCM LOS	Α.		4.7		V						
FEMALES IN SERVICE							5 Er			11 11	
Minor Lane/Major Mvn	nt	NBL	NBT	EBLn1 l	-Bl n2	SBT	SBR	31 10			
Capacity (veh/h)	0.0	1449	HO.		972	001	ODIN	MIN.			
HCM Lane V/C Ratio		0.01		0.009	0.01	-					
HCM Control Delay (s)	DIN	7.5		9.2	8.7		-i				
HCM Lane LOS		Α.5		9.2 A	Α	-					
HCM 95th %tile Q(veh	1	0		0	0		unio.				
TION SOUT JOUR COVER	1	U	- 5	U	U		150				

3: US 550 & Cascade Village Existing Access/Site 1 Access/

		_												-
Intersection		10 15	100	35					U		15	18.81		į
Int Delay, s/veh	3													
Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR		BL	SBT	SBR	ş
Lane Configurations	7		7	ሻ		7	ሻ	f >				4	7	
Traffic Vol, veh/h	0	0	10	8	0	1	4	34	2		1	22	0	
Future Vol, veh/h	0	0	10	8	0	1	4	34	2		1	22	0	
Conflicting Peds, #/hr	0	0	0	0	0	0	0	0	0		0	0	0	
Sign Control	Stop	Stop	Stop	Stop	Stop	Stop	Free	Free	Free	F	ree	Free	Free	
RT Channelized	100		Stop	THE P	F 123.	None	100		None		-	- 1	None	
Storage Length	25	-	0	0	-	0	420		-		2	-	280	
/eh in Median Storage,	# -	0		- 18	0		1100	0			-	0		
Grade, %	-	0	-		0		19	0	8		2	0	-	
Peak Hour Factor	92	92	45	92	92	92	38	68	92		92	90	92	
Heavy Vehicles, %	0	2	9	2	2	2	14	7	2		2	8	2	
/lvmt Flow	0	0	22	9	0	1	11	50	2		1	24	0	
Major/Minor N	linor2	18 18	15 Lb ²	Minor1	BXX		Major1			Maj	or2	QP.	18 = 1	17
Conflicting Flow All	100	-	24	99	:40	51	24	0	0		52	0	0	
Stage 1	26			73				-	515			- 4	(4)	
Stage 2	74			26	: #0		0.00		-			-	:=0	
ritical Hdwy	7.1	ov s	6.29	7.12		6.22	4.24	-		4	.12		-	
Critical Hdwy Stg 1	6.1		:+	6.12) # ()	8	0.0		-		æ	-	200	
Critical Hdwy Stg 2	6.1			6.12			1 30					110	ICV æ	
ollow-up Hdwy	3.5	-	3.381	3.518	-	3.318	2.326	-		2.:	218			
ot Cap-1 Maneuver	886	0	1033	883	0	1017	1516	5 Ma		1	554		1001	
Stage 1	997	0	-	937	0	-		-	F-					
Stage 2	940	0		992	0			85 0				(*)	190	
Platoon blocked, %									=			18	:=:	
lov Cap-1 Maneuver	880		1033	858	lhi-	1017	1516			1	554			
Nov Cap-2 Maneuver	880	:=:		858				:3	7			/ =	120	
Stage 1	990	1.00		930			12	1.5			or.	0 1	3.	
Stage 2	932	1.00		970	12.	- 51					-	75	**	
Approach	EB		200	WB			NB				SB		25	
HCM Control Delay, s	8.6			9.1			1.2				0.3			
HCM LOS	Α			Α										
		w.Y.					10						11/2	
Minor Lane/Major Mymt		NBL	NBT	NBR		EBLn2V			SBL	SBT S	BR		3. Y.	il.
Capacity (veh/h)		1516				1033	858	1017	1554					
HCM Lane V/C Ratio		0.007	9		-	0.022	0.01	0.001	0.001	-	14			
HCM Control Delay (s)		7.4	*	(6)	0	8.6	9.2	8.5	7.3	0				
HCM Lane LOS		Α	¥	7=	Α	Α	Α	Α	Α	Α	4			
HCM 95th %tile Q(veh)		0	*	-		0.1	0	0	0	-	-			

Intersection		180	ve i					W. Tis		
Int Delay, s/veh	4.1									
Movement	EBL	EBR	NBL	NBT	SBT	SBR			8"	16
Lane Configurations	ሻ	7	ħ	↑	ĵ.					
Traffic Vol, veh/h	5	45	21	35	37	2				
Future Vol, veh/h	5	45	21	35	37	2				
Conflicting Peds, #/hr	0	0	0	0	0	0				
Sign Control	Stop	Stop	Free	Free	Free	Free				
RT Channelized	4	None	-	None		None				
Storage Length	0	0	0	-	-	-				
Veh in Median Storage	,# 0		3,12	0	0	80 F				
Grade, %	0	-		0	0	-				
Peak Hour Factor	92	92	92	92	92	92				
Heavy Vehicles, %	2	2	2	2	2	2				
Mvmt Flow	5	49	23	38	40	2				
Major/Minor	Minor2		Major1	200	Major2			ALC: U	ton.	-
Conflicting Flow All	125	41	42	0	viajoiz	0	ال المات			
Stage 1	41	41	42	U		0				
Stage 2	84									
	6.42	6.22	4.12		**					
Critical Hdwy Critical Hdwy Stg 1	5.42	0.22	4.12							
Critical Hdwy Stg 2	5.42									
	3.518	3.318	2 240	-		- 4.3				
Follow-up Hdwy Pot Cap-1 Maneuver					*	-				
	870	1030	1567		-					
Stage 1	981			-		- 5				
Stage 2	939									
Platoon blocked, %	0.57	1000	4507		1.20					
Mov Cap-1 Maneuver	857	1030	1567	0.03		5				
Mov Cap-2 Maneuver	857	15.	-7.		150	-				
Stage 1	966		- 2	A 1 5						
Stage 2	939	(£								
Approach	EB		NB		SB		NI BUI		100	
HCM Control Delay, s	8.8		2.7		0	ni v s	11 11			
HCM LOS	A	100	(54.0)							
				Sept.						
Minor Lane/Major Mvn	nt	NBL	NBT	EBLn1	EBLn2	SBT	SBR		-	
Capacity (veh/h)	U pr	1567		857	1030			No. of Street,		11
HCM Lane V/C Ratio		0.015		0.006		" "				
HCM Control Delay (s)		7.3	11	9.2	8.7	- T	I F			
HCM Lane LOS		Α.		9.2 A	A					
HCM 95th %tile Q(veh	1	0		0	0.1					
HOW SOUT WHIE CI(VEN	1	U	-	U	0.1		-			

Intersection	- 12			B) A			1 1		150		71000		S COUNTY OF
Int Delay, s/veh	2							-					
Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR	
Lane Configurations	7	LUI	7	T	WOI	7	T	1	MDIN	ODE	4	7	
Traffic Vol, veh/h	2	0	5	5	0	1	6	33	7	1	57	3	
Future Vol, veh/h	2	0	5	5	0	1	6	33	7	1	57	3	
Conflicting Peds, #/hr	0	0	0	0	0	0	0	0	Ó	Ö	0	0	
Sign Control	Stop	Stop	Stop	Stop	Stop	Stop	Free	Free	Free	Free	Free	Free	
RT Channelized	-	- Otop	Stop	Otop	Otop	None	1100	-	None	-	-	None	
Storage Length	25	140	0	0	_	0	420		-	-	-	280	
Veh in Median Storage,		0			0			0			0		
Grade, %		0	8		0	-	740	0	_	_	0	-	
Peak Hour Factor	25	92	50	92	92	92	42	96	92	92	73	50	
Heavy Vehicles, %	0	2	9	2	2	2	14	7	2	2	8	2	
Mymt Flow	8	ō	10	5	0	1	14	34	8	1	78	6	
Major/Minor N	linor2		W 5 8	Minor1	17.3		Major1		1,3	Major2		Tale V	TO SEL
Conflicting Flow All	147		78	149		38	84	0	0	42	0	0	
Stage 1	80			66				-		- 1			
Stage 2	67			83	:+::								
Critical Hdwy	7.1		6.29	7.12		6.22	4.24			4.12		10.	
Critical Hdwy Stg 1	6.1	(=)	0.20	6.12		-			-	-			
Critical Hdwy Stg 2	6.1			6.12		-	A 5.		11.000	C 10 C 10			
Follow-up Hdwy	3.5	_	3.381	3.518	_	3.318	2.326		=	2.218	1 =	·	
Pot Cap-1 Maneuver	826	0	964	819	0	1034	1440		- 4	1567		- 2	
Stage 1	934	0	-	945	0			-	2	-			
Stage 2	948	0		925	0			X L			Unga		
Platoon blocked, %											-	2	
Mov Cap-1 Maneuver	819		964	804	T U	1034	1440		108	1567	10.15	41	
Mov Cap-2 Maneuver	819	-	-	804					-	-	-	40	
Stage 1	925		JIET.	936				14.4	E 2	100		12.1	
Stage 2	938		-	914	12	-	12	2	¥	-		546	
Marine St.													
Approach	EB	ST 17	10.00	WB		i Llio	NB	15.Ju	1131	SB	10	12 10	17 19
HCM Control Delay, s	9.1	ll'o T		9.3			1.9		4 _ 7,	0.1	LP C	17.11	
HCM LOS	Α			Α									
Minor Lane/Major Mvmt		NBL	NBT	NBR		EBLn2\	VBLn1V	VBLn2	SBL	SBT SBR			
Capacity (veh/h)		1440	113		819	964	804	1034	1567				
HCM Lane V/C Ratio		0.01			0.01	0.01	0.007	0.001	0.001				
HCM Control Delay (s)		7.5		V. Te	9.4	8.8	9.5	8.5	7.3	0 -			
HCM Lane LOS		Α		-	Α	Α	Α	Α	Α	Α -			
TION Land LOO													

-							_
Intersection		Park I		7.1	4.00	ile Y	1
Int Delay, s/veh	2.8						
		Enn	NUM	Althar	ODT	Opm	
Movement	EBL	EBR	NBL	NBT	SBT	SBR	EIII
Lane Configurations	*	12	7	↑	†	7*	
Traffic Vol., veh/h	0	12	5	34	24	0	
Future Vol, veh/h	0	12	5	34	24	0	
Conflicting Peds, #/hr		0	_ 0	_ 0	0	0	
Sign Control	Stop	Stop	Free	Free	Free	Free	
RT Channelized	-	Stop	400			None	
Storage Length	25	0	420	-	-	280	
Veh in Median Storage				0	0		
Grade, %	0	-	*	0	0	-	
Peak Hour Factor	92	45	38	68	90	92	
Heavy Vehicles, %	0	9	14	7	8	2	
Mvmt Flow	0	27	13	50	27	0	
Major/Minor	Minor2		Major1		Major2		
Conflicting Flow All	103	27	27	0	-	0	
Stage 1	27	21	21	-		-	
Stage 2	76						
Critical Hdwy	6.4	6.29	4.24	مدور			
Critical Hdwy Stg 1	5.4	0.29	4.24	-		EL V. S.	
Critical Hdwy Stg 2	5.4	1000					
Follow-up Hdwy	3.5	3.381	2.326	-		1 5	
				_	. Tr.		
Pot Cap-1 Maneuver	900	1029	1512	•	- 1	8	
Stage 1	1001			*		•	
Stage 2	952						
Platoon blocked, %	000	4000	4540			•	
Mov Cap-1 Maneuver		1029	1512	- 10	3 3	-	
Mov Cap-2 Maneuver		-	-	1.0	121		
Stage 1	992		£ - 8	1		-	
Stage 2	952	-	-	- 2	340	2	
Approach	EB		NB	NX.	SB		100
HCM Control Delay, s	_		1.5		0		
HCM LOS	Α		1.0		U		
HOW LOO	^			200			
Minor Lane/Major Mvn	nt	NBL	NBT	EBLn1	EBLn2	SBT	SBR
Capacity (veh/h)	Phi la	1512		TE.	1029	MY.	4.5
HCM Lane V/C Ratio		0.009			0.026		(€)
HCM Control Delay (s)	7.4		0	8.6	100	
HCM Lane LOS		Α		A	A		(*)
HCM 95th %tile Q(veh	1)	0		N. S. V.	0.1		
TOTAL COULT VOLICE OCCUPANT	,	U	_ 4 5		0.1		192

Intersection			وأنان	at Sin										
Int Delay, s/veh	1.9													
Movement	EBL	EBR	NBL	NBT	SBT	SBR	7 71	440	WITH S	18	J. 11/100	Time	5. TH	WE
Lane Configurations	N,	7	ሻ	^	†	7#								
Traffic Vol, veh/h	2	6	7	34	61	4								
Future Vol, veh/h	2	6	7	34	61	4								
Conflicting Peds, #/hr	0	0	0	0	0	0								
Sign Control	Stop	Stop	Free	Free	Free	Free								
RT Channelized		Stop		None										
Storage Length	25	0	420		-	280								
Veh in Median Storage		-	-	0	0									
Grade, %	0	(2)	2	0	0	u								
Peak Hour Factor	25	50	42	96	73	50								
Heavy Vehicles, %	0	9	14	7	8	2								
Mvmt Flow	8	12	17	35	84	8								
Major/Minor	Minor2		Major1		Major2	V In	521 27 5		. 9 81	V TT	N 14	11536		507
Conflicting Flow All	153	84	92	0	viajuiz	0								
-	84	04	92	U										
Stage 1	69				V	-								
Stage 2	6.4	6.29	4.24	_	: •:									
Critical Hdwy Critical Hdwy Stg 1	5.4	0.29	4.24											
	5.4		-	_										
Critical Hdwy Stg 2 Follow-up Hdwy	3.5	3.381	2.326											
Pot Cap-1 Maneuver	843	956	1430	-		10.50								
Stage 1	944	900	1430	- 2	-									
Stage 2	959			T-										
Platoon blocked, %	303													
Mov Cap-1 Maneuver	833	956	1430		0 30									
Mov Cap-1 Maneuver	833	330	1700		-									
Stage 1	933	0.2	THE STATE OF	1 2	- 9	2								
Stage 2	959	-	-	- 3		9								
Glaye Z	303					i u i								
State Control of the	1000		1970											
Approach	EB	Mag.	NB		SB	ببليه				1	لبليد		LW N	\$3X .
HCM Control Delay, s	9		2.4		0									
HCM LOS	Α													
Minor Lane/Major Mvn	nt	NBL	NBT	EBLn1	EBLn2	SBT	SBR	135 1	9 449	145			Mari	IFE.
Capacity (veh/h)		1430		833	956									
HCM Lane V/C Ratio		0.012		0.01	0.013									
HCM Control Delay (s))	7.5		9.4	8.8									
HCM Lane LOS		Α		Α	Α									
HCM 95th %tile Q(veh)	0		0	0	0 4	11.							

3: US 550 & Cascade Village Existing Access/Site 1 Access/-Term (2046) Background + Site Generated Traffic

Intersection	M 47 6		3 746	W. 10					10				
nt Delay, s/veh	3												
Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBI	SBT	SBR	
ane Configurations	7		7	ħ		7	ħ	↑			4	7	
Fraffic Vol, veh/h	0	0	12	8	0	1	5	39	2			0	
uture Vol, veh/h	0	0	12	8	0	1	5	39	2	•		0	
Conflicting Peds, #/hr	0	0	0	0	0	0	0	0	0		0	0	
Sign Control	Stop	Stop	Stop	Stop	Stop	Stop	Free	Free	Free	Free	Free	Free	
RT Channelized			Stop		140	None	VE	-	None			None	
Storage Length	25	: E	0	0	-	0	420	- 2			- 12	280	
eh in Median Storage,	# -	0			0	П.	1/2	0			- 0		
Grade, %	-	0	_	=	0	_	12	0	-		- 0	- 120	
Peak Hour Factor	92	92	45	92	92	92	38	68	92	92		92	
Heavy Vehicles, %	0	2	9	2	2	2	14	7	2	2		2	
Nymt Flow	0	0	27	9	0	1	13	57	2			0	
Major/Minor N	linor2			Minor1	4		Major1			Major2		271	
Conflicting Flow All	116	-	29	115		58	29	0	0	59	0	0	
Stage 1	31		- "	84	100			-				-	
Stage 2	85	-	-	31	j # 3		(*	:=0					
Critical Hdwy	7.1	5 L	6.29	7.12	(10)	6.22	4.24			4.12			
Critical Hdwy Stg 1	6.1	-	-	6.12		*	15	90	*			. 	
Critical Hdwy Stg 2	6.1			6.12			-		100			-	
Follow-up Hdwy	3.5	-	3.381	3.518	-	3.318	2.326		*	2.218	3 :-	:=0	
Pot Cap-1 Maneuver	865	0	1026	862	0	1008	1510			1545	,		
Stage 1	991	0	-	924	0	-	17.					(⊕)	
Stage 2	928	0	11/3	986	0		-		-				
Platoon blocked, %									77			3.00	
Mov Cap-1 Maneuver	858		1026	834	- 32	1008	1510	-		1545		20	
Nov Cap-2 Maneuver	858	-	-	834		5	0.5	2				3.00	
Stage 1	982		- 1	916	V (6)		- 2	- 3					
Stage 2	919	-	-	959				-	7			320	
									li.				
Approach	EB		31	WB			NB		- 100	SE			
HCM Control Delay, s	8.6			9.3			1.3			0.3	3		
HCM LOS	Α			Α									
		UT NOT				-12 4							
Minor Lane/Major Mvmt		NBL	NBT	NBR	=BLn1	EBLn2V			SBL	SBT SBF	CLEE		
Capacity (veh/h)		1510	1 2			10.000	834		1545				
HCM Lane V/C Ratio		0.009		*	-		0.01	0.001	0.001	-	-		
HCM Control Delay (s)		7.4			0	8.6	9.4	8.6	7.3		THE P		
HCM Lane LOS		Α	-	•	Α	Α	Α		Α	Α	-		
HCM 95th %tile Q(veh)		0		8 10	150	0.1	0	0	0				

Intersection	St 177		HVY	N. San		EN
Int Delay, s/veh	3.8					
Movement	EBL	EBR	NBL	NBT	SBT	SBR
Lane Configurations	3	7	ሻ	↑	f	457
Traffic Vol, veh/h	5	45	21	41	44	2
Future Vol, veh/h	5	45	21	41	44	2
Conflicting Peds, #/hr	0	0	0	0	0	0
Sign Control	Stop	Stop	Free	Free	Free	Free
RT Channelized	Otop	None	1100	None	-	None
Storage Length	0	0	0	NONE -		HOHE
Veh in Median Storage	_	-	-	0	0	
					_	
Grade, %	0	-	- 00	0	0	-
Peak Hour Factor	92	92	92	92	92	92
Heavy Vehicles, %	2	2	2	2	2	2
Mvmt Flow	5	49	23	45	48	2
Major/Minor	Minor2		Major1		Major2	
Conflicting Flow All	140	49	50	0	Island Inchines	0
Stage 1	49	-	-			
Stage 2	91			-	1	2
-	6.42	6.22	4.12	0.00		
Critical Hdwy			4,12	19.		
Critical Hdwy Stg 1	5.42		_	-	*	
Critical Hdwy Stg 2	5.42	1	- V -			
Follow-up Hdwy		3.318		-	-	:2
Pot Cap-1 Maneuver	853	1020	1557		-21	- 4
Stage 1	973	-	-	-	<u></u>	2
Stage 2	933			*	100	
Platoon blocked, %				=	: = 5	:=
Mov Cap-1 Maneuver	840	1020	1557		-	
Mov Cap-2 Maneuver	840	(#S	-	-	: *:	-
Stage 1	958	783			-	
Stage 2	933	200	-	_	1:41	-
Olage 2	500					
	-		1775			
Approach	EB	met of the	NB		SB	
HCM Control Delay, s	8.8		2.5		0	
HCM LOS	Α					
Minor Lane/Major Mvm	of .	NBL	MRT	EBLn1	ERI n2	SBT
	US					
Capacity (veh/h)		1557	-	840	1020	-1.5
HCM Lane V/C Ratio		0.015				- 3
HCM Control Delay (s)	0	7.3	100 6	9.3	8.7	3
HCM Lane LOS		Α	-	Α	Α	-
HCM 95th %tile Q(veh)	0	11.0	0	0.2	10,75

Intersection	Toj e	18		W.	Light.	111		V-1-5		7 7 7 8 8	400	10.3	
Int Delay, s/veh	2												
Movement	EBL	EBT	EBR	WBL	WBT	WBR	NBL	NBT	NBR	SBL	SBT	SBR	d tamberin
Lane Configurations	7		7	ħ		7	7	^			स्	7	
Traffic Vol, veh/h	2	0	6	5	0	1	7	38	7	1		4	- V 0 A 1 4 1
Future Vol, veh/h	2	0	6	5	0	1	7	38	7	1	66	4	
Conflicting Peds, #/hr	0	0	0	0	0	0	0	0	0	0	0	0	
Sign Control	Stop	Stop	Stop	Stop	Stop	Stop	Free	Free	Free	Free	Free	Free	
RT Channelized		1 6	Stop		- 2	None			None	CII I	-1/4° -	None	
Storage Length	25	-	0	0	-	0	420	-	5.75		-	280	
Veh in Median Storage,	# -	0	1 9	18	0	12		0			0	1 1	
Grade, %	-	0	.7	(\ 2)	0	5.		0			. 0		
Peak Hour Factor	25	92	50	92	92	92	42	96	92	92	73	50	
Heavy Vehicles, %	0	2	9	2	2	2	14	7	2	2	8	2	
Mvmt Flow	8	0	12	5	0	1	17	40	8	18 11	90	8	
Major/Minor N	linor2	J		Minor1			Major1			Major2			
Conflicting Flow All	171	-	90	174		44	98	0	0	48	0	0	
Stage 1	92		2	78		-			76				
Stage 2	79	-	-	96				_	1/2			-	
Critical Hdwy	7.1	11	6.29	7.12	21.2	6.22	4.24	- 2	114	4.12			
Critical Hdwy Stg 1	6.1	190		6.12	-	2		2	(4)		1 12	~	
Critical Hdwy Stg 2	6.1		1	6.12			-	1 4	1/21		100	2 100	
Follow-up Hdwy	3.5	-	3.381	3.518	-	3.318	2.326	2		2.218	12	-	
Pot Cap-1 Maneuver	797	0	949	789	0	1026	1423		LIF	1559	ETP	12	
Stage 1	920	0	-	931	0	-	-	-				- 4	
Stage 2	935	0	THE IS	911	0		`					100	
Platoon blocked, %								-	7=0		· =	4	
Mov Cap-1 Maneuver	788	15-1	949	772		1026	1423		-	1559	100	11 1	
Mov Cap-2 Maneuver	788	(€.	-	772	-	*:		-	(æ)			:4	
Stage 1	909			920						THE PARTY			
Stage 2	923		-	899					:(-)			-	
Approach	EB			WB			NB		BA.	SE			4.X1.7.1.10
HCM Control Delay, s	9.1	TAILE		9.5	1 (2	7,170	0.00	0.1			VIII CONTRACTOR
HCM LOS	Α			Α						0.1			
				إنعار					8 :	14, 14,			
Minor Lane/Major Mvmt	(= =	NBL	NBT	NBR F	Bl n1	EBLn2V	VBI n11	VBI n2	SBL	SBT SBR			
Capacity (veh/h)		1423			788	949		1026	1559	ODI ODI			
HCM Lane V/C Ratio		0.012		-		0.013		0.001	0.001	The state of the s			
HCM Control Delay (s)	221	7.6	. Tak	027	9.6	8.8	9.7	8.5	7.3				
HCM Lane LOS		Α.	-100	-	9.0 A	Α	9.7 A	6.5 A	7.5 A				
HCM 95th %tile Q(veh)		0		21 22	0	0	0	0	0	Α.			HAT THE P
HOW JOHN JOHN Q(VEII)		U	-	-	U	U	U	U	U				

Long-Term (2046) Background + Site Generated Traffic

Intersection	3.17		1 11116			
Int Delay, s/veh	3,3					
	ED)	EDD	NIDI	NDT	SBT	SBR
Movement	EBL	EBR	NBL	NBT		JOK
Lane Configurations	ħ	7	7	†	∱	F
Traffic Vol, veh/h	4	33	47	48	72	5
Future Vol, veh/h	4	33	47	48	72	5
Conflicting Peds, #/hr	0	0	0	_ 0	0	0
Sign Control	Stop	Stop	Free	Free	Free	Free
RT Channelized		None		None	- 2	None
Storage Length	0	0	0	: •	F-1	¥
Veh in Median Storage	e,# 0	100		0	0	
Grade, %	0	:45	2	0	0	¥
Peak Hour Factor	92	92	92	92	92	92
Heavy Vehicles, %	2	2	2	2	2	2
Mvmt Flow	4	36	51	52	78	5
WWITH FIOW	4	50	JI	JZ	10	J
Major/Minor	Minor2	VE EW	Major1		Vajor2	E S
Conflicting Flow All	235	81	83	0	: 9	0
Stage 1	81	-	-			
Stage 2	154				100	
	6.42	6.22	4.12		194	
Critical Hdwy			4.12		20	
Critical Hdwy Stg 1	5.42		1	*	2	
Critical Hdwy Stg 2	5.42	0.040	0.040		150	
Follow-up Hdwy		3.318		•	<u> </u>	
Pot Cap-1 Maneuver	753	979	1514			
Stage 1	942		-		•	
Stage 2	874		111		•	IEY IIE
Platoon blocked, %					•	8
Mov Cap-1 Maneuver	727	979	1514	ě		
Mov Cap-2 Maneuver	727	-	-	-	- 1	2
Stage 1	910		- Y		100	
Stage 2	874	-	-	-	4	-
Olago Z	317					
Approach	EB	25.33	NB		SB	
HCM Control Delay, s	8.9		3.7	1	0	
HCM LOS	А					
						8.1
Minor Lane/Major Mvn	nt	NBL	NBT	EBLn1		SBT
Capacity (veh/h)		1514		727	979	1
HCM Lane V/C Ratio		0.034	-	0.006	0.037	:7
HCM Control Delay (s) = 1	7.5	411.5	10	8.8	
HCM Lane LOS		Α		В	A	ā
HCM 95th %tile Q(veh	1	0.1			0.1	-
TOW COUL TOUC OCCOR	/	0.1		J	0.1	



Building a Better World for All of Us®

Sustainable buildings, sound infrastructure, safe transportation systems, clean water, renewable energy and a balanced environment. Building a Better World for All of Us communicates a company-wide commitment to act in the best interests of our clients and the world around us.

We're confident in our ability to balance these requirements.

Join Our Social Communities









COLORADO DEPARTMENT OF TRANSPORTATION STATE HIGHWAY ACCESS PERMIT APPLICATION

Issuing authority application acceptance date:

Instructions: Contact the Colorado Depart					
Please print Contact the issuing authority					
or type - Complete this form (some quinciple) - Submit an application for each	•	ou) and attach all necessary	documents a	ing Submit it to the	s issuing authority.
*Indicates = If you have any questions, co					
required field - For additional information, se		ment website at http://www.c	odot.gov/bus	siness/permits/acc	esspermits.
1) Property Owner (Permittee)*		2) Applicant or Agent for Pe	ermittee (if di	fferent from prope	rty owner)
Cascade Hospitality		SEH Inc Paul			. ,
Street Address*		Mailing Address			
PO Box 34781		934 Main Ave, l	Jnit C		
City, State & Zip* Phone #		City, State & Zip		Phone #	
Charlotte, NC 28234		Durango, CO 8		970.459.4	259
E-mail Address*		E-mail Address (if available	•		
		poneil@sehinc.	com		
3) Address of property to be served by permit*	00				
50221 Highway 550, Durango					
Legal description of property: (If within jurisdiction county subdivision block			towns	hin	range
county subdivision block San Juan 3	lot	section	391	14	range 9W
5) What State Highway are you requesting access f	rom?*	6) What side of the highway			
US 550		□N □S □E ®	•		
7) How many feet is the proposed access from the	nearest milepost (or cross s	I treet if mile post unknown)?*			
970 feet (■N □S □E □W) fro		, ,			
8) What is the approximate date you intend to begin	construction?				
08/01/2025					
9) Check here if you are requesting a:*					
	cess (duration anticipated:		•	to Existing Access	
☐ Change in Access Use ☐ Removal of A 10) Provide existing property use	ccess	□ R	elocation of	an Existing Access	s (provide detail)
Vacant					
11) Do you have knowledge of any State Highway a	ccess permits serving this	property, or adjacent properti	es in which	ou have a proper	ty interest?*
■ No ☐ Yes, if yes – what are the permi				ermit date:	
12) Does the property owner own or have any interest	ests in any adiacent propert	v?*			
□ No ■ Yes, if yes – please describe: □			erall dev	elopment	
13) Are there other existing or dedicated public stre ☐ No ☐ Yes, if yes – list them on your p				operty:	
14) If you are requesting agriculture field access - h	low many acres will the acc	ess serve?			
15) If you are requesting commercial or industrial acce	la-as indicate the bases	and number of businesses and	l pervide the	Poor area aguara fa	otogo of opph
Business/Land Use	Square Footage		s/Land Use	noor area square io	Square Footage
Buointoon Edina Coo					
16) If you are requesting residential development ac				mber of units?	
Туре	Number of Units	i	уре		Number of Units
Townhomes/Condos	102	Rest	araunt		1000
Single Family/Cabins	14	Re	etail		5000
17) Provide the following vehicle count estimates for	r vehicles that will use the a	access. Leaving the property	then returning	ng is two counts.*	
Indicate if your counts are	# of passenger cars and light	trucks at peak hour volumes	# of multi-unit	trucks at peak hour v	rolumes
peak hour volumes or average daily volumes.	89				
# of single unit vehicles in excess of 30 ft.	# of farm vehicles (field equip	, , , , , , , , , , , , , , , , , , ,	Total count of 39	f all vehicles	

1- It is the applicant's responsibility to contact appropriate agencies and obtain all environmental clearances that apply to their activities. Such clearances may include Corps of Engineers 404 Permits or Colorado Discharge Permit System permits, or ecological, archeological, historical or cultural resource clearances. Information about prohibited discharges, and may be obtained from Regional CoOT Utility/Special Use Permit offices or accessed via the COOT Plannipforsurtoin-Environmental-Guidance webpage: https://www.codot.gov/programs/environmental/resources/guidance-standards/environmental-clearances-info-summary-august-2017/view. 2- All workers within within the State Highway right of way shall comply with their employer's safety and health policies/ procedures, and all applicable U.S. Occupational Safety and Health Administration (OSHA) regulations -including, but not limited to the applicable sections of 29 CFR Part 1910 -Occupational Safety and Health Standards and 29 CFR Part 1926 - Safety and Health Regulations for Construction. Personal protective equipment (e.g. head protection, footwear, high visibility apparel, safety glasses, hearing protection, respirators, gloves, etc.) shall be worn as appropriate for the work being performed, and as specified in regulation. At a minimum, all workers in the State Highway right of way, except when in their vehicles, shall wear the following personal protective equipment High visibility apparel as specified in the Traffic Control provisions of the documentation accompanying the Notice to Proceed related to this permit (at a minimum, All Workers in the State Highway right of way, except when in their vehicles, shall wear the following personal protective equipment. High visibility apparel as specified in the Traffic Control provisions of the documentation accompanying the Notice to Proceed related to this permit (at a minimum, All Workers in the State Highway right of way, except when in their vehicles, shall wear the following personal protective equipment. Hi	 a) Property map indicating other access, bordering roads and s b) Highway and driveway plan profile. c) Drainage plan showing impact to the highway right-of-way. d) Map and letters detailing utility locations before and after development in and along the right-of-way. 	f) Propose g) Parcel a h) Traffic si	sion, zoning, or development pl d access design. ind ownership maps including of tudies. ownership.	
and all applicable U.S. Occupational Safety and Health Administration (OSHA) regulations -including, but not limited to the applicable sections of 29 CFR Part 1910 -Occupational Safety and Health Standards and 29 CFR Part 1926 - Safety and Health Regulations for Construction. Personal protective equipment (e.g. head protection, footwear, high visibility apparel, safety glasses, hearing protection, respirators, gloves, etc.) shall be wom as appropriate for the work being performed, and as specified in regulation. At a minimum, all workers in the State Highway right of way, except when in their vehicles, shall wear the following personal protective equipment: High visibility apparel as specified in the Traffic Control provisions of the documentation accompanying the Notice to Proceed related to this permit (at a minimum, ANSI/ISEA 107-1999, class 2); head protection that complies with the ANSI 289.1-1997 standard; and at all construction sites or whenever there is danger of injury to feet, workers shall comply with OSHA's PPE requirements for foot protection per 29 CFR 1910.136, 1926.95, and 1926.96. If required, such footwear shall meet the requirements of ANSI 241-1999. Where any of the above-referenced ANSI standards have been revised, the most recent version of the standard shall apply. 3- The Permittee is responsible for complying with the Revised Guidelines that have been adopted by the Access Board under the American Disabilities Act (ADA). These guidelines define traversable slope requirements and prescribe the use of a defined pattern of truncated domes as detectable warnings at street crossings. The new Standards Plans and can be found on the Design and Construction Project Support web page at: https://www.codot.gov/business/civ/linchts/ada/resources-engineers. If an access permit is issued to you, it will state the terms and conditions for its use. Any changes in the use of the permitted access not consistent with the terms and conditions listed on the permit may be considered a violation of the p	activities. Such clearances may include Corps of Engineer ecological, archeological, historical or cultural resource cle presents contact information for agencies administering ce obtained from Regional COOT Utility/Special Use Permit of Guidance webpage: https://www.codot.gov/programs/environments/	s 404 Permits or Colora arances. The COOT Er rtain clearances, inform ffices or accessed via the	ado Discharge Permit Sys nvironmental Clearances I nation about prohibited dis he COOT Planning/Const	tem permits, or nformation Summary charges, and may be ruction-Environmental-
Personal protective equipment (e.g. head protection, footwear, high visibility apparel, safety glasses, hearing protection, respirators, gloves, etc.) shall be worn as appropriate for the work being performed, and as specified in regulation. At a minimum, all workers in the State Highway right of way, except when in their vehicles, shall wear the following personal protective equipment: High visibility apparel as specified in the Traffic Control provisions of the documentation accompanying the Notice to Proceed related to this permit (at a minimum, ANSI/ISEA 107-1999, class 2); head protection that complies with the ANSI 289.1-1997 standard; and at all construction sites or whenever there is danger of injury to feet, workers shall comply with OSHA's PPE requirements for foot protection per 29 CFR 1910.136, 1926.95, and 1926.96. If required, such footwear shall meet the requirements of ANSI 241-1999. Where any of the above-referenced ANSI standards have been revised, the most recent version of the standard shall apply. 3- The Permittee is responsible for complying with the Revised Guidelines that have been adopted by the Access Board under the American Disabilities Act (ADA). These guidelines define traversable slope requirements and prescribe the use of a defined pattern of truncated domes as detectable warnings at street crossings. The new Standards Plans and can be found on the Design and Construction Project Support web page at: https://www.codol.gov/business/civilrights/ada/resources-engineers . If an access permit is issued to you, it will state the terms and conditions for its use. Any changes in the use of the permited access not consistent with the terms and conditions listed on the permit may be considered a violation of the permit. The applicant declares under penalty of perjury in the second degree, and any other applicable state or federal laws, that all information provided on this form and submitted attachments are	and all applicable U.S. Occupational Safety and Health Ad	ministration (OSHA) reg	gulations -including, but no	ot limited to the
gloves, etc.) shall be worn as appropriate for the work being performed, and as specified in regulation. At a minimum, all workers in the State Highway right of way, except when in their vehicles, shall wear the following personal protective equipment: High visibility apparel as specified in the Traffic Control provisions of the documentation accompanying the Notice to Proceed related to this permit (at a minimum, ANSI/ISEA 107-1999, class 2); head protection that complies with the ANSI 289.1-1997 standard; and at all construction sites or whenever there is danger of injury to feet, workers shall comply with OSHA's PPE requirements for foot protection per 29 CFR 1910.136, 1926.95, and 1926.96. If required, such footwear shall meet the requirements of ANSI 241-1999. Where any of the above-referenced ANSI standards have been revised, the most recent version of the standard shall apply. 3- The Permittee is responsible for complying with the Revised Guidelines that have been adopted by the Access Board under the American Disabilities Act (ADA). These guidelines define traversable slope requirements and prescribe the use of a defined pattern of truncated domes as detectable warnings at street crossings. The new Standards Plans and can be found on the Design and Construction Project Support web page at: https://www.codot.gov/business/civilrights/ada/resources-engineers . If an access permit is issued to you, it will state the terms and conditions for its use. Any changes in the use of the permitted access not consistent with the terms and conditions listed on the permit may be considered a violation of the permit. The applicant declares under penalty of perjury in the second degree, and any other applicable state or federal laws, that all information provided on this form and submitted attachments are to the best of their knowledge true and complete. I understand receipt of an access permit does not constitute permission to start acce	- Safety and Health Regulations for Construction.			
3- The Permittee is responsible for complying with the Revised Guidelines that have been adopted by the Access Board under the American Disabilities Act (ADA). These guidelines define traversable slope requirements and prescribe the use of a defined pattern of truncated domes as detectable warnings at street crossings. The new Standards Plans and can be found on the Design and Construction Project Support web page at: https://www.codot.gov/business/civilrights/ada/resources-engineers . If an access permit is issued to you, it will state the terms and conditions for its use. Any changes in the use of the permitted access not consistent with the terms and conditions listed on the permit may be considered a violation of the permit. The applicant declares under penalty of perjury in the second degree, and any other applicable state or federal laws, that all information provided on this form and submitted attachments are to the best of their knowledge true and complete. I understand receipt of an access permit does not constitute permission to start access construction work. Applicant or Agent for Permittee Signature Print Name Paul O'Neil If the applicant is not the owner of the property, we require this application also to be signed by the property owner or their legally authorized representative (or other acceptable written evidence). This signature shall constitute agreement with this application by all owners-of-interest unless stated in writing. If a permit is issued, the property owner, in most cases, will be listed as the permittee.	gloves, etc.) shall be worn as appropriate for the work beir the State Highway right of way, except when in their vehicl apparel as specified in the Traffic Control provisions of the (at a minimum, ANSI/ISEA 107-1999, class 2); head protection construction sites or whenever there is danger of injury to	ig performed, and as spes, shall wear the follow documentation accomption that complies with feet, workers shall comp	pecified in regulation. At a ving personal protective expanying the Notice to Procethe ANSI 289.1-1997 starely with OSHA's PPE required	minimum, all workers in quipment: High visibility eed related to this permit dard; and at all tirements for foot
3- The Permittee is responsible for complying with the Revised Guidelines that have been adopted by the Access Board under the American Disabilities Act (ADA). These guidelines define traversable slope requirements and prescribe the use of a defined pattern of truncated domes as detectable warnings at street crossings. The new Standards Plans and can be found on the Design and Construction Project Support web page at: https://www.codot.gov/business/civilrights/ada/resources-engineers . If an access permit is issued to you, it will state the terms and conditions for its use. Any changes in the use of the permitted access not consistent with the terms and conditions listed on the permit may be considered a violation of the permit. The applicant declares under penalty of perjury in the second degree, and any other applicable state or federal laws, that all information provided on this form and submitted attachments are to the best of their knowledge true and complete. I understand receipt of an access permit does not constitute permission to start access construction work. Applicant or Agent for Permittee Signature Print Name Paul O'Neil If the applicant is not the owner of the property, we require this application also to be signed by the property owner or their legally authorized representative (or other acceptable written evidence). This signature shall constitute agreement with this application by all owners-of-interest unless stated in writing. If a permit is issued, the property owner, in most cases, will be listed as the permittee.	Where any of the above-referenced ANSI standards have	peen revised, the most	recent version of the stan	dard shall apply.
not consistent with the terms and conditions listed on the permit may be considered a violation of the permit. The applicant declares under penalty of perjury in the second degree, and any other applicable state or federal laws, that all information provided on this form and submitted attachments are to the best of their knowledge true and complete. I understand receipt of an access permit does not constitute permission to start access construction work. Applicant or Agent for Permittee Signature Print Name Paul O'Neil Date 04/15/2025 If the applicant is not the owner of the property, we require this application also to be signed by the property owner or their legally authorized representative (or other acceptable written evidence). This signature shall constitute agreement with this application by all owners-of-interest unless stated in writing. If a permit is issued, the property owner, in most cases, will be listed as the permittee.	3- The Permittee is responsible for complying with the Rev American Disabilities Act (ADA). These guidelines define to of truncated domes as detectable warnings at street crossi	ised Guidelines that ha aversable slope requirency. The new Standard	ve been adopted by the A ements and prescribe the Is Plans and can be found	ccess Board under the use of a defined pattern on the Design and
all information provided on this form and submitted attachments are to the best of their knowledge true and complete. I understand receipt of an access permit does not constitute permission to start access construction work. Applicant or Agent for Permittee Signature Print Name Paul O'Neil If the applicant is not the owner of the property, we require this application also to be signed by the property owner or their legally authorized representative (or other acceptable written evidence). This signature shall constitute agreement with this application by all owners-of-interest unless stated in writing. If a permit is issued, the property owner, in most cases, will be listed as the permittee.	If an access permit is issued to you, it will state the terms a not consistent with the terms and conditions listed on the p	and conditions for its use ermit may be considere	e. Any changes in the use	of the permitted access
Applicant or Agent for Permittee Signature Print Name Paul O'Neil Date 04/15/2025 If the applicant is not the owner of the property, we require this application also to be signed by the property owner or their legally authorized representative (or other acceptable written evidence). This signature shall constitute agreement with this application by all owners-of-interest unless stated in writing. If a permit is issued, the property owner, in most cases, will be listed as the permittee.	The applicant declares under penalty of perjury in the all information provided on this form and submitted at	second degree, and a lachments are to the l	ny other applicable state best of their knowledge	e or federal laws, that true and complete.
Paul O'Neil O4/15/2025 If the applicant is not the owner of the property, we require this application also to be signed by the property owner or their legally authorized representative (or other acceptable written evidence). This signature shall constitute agreement with this application by all owners-of-interest unless stated in writing. If a permit is issued, the property owner, in most cases, will be listed as the permittee.	I understand receipt of an access permit does not con	stitute permission to s	start access constructio	n work.
If the applicant is not the owner of the property, we require this application also to be signed by the property owner or their legally authorized representative (or other acceptable written evidence). This signature shall constitute agreement with this application by all owners-of-interest unless stated in writing. If a permit is issued, the property owner, in most cases, will be listed as the permittee.	,		I	
Property Owner Signature Print Name Date	If the applicant is not the owner of the property, we require authorized representative (or other acceptable written evid	ence). This signature st	hall constitute agreement	with this application by
	Property Owner Signature	Print Name		Date

18) Check with the issuing authority to determine which of the following documents are required to complete the review of your application.

INSTRUCTIONS FOR COMPLETING APPLICATION FOR ACCESS PERMIT (CDOT FORM NO. 137)

December 2018

To construct, relocate, close, or modify access(es) to a State Highway or when there are changes in use of such access point(s), an application for access permit must be submitted to the Colorado Department of Transportation (CDOT) or the local jurisdiction serving as the issuing authority for State Highway Access Permits. Contact the CDOT Regional Access Unit in which the subject property is located to determine where the application must be submitted. The following link will help you determine which CDOT Region office to contact:

https://www.codot.gov/business/permits/accesspermits/regional-offices.html

All applications are processed and access permits are issued in accordance to the requirements and procedures found in the most current version of the State Highway Access Code (Access Code). Code and the application form are also available from CDOT's web site at:

https://www.codot.gov/business/permits/accesspermits

Please complete all information requested accurately. Access permits granted based on applications found to contain false information may be revoked. An incomplete application will not be accepted. If additional information, plans and documents are required, attach them to the application. Keep a copy of your submittal for your records. Please note that only the original signed copy of the application will be accepted. Do not send or enclose any permit fee at this time. A permit fee will be collected if an access permit is issued. The following is a brief description of the information to be provided on each enumerated space on the application form (CDOT Form 137, 2010).

- 1. Property Owner (Permittee): Please provide the full name, mailing address and telephone number and the E-mail address (if available) of the legal property owner (owner of the surface rights). Please provide a telephone number where the Permittee can be reached during business hours (8:00 a.m. to 5:00 p.m.). Having a contract on the property is not a sufficient legal right to that property for purposes of this application. If the access is to be on or across an access easement, then a copy of the easement MUST accompany this application. If federal land is involved, provide the name of the relevant federal agency AND attach copy of federal authorization for property use.
- 2. Agent for permittee: If the applicant (person completing this application) is different than the property owner (Permittee), provide entity name (if applicable), the full name of the person serving as the Agent, mailing address, telephone number, and the E-mail address (if available). Please provide a telephone number where the Agent can be reached during business hours (8:00 a.m. to 5:00 p.m.). Joint applications such as owner/lessee may be submitted. Corporations must be licensed to do business in Colorado: All corporations serving as, or providing, an Agent as the applicant must be licensed to do business in Colorado.

- 3. Address of Property to be Served: Provide if property to be served has an official street address. If the access is a public road, note the name (or future name) of the road.
- 4. Legal Description of Property: Fill in this item to the extent it applies. This information is available at your local County Courthouse, or on your ownership deed(s). A copy of the deed may be required as part of this application in some situations. To determine applicability, check with the CDOT's Regional Access Manager or issuing authority staff.
- 5. State Highway: Provide the State Highway number from which the access is requested.
- **6. Highway Side:** Mark the appropriate box to indicate what side of the highway the requested access is located.
- **Access Mile Point:** Without complete information, we may not be able to locate the proposed access. To obtain the distance in feet, drive the length between the mile point and the proposed access, rounding the distance on the odometer to the nearest tenth of a mile; multiply the distance by 5,280 feet to obtain the number of feet from the mile point. Then enter the direction (i.e. north, south, east, west) from the mile point to the proposed access. Finally, enter the mile point number. It is helpful in rural or undeveloped areas if some flagging is tied to the right-of-way fence at the desired location of the access. If the mile post is unknown, note the distance in feet (using the same procedures noted above) from that cross street or road closest to the proposed access.
- **8. Access Construction Date**: Fill in the date on which construction of the access is planned to begin.
- 9. Access Request: Mark items that apply. More than one item may be checked.
- 10. Existing property use: Describe how the property is currently being used. For example, common uses are Single Family Residential, Commercial or Agricultural.
- 11. Existing Access: Does the property have any other legal alternatives to reach a public road other than the access requested in this application? Note the access permit number(s) for any existing state highway access point(s) along with their issue date(s). If there are no existing access point(s), mark the "no" box.
- **12. Adjacent Property:** Please mark the appropriate box. If the "yes" box is marked, provide a brief description of the property (location of the property in relation to the property for which this access application is being made).
- 13. Abutting Streets: If there are any other existing or proposed public roads or easements abutting the property, they should be shown on a map or plan attached to this application.
- 14. Agricultural Acres: Provide number of acres to be served.

- 15. Access Use: List the land uses and square footage of the site as it will be when it is fully developed. The planned land uses as they will be when the site is fully developed are used to project the amount of traffic that the site will generate, peak hour traffic levels and the type of vehicles that can be expected as a result of the planned land uses. There may be exceptional circumstances that would allow phased installation of access requirements. This is at the discretion of the CDOT Regional Access Unit or issuing authority staff.
- 16. Estimated Traffic Count: Provide a reasonable estimate of the traffic volume expected to use the access. Note the type of vehicles that will use the access along with the volume (number of vehicles in and out at either the peak hour or average daily rates) for each type of vehicle. A vehicle leaving the property and then returning counts as two trips. If 40 customers are expected to visit the business daily, there would be 80 trips in addition to the trips made by all employees and other visitors (such as delivery and trash removal vehicles). If the PDF on-line version of this application is being used, the fields for each type of vehicle will automatically be added together to populate the last field on the page.
- 17. Documents and Plans: The CDOT Regional Access Manager or issuing authority staff will determine which of these items must be provided to make the application complete. Incomplete applications will not be accepted. If an incomplete application is received via U.S. mail or through means other than in the hand of the Access Manager or issuing authority staff, it will not be processed. It is the responsibility of the applicant to verify with the CDOT Regional Access Manager or issuing authority staff whether the application is complete at the time of submission.

Signature: Generally, if the applicant is not the property owner, then the property owner or a legally authorized representative must sign the application. With narrow exceptions, proof of the property owner's consent is required to be submitted with the application (proof may be a power of attorney or a similar consent instrument). The CDOT Regional Access Manager or issuing authority staff will determine if the exception provided in the Access Code (2.3 (3) (b)) is applicable.

If CDOT is the issuing authority for this application, direct your questions to the CDOT Regional Access Manager or the issuing authority staff serving the subject property.

https://www.codot.gov/business/permits/accesspermits/regional-offices.html

If the application is accepted, it will be reviewed by the CDOT Regional Access Manager or the issuing authority staff. If an Access Permit is issued, be sure to read all of the attached Terms and Conditions before signing and returning the Access Permit. The Terms and Conditions may require that additional information be provided prior to issuance of the Notice to Proceed.

The CDOT Regional Access Manager (or issuing authority staff) MUST be contacted prior to commencing work on any Access Permit project. A Notice to Proceed that authorizes the Permittee to begin access related construction MUST be issued prior to working on the access in the State Highway right-of-way. The Notice to Proceed may also have Terms and Conditions that must be fulfilled before work may begin on the permitted access.



Memo

To:

William Tookey, San Juan County Administrator

From:

Sean Moore (SME Environmental, Inc.)

Date:

July 18, 2025

Re:

Status of 404 permitting for the Cascade Village Tracts A1-B1 project

Introduction

The purpose of this memorandum is to summarize the status of Clean Water Act Section 404 Permitting for the Cascade Village Tracts A1-B1 project which is located west of US Highway 550 just north of the San Juan/La Plata County boundary. As summarized in the attached letter from Reynolds Ash + Associates (Attachment A), for a couple of reasons, the project proponent plans to phase the construction of the development. Phase I will entail the construction of the access road from the southern end of the existing Cascade Village development to a shred access point on US 550 with the landowner due south of the subject property. Subsequent phases of the Cascade Village Tracts A1-B1 project will entail the build out of residential units served by the access road constructed in Phase I.

Phased 404 Permitting

Since the construction of Phase I will incur an impact of 0.18 acre of wetland impact, SME has prepared a Pre-construction Notification for Nationwide Permit (NWP) #14 (Linear Transportation Crossings) that will be submitted to the US Army Corps of Engineers (USACE) in the coming weeks. If necessary, subsequent phases of the development would be permitted under either NWP #39 (Commercial and Institutional Developments) of an Individual 404 Permit, per confirmation from the USACE.

Pending Revision to Jurisdictional Limits of Waters of the US

In March of 2025 the US Environmental Protection Agency released a memo summarizing forthcoming new guidance on adjacent (currently jurisdictional) wetlands (Attachment C). Implementation of the new guidance is expected sometime in the next 18 months. Should the details on implementation include the second bullet in the attached memo: wetlands separated from local perennial or intermittent streams by "berms, dikes, uplands or indirect hydrologic features (ditches, swales, pipes, etc.) no longer qualify as adjacent". The wetland complex in the Cascade Village Tracts A1-B1 project area is such a wetland as it is connected to Cascade Creek/the Animas River through culverts under US 550 on the Durango Mountain Resort/Purgatory property. Should these culverts serve as a disconnect of USACE jurisdiction when the new guidance becomes official, impacts to the wetland complex

resulting from Phase II (and beyond) of the Cascade Village Tracts A1-B1 project would not require a 404 Permit. This is another reason the project proponent feels it is important to phase implementation of the project as completion of the residential component of the project without the need for 4094 Permitting and required mitigation will realize a significant cost savings.

ATTACHMNENT A Project Phasing Letter (from RA+A)



ARCHITECTURE & ENGINEERING

06-21-2025

CASCADE MEADOWVIEW DRIVE

Application for a 404 Permit

To: The Army Corps of Engineers SME Environmental, Inc.

To Whom it May Concern,

Reynolds Ash and Associates (RA+A) has been working diligently with the owner and San Juan County on building out the southern portion of the master plan for Cascade Village in Durango, Colorado. The south side of the original master plan includes about 79 acres of land including what is referred to as Tract A-1/Tract B-1. The Cascade Village master plan is approved for additional residential and multi-family units that extend from the current edge of development to the southern boundary. The long term build out is anticipating about 50-60 residential units that will be part of the full build out. The master plan requires an extension of Meadowview Road, which will connect the existing road to a south entry off of Highway 550. However, the residential units will take more time to get fully approved, entitled and permitted through San Juan County.

Recently, Xcel impacted the site in question, to install a new pipeline that follows the proposed path of Meadowview Drive. The installation of the pipeline disturbed the soil and presumably touched the existing wetlands.

The design team, working with the Owner, has designed the completion of the road to include full grading, specs for paved driving surface, rough in for utilities to serve future build out. The design meets best practices, follows the easement established by the Xcel pipeline and to the best of our abilities, has minimal impact to the wetlands. Our civil engineer has kept all grading as tight as possible.

However, due to the short building season and the potential for the Corps to modify how wetlands are defined, the owner wishes only to build out the road in the first phase of construction. Following the road installation, the Owner will submit additional land use applications to San Juan County for the building pads and residential improvements. Since the road has a small impact to the wetlands, and since there could be a shift in jurisdictional wetlands, we believe that phasing the permits for this project are best.

Once the Corps comes out with new guidance on jurisdiction, the design team can better plan for and adjust as necessary the plan for build out.

Thank you,

auren Davis, AIA, AICP

APPENDIX B Pre-Construction Notification for NWP 14 for Phase I

U.S. Army Corps of Engineers (USACE)

NATIONWIDE PERMIT PRE-CONSTRUCTION NOTIFICATION (PCN)

33 CFR 330. The proponent agency is CECW-CO-R.

Form Approved -OMB No. 0710-0003 Expires: 02-28-2022

DATA REQUIRED BY THE PRIVACY ACT OF 1974

Authority

Rivers and Harbors Act, Section 10, 33 USC 403; Clean Water Act, Section 404, 33 USC 1344; Regulatory Program of the Corps of

Engineers (Corps); Final Rule 33 CFR 320-332.

Principal Purpose Information provided on this form will be used in evaluating the nationwide permit pre-construction notification.

Routine Uses

This information may be shared with the Department of Justice and other federal, state, and local government agencies, and the public and

may be made available as part of the agency coordination process.

Disclosure

Submission of requested information is voluntary, however, if information is not provided the permit application cannot be evaluated nor can

a permit be issued.

The public reporting burden for this collection of information, 0710-0003, is estimated to average 11 hours per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding the burden estimate or burden reduction suggestions to the Department of Defense, Washington Headquarters Services, at whs.mc-alex.esd.mbx.dd-dod-information-collections@mailto:mil. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.

PLEASE DO NOT RETURN YOUR RESPONSE TO THE ABOVE EMAIL.

One set of original drawings or good reproducible copies which show the location and character of the proposed activity must be attached to this application (see sample drawings and/or instructions) and be submitted to the district engineer having jurisdiction over the location of the proposed activity. An application that is not completed in full will be returned.

not completed in rail will be retarned.							
(ITEMS 1 THRU 4 TO BE FILLED BY THE CORPS)							
1. APPLICATION NO.	2. FIELD OFFICE CODE		3. DATE RECEIVED	4. DATE APPLICATION COMPLETE			
(ITEMS BELOW TO BE FILLED BY APPLICANT)							
5. APPLICANT'S NAME 8.			8. AUTHORIZED AGENT'S NAME AND TITLE (agent is not required)				
First - Charles Middle - Lindsey	Last - McAlpine	First - Sean	Middle -	Last - Moore			
Company - CitiSculpt		Company - SME Environmental, Inc. (SME)					
Company Title -		E-mail Address - smoore@sme-env.com					
E-mail Address - Lmcalpine@citisculpt.com							
6. APPLICANTS ADDRESS		9. AGENT'S ADDRESS					
Address- 1355 Greenwood Cliff #150		Address- 679 East 2nd Avenue Unit 8					
City - Charlotte State - NC Z	Zip - 28204 Country - USA	City - Duran	go State - C	O Zip - 81301 Country - USA			
7. APPLICANT'S PHONE NOs. with AREA COI	10. AGENT'S PHONE NOs. with AREA CODE						
a. Residence b. Business c. Fax 704-361-3758	d. Mobile	a. Residence	b. Business (970) 259-9595	c. Fax d. Mobile (970) 259-0050			
	STATEMENT OF	AUTHORIZATI	ON				
11. I hereby authorize,SME Environmental, Inc to act in my behalf as my agent in the processing of this nationwide permit pre-construction notification							
and to furnish, upon request, supplemental information in support of this nationwide permit pre-construction notification.							
	SIGNATURE OF APPLICA	ANT	DATE				
NAME, LOCATION, AND DESCRIPTION OF PROJECT OR ACTIVITY							
2. PROJECT NAME or TITLE (see instructions) Cascade Village Tracts A1-B1							


NAME, LOCATION, AND DESCRIPTION OF PROJECT OR ACTIVITY							
13. NAME OF WATERBODY, IF KNOWN (if applicable)	14. PROPOSED ACTIVITY STREET ADDRESS (if applicab South of and adjacent to 56 Meadowview Dr	le)				
15. LOCATION OF PROPOSED ACTIVITY		Cily:	State:	Zip:			
	ongitude °W 07.810142	Durango	СО	81301			
16. OTHER LOCATION DESCRIPTIONS,	IF KNOWN (see instructions)						
State Tax Parcel ID		Municipality Durango					
Section 13	Township 39N	Range 9W					
17. DIRECTIONS TO THE SITE The project site is located west of U.S. Highway 550, north of Purgatory Resort by about .8 mile, and just south of the Cascade Village development in San Juan County, Colorado. Exit west off U.S. Highway 550 on Meadowview Drive and proceed left (south) on Meadowview Drive. Continue south on Meadowview Drive until the road ends at a cul-de-sac. The project site is located south and west of the end of the cul-de-sac. A road map is provided as Figure '1' and a topographic map is provided as Figure'2' in the Aquatic Resources Delineation Report (Appendix 'A' of Attachment '2'). 18. IDENTIFY THE SPECIFIC NATIONWIDE PERMIT(S) YOU PROPOSE TO USE Nationwide Permit 14 - Linear Transportation Projects							
19. DESCRIPTION OF PROPOSED NATIONWIDE PERMIT ACTIVITY (see instructions) The proposed project involves the installation of the extension of Meadowview Road, which will connect the existing road to a south entry off of Highway 550. The design of the road includes full grading, specs for paved driving surface, and rough in for utilities to serve future build out. The road is the first phase of this project and the subject of this PCN. The second phase includes the development and building of additional residential and multi family units and will be permitted under a future 404 Permit action if necessary.							
20. DESCRIPTION OF PROPOSED MITIGATION MEASURES (see instructions) Mitigation will occur through the Animas River Wetlands Bank. Additionally, standard construction practices would be implemented on-site (as applicable) to minimize impacts to aquatic resources to the maximum extent practicable during construction. BMPs would be used to prevent erosion and sediment runoff prior to, during and after construction (as necessary and applicable) to minimize impacts to important natural resources. Any exposed slopes or areas of disturbed soil would be stabilized and revegetated as soon as possible upon completion of construction. All temporary impact areas will be restored to pre-construction conditions.							
21. PURPOSE OF NATIONWIDE PERMIT ACTIVITY (Describe the reason or purpose of the project, see instructions) The purpose of the Nation Wide permit is to construct an access road to that eventually provide access to the Cascade Village Tracts A1 - B1 development.							
22. QUANTITY OF WETLANDS, STREAM: (see instructions)	S, OR OTHER TYPES OF WATE	ERS DIRECTLY AFFECTED BY PROPOSED NATIONWIDE PER	MIT ACT	IVITY			
Acres 0.184 (8,021 sq ft) see Figure 1	Linear Feet N/A	Cubic Yards Dredged or Discha N/A	rged				
Each PCN must include a delineation of wetlands, other special aquatic sites, and other waters, such as lakes and ponds, and perennial, intermittent, and ephemeral streams, on the project site.							
related activity. (see instructions) 24. If the proposed activity will result in the	loss of greater than 1/10-acre of v	used or intended to be used to authorize any part of the proposed wetlands and requires pre-construction notification, explain how the second contract of the proposed wetlands and requires pre-construction notification, explain how the second contract of the proposed wetlands and requires pre-construction notification, explain how the second contract of the proposed co	he compe	nsatory			
mitigation requirement in paragraph (c) of general condition 23 will be satisfied, or explain why the adverse environmental effects are no more than minimal and why compensatory mitigation should not be required for the proposed activity. The proposed project would result in the loss of greater than 1/10 acre of wetlands. Total impacts equal to 0.181 acres of PEM wetland.							

ENG FORM 6082, OCT 2019 Page 2 of 6

installed before construction begins and would remain in place until construction is completed, with removal as appropriate. Following completion of construction activities, temporary impact areas wold be restored to pre-construction conditions and revegetated, as appropriate.
25. Is any portion of the nationwide permit activity already complete? Yes No If Yes, describe the completed work:
26. List the name(s) of any species listed as endangered or threatened under the Endangered Species Act that might be affected by the proposed NWP activity or utilize the designated critical habitat that might be affected by the proposed NWP activity. (see instructions)
27. List any historic properties that have the potential to be affected by the proposed NWP activity or include a vicinity map indicating the location of the historic property or properties. (see instructions) The following information is provided in accordance with General Condition 20 Historic Properties. SME contacted the Colorado Office of Archaeology and Historic Preservation (OAHP) to request a database search for the proposed project area on June 30, 2025. The Colorado OAHP usually provides results within 20 business days from the request. SME will provide cultural results when they are received.
28. For a proposed NWP activity that will occur in a component of the National Wild and Scenic River System, or in a river officially designated by Congress as a "study river" for possible inclusion in the system while the river is in an official study status, identify the Wild and Scenic River or the "study river": N/A
29. If the proposed NWP activity also requires permission from the Corps pursuant to 33 U.S.C. 408 because it will alter or temporarily or permanently occupy or use a U.S. Army Corps of Engineers federally authorized civil works project, have you submitted a written request for section 408 permission from the Corps district having jurisdiction over that project? Yes No If "yes", please provide the date your request was submitted to the Corps district: N/A
30. If the terms of the NWP(s) you want to use require additional information to be included in the PCN, please include that information in this space or provide it on an additional sheet of paper marked Block 30. (see instructions) N/A
31. Pre-construction notification is hereby made for one or more nationwide permit(s) to authorize the work described in this notification. I certify that the information in this pre-construction notification is complete and accurate. I further certify that I possess the authority to undertake the work described herein or am acting as the duly authorized agent of the applicant.
SIGNATURE OF APPLICANT DATE SIGNATURE OF AGENT DATE
The pre-construction notification must be signed by the person who desires to undertake the proposed activity (applicant) and, if the statement in Block 11 has been filled out and signed, the authorized agent. 18 U.S.C. Section 1001 provides that: Whoever, in any manner within the jurisdiction of any department or agency of the United States knowingly and willfully falsifies, conceals, or covers up any trick, scheme, or disguises a material fact or makes any false, fictitious or fraudulent statements or representations or makes or uses any false writing or document knowing same to contain any false, fictitious or fraudulent statements or entry, shall be fined not more than \$10,000 or imprisoned not more than five years or both.

ENG FORM 6082, OCT 2019 Page 3 of 6

ATTACHMENT 1 Impacts Figures






Drawn By:	Rywd. By:	Proj. No.:
SB	SM	240008
Date:	Rvsd. Date:	Seale:
7/2/2025	NA	1 in = 317 fc
N		
1 1	0 3	240 480

AQUATIC RESOURCES DELINEATION CASCADE VILLAGE TRACTS A1-B1 SAN JUAN COUNTY, CO

FIGURE

ATTACHMENT 2 Aquatic Resources Delineation Report

Aquatic Resources Delineation Report Cascade Village Tracts A1-B1 San Juan County, CO



Prepared for:

Prepared by:

CitiSculpt 1355 Greenwood Cliff, #150 Charlotte, North Carolina, 28204



July 2025

EXECUTIVE SUMMARY

Wetlands and other Waters of the U.S. (WOUS) in Cascade Village Tracts A1-B1 survey area were identified by SME Environmental, Inc. (SME) on June 16th, 2025 using the methodology defined in the Routine Determination procedure set forth in the U.S. Army Corps of Engineers Wetlands Delineation Manual (USACE 1987) and the Regional Supplement: Western Mountains, Valleys, and Coast Region (Version 2.0). Aquatic resources boundaries were surveyed based on presence of hydrophytic vegetation, hydric soils, and hydrologic indicators that under normal conditions would indicate wetland conditions. Additionally, SME surveyed for the presence of an ordinary high-water mark (OHWM) in accordance with the National Ordinary High Water Mark Field Delineation Manual for Rivers and Streams: Final Version (USACE 2025).

The Cascade Village Tracts A1-B1 Project survey area is 79.50 acres. Based on the site investigation, approximately 7.36 acre (320,679 sq. feet) of aquatic resources exist in the survey area. The survey area is located west of U.S. Highway 550, north of Purgatory resort about 0.8 mile, and just south of Cascade Village Condos in Durango, CO within San Juan County. SME prepared this report for Charles McAlpine of CitiSculpt to document the boundaries of aquatic resources within the survey area of Cascade Village Tracts A1-B1 project.

TABLE OF CONTENTS

1.0	INTRODUCTION	1
2.0	PROJECT LOCATION	1
3.0	DELINEATION METHODS	2
4.0	EXISTING CONDITIONS	2
4.1	Landscape Setting	2
4.2	Aquatic Resources Error! Bookman	k not defined.
4.3	Vegetation	3
4.4	Soils	3
4.5	Hydrology	4
4.6	Interstate Commerce	4
4.7	Limitations	4
5.0	REFERENCES – General and Cited	5
TABL Table	ES 1: Cowardin Classification, Acreage and Linear Footage of Aquatic Reso	
Table 2	2: Characteristics of Aquatic Resources within the Survey Area	3

APPENDICES

Appendix A: Supporting Figures

Appendix B: Site Photo Documentation

Appendix C: Plant List

Appendix D: Wetland Determination Data Sheets

Appendix E: USDA NRSC Soils Reports

ACRONYMS AND ABBREVIATIONS

CR County Road

HUC Hydrologic Unit Code NAD North American Datum

NRCS Natural Resources Conservation Service

NWI National Wetland Inventory NWPL National Wetland Plant List OHWM Ordinary high-water mark

PEM Palustrine emergent

ROW Right-of-way

R4SB Riverine Intermittent Streambed RPW Relatively Permanent Water SME SME Environmental, Inc. TNW Traditional Navigable Water

US 550 U.S. Highway 550

USACE U.S. Army Corps of Engineers USDA U.S. Department of Agriculture

USGS U.S. Geological Survey

USFWS U.S. Fish and Wildlife Service

1.0 INTRODUCTION

Project Name: Cascade Village Tracts A1-B1

USACE File #: N/A, initial submittal

SME #: 240008

Applicant:

CitiSculpt

1355 Greenwood Cliff #150, Charlotte, NC 28204

Phone: Office (704) 361-3758

Contact: Mr. Charles Lindsey McAlpine; Email: Lmcalpine@citisculpt.com Transportation

Agent/Consultant:

SME Environmental, Inc. (SME)

679 East 2nd Avenue, Unit E2, Durango, CO 81301

Phone: (970) 259-9595; Fax: (970) 259-0050

Contact: Mr. Sean Moore, Principal; Email: smoore@sme-env.com

Survey Area Description: The area surveyed by SME in support of the project is west of US 550. The eastern portion of the survey area wetland areas. The western portion of the survey area is undeveloped forested land on an east facing slope. The area surrounding the survey area is low density residential buildings and Purgatory Resort.

Purpose: The purpose of this report is to identify and describe aquatic resources within the survey area for due diligence of Clean Water Act Section 404.

2.0 PROJECT LOCATION

Municipality: Durango; County: San Juan County; State: Colorado; Street Address: South of and adjacent to 56 Meadowview Drive

Section, Township, Range (New Mexico Principal Meridian): Township 39 North, Range 9 West, parts of Section 13.

Lat/Long: Project area centroid (NAD 83) Lat: 37.647922° Long: -107.811529°

USGS Quad Name: Engineer Mountain, Colorado

Directions: The survey area is approximately 1.15 miles north of Purgatory Ski Resort and west of US 550. From the city of Durango head north on US 550 for approximately 25 miles. The survey can be accessed from a pullout on the west side of the highway. A Road Vicinity map is included as <u>Figure 1</u> and a topographic map is provided as <u>Figure 2</u> (<u>Appendix A</u>).

3.0 DELINEATION METHODS

Aquatic resources in the survey area were identified on June 19, 2025 using the methodology defined in the Routine Determination procedure set forth in the 1987 U.S. Army Corps of Engineers Wetlands Delineation Manual (USACE 1987), the Regional Supplement to the USACE Wetland Delineation Manual: Western Mountains, Valleys, and Coast (Version 2.0), and National Ordinary High Water Mark Field Delineation Manual for Rivers and Streams: Final Version (USACE 2025). Wetland boundaries were defined based on presence of hydrophytic vegetation, hydric soils, and hydrologic indicators that under normal conditions would indicate wetland conditions. In the absence of wetland conditions, the extent of aquatic resources was determined based on the lateral extent of the OHWM.

Prior to conducting the field survey, SME conducted a desktop survey of available publications covering the survey area including U.S. Geological Survey (USGS) 7.5' topographic quadrangles, U.S. Fish and Wildlife (USFWS) National Wetlands Inventory (NWI) data, U.S. Department of Agriculture (USDA) Natural Resources Conservation Service (NRCS) soils data, and *ESRI World Layer maps* for aerial imagery. The boundaries of aquatic resources were survey-located using Trimble R1 GNSS GPS unit (sub-meter accuracy) and are depicted in Figure 4.

4.0 EXISTING CONDITIONS

4.1 Landscape Setting

Size of Survey Area: Approximately 79.5 acres.

Watershed Name and Size (HUC 8): Animas Watershed, HUC 14080104, 1,371 square miles.

Elevation Range of Site: Approximately 8,850-9,710 feet above mean sea level (msl) (Figure 2).

Geographic Setting: The survey area is located in the San Juan Mountains just southwest of Coal Bank Pass. Boyce Lake is located approximately 0.3 mile east of the survey area. The survey area is surrounded primarily by undeveloped open and forested land, with scattered homes and US 550 to the east.

Geology: The underlying geology is comprised of Rico, Hermosa, and Molas Formations (U.S. Geological Survey). Rico formation consists of nonmarine red beds of shale, siltstone, arkosic sandstone, and grit. Hermosa formation west of the Los Pinos River is largely dark-gray marine shale, limestone, and sandstone. Molas formation is mostly nonmarine shale, siltstone, sandstone, conglomerate, and basal red breccia, maximum thickness about 125 feet.

Land Use: The survey area is located west of and adjacent to US 550 which receives high vehicular traffic. Purgatory Ski Resort is located south and east of the survey area which contains residential and commercial properties and is a high use recreation area during the summer and winter. The surrounding area is San Juan National Forest.

Precipitation: According to the Antecedent Precipitation Tool (USACE), the site visit was conducted during the dry season while the area was experiencing severe drought.

4.2 Aquatic Resources

The survey area contains two palustrine emergent (PEM) wetland areas. PEM Wetland Area B is north of the prosed driveway and PEM Wetland Area C is south of the proposed driveway (Figure 4). Although shrub stratum species such as shrubby cinquefoil (*Dasiphora fruticosa*) and mountain willow (*Salix monticola*) are present, the wetland areas are dominated by the herb stratum and are therefore classified as PEM. Additionally, PEM Wetland Area B has approximately 0.24 acre of open water (Area A). PEM Wetland Area B continues east of Tract B-1 and drains east under US 550 and into Cascade Creek. Cascade Creek is an (a)(3) Tributary of the Animas River (a)(1). Additionally, water is conveyed under the driveway from PEM Wetland Area B into PEM Wetland Area C towards Greyrock Village North. The boundaries of aquatic resources delineated within the survey area are depicted in Figure 4. Appendix B contains photographs of the aquatic resources within the survey area.

<u>Table 1</u>. Cowardin Classification, Acreage, and Linear Footage of Aquatic Resources within the Survey Area.

Waters of the U.S.	Square Feet	Acres	Linear Feet
Open Water (Area A)	10,440	0.240	N/A
Palustrine Emergent (PEM) Wetland (Area B)	307,189	7.052	N/A
Palustrine Emergent (PEM) Wetland (Area C)	3,051	0.070	N/A
TOTAL	320,679	7.36	N/A

Table 2. Characteristics of Aquatic Resources within the Survey Area.

Name	Flow Frequency	Flows to	Rationale
Open Water (Area A)	Seasonally Saturated	Cascade Creek	(a)(4) Adjacent Wetlands
PEM Wetland (Area B)	Seasonally Saturated	Cascade Creek	(a)(4) Adjacent Wetlands
PEM Wetland (Area C)	Seasonally Saturated	Cascade Creek	(a)(4) Adjacent Wetlands

4.3 Vegetation

The wetlands in the survey area are dominated by mountain willow (Salix monticola), reed canary grass (Agrostis stolonfera), carex species (Carexs spp.), and white marsh marigold (Caltha leptosepala). The uplands of the survey area are dominated by smooth brome (Bromus inermis), orchard grass (Dactylis glomerata), and common snowberry (Symphoricarpos albus). Appendix C provides a list of plant species observed during the field investigation. Wetland Determination Data forms for the Western Mountains, Valleys, and Coast Region are included with this report as Appendix D and include detailed information about the vegetation observed at each data point location.

4.4 Soils

Soil data for the survey area was obtained from the USDA NRCS. A soil map is included in <u>Figure 3</u> and a complete description of the soil map series is included as <u>Appendix E</u>. The survey area is

located within the mapped Cryaquolls-Typic Cryaquents complex 1 to 5 percent slopes, Needleton stony loam, 15 to 30 percent slopes, Clayburn-Hourglass complex, 5 to 25 percent slopes and Needleton-Snowdon-Rock outcrop complex, 30 to 80 percent slopes soil units. The Cryaquolls-Typic Cryaquents complex soil map unit is listed on the State Soil Data Access (SDA) Hydric Soils List (NRCS 2018). Data collected from soil transects during the field investigation revealed primarily silty clay loam soils. The primary hydric soil indicator observed at the soil boring locations within the wetland areas was redoximorphic features (i.e., mottles) located within a dark soil matrix. Data from specific soil bores is presented on the data sheets in Appendix D.

4.5 Hydrology

The hydrology in survey area is sourced by two intermittent waterways that flow down the east facing slope into the valley where Tract B-1 is located. The topography to the west supports higher elevation slopes that carry stormwater and snowpack along the two unnamed intermittent channels from west to east, through the survey area and eventually flow to the Cascade Creek corridor. The unnamed waterways that support delineated wetlands are identified on the USGS Engineer Mountain, Colo. 7.5-minute Topographic Quadrangle 1:24,000 map as intermittent aquatic resources. The hydrology of these wetland areas is anticipated to primarily be the referenced unnamed intermittent channels.

4.7 Limitations


Field indicators can change with variations in hydrology and other factors. This report assesses the potential for aquatic resources at the site at the time of our review and does not address conditions at a given time in the future. Accordingly, on behalf of our client, SME reserves the right to revisit the jurisdictional status of boundaries of aquatic resources as presented herein, should any of this information warrant modifications. We make no other warranties, either expressed or implied, and our report is not a recommendation to buy, sell or develop the property. This report does not constitute a Jurisdictional Determination of Waters of the United States since such determinations must be verified by the USACE or the NRCS (as applicable) and are subject to review by the U.S. Environmental Protection Agency (USEPA).

5.0 REFERENCES - General and Cited

- Cowardin, L.M., V. Carter, F.C. Golet, and E.T. LaRoe. 1979. Classifications of Wetlands and Deepwater Habitats of the United States. (FWS/OBS-79/31) U.S. Fish and Wildlife Service. Washington D.C.
- ESRI World Imagery Map. USA FSA NAIP. 2015 2015-09-11. Available at: http://www.arcgis.com/.
- Haynes, D.D., Vogel, J.D., and Wyant, D.G., 1972, Geology, structure, and uranium deposits of the Cortez quadrangle, Colorado and Utah: U.S. Geological Survey, Miscellaneous Geologic Investigations Map I-629, scale 1:250,000.
- Kartesz, J.T. 2014. Floristic Synthesis of North America, Version 1.0 Biota of North America Program (BONAP). (in press). http://www/bonap.org/.
- Lichvar, R.W., D.L. Banks, W.N. Kirchner, and N.C. Melvin. 2016. *The National Wetland Plant List*: 2016 wetland ratings. Phytoneuron 2016-30: 1-17. Published 28 April 2016. ISSN 2153 733X. http://www.phytoneuron.net/.
- U.S. Army Corps of Engineers (USACE). 2016. National Wetland Plant List, version 3.3. National Wetland Plant List, version 3.3. http://wetland_plants.usace.army.mil/. U.S. Army Corps of Engineers. Engineer Research and Development Center. Cold Regions Research and Engineering Laboratory, Hanover, NH
- USACE. 2023. Antecedent Precipitation Tool (ATP) Version 2.0: Technical and User Guide. U.S. Army Engineer Research and Development Center. Cold Regions Research and Engineering Laboratory, Hanover, NH.
- USACE. 2014. A Guide to Ordinary High Water Mark (OHWM) Delineation for Non-Perennial Streams in the Western Mountains, Valleys, and Coast Region of the United States. Engineer Research and Development Center. Cold Regions Research and Engineering Laboratory, Hanover, NH.
- USACE. December 2008. Clean Water Act Jurisdiction Following the U.S. Supreme Court's Decision in the Rapanos v. United States & Carabell v. United States. Available at: http://www.usace.army.mil/Portals/2/docs/civilworks/regulatory/cwa_guide/cwa_juris_2_dec08.pdf.
- USACE. 2008. A Field Guide to the Identification of the Ordinary High Water Mark (OHWM) in the Arid West Region of the Western United States: A Delineation Manual. U.S. Army Engineer Research and Development Center Cold Regions Research and Engineering Laboratory. Hanover, NH.
- USACE. December 2005. Regulatory Guidance Letter No. 05-05. Guidance on Ordinary High Water Mark Identification.

- USACE. 1987. Corps of Engineers Wetland Delineation Manual. Technical Report Y-87-1, Environmental Laboratory, U.S. Army Corps of Engineer Waterways Experiment Station. Vicksburg, MS.
- USACE and U.S. Environmental Protection Agency (USEPA). 2007. Jurisdictional Determination Guidebook. Available at: http://www.usace.army.mil/Portals/2/docs/civilworks/regulatory/cwa_guide/jd_guidebook_051207final.pdf.
- U. S. Department of Agriculture (USDA). 2018. United States Drought Monitor. Available at: http://droughtmonitor.unl.edu/.
- USDA NRCS. 2018. Soil Data Access (SDA) Hydric Soils List. Available at: https://www.nrcs.usda.gov/Internet/FSE_DOCUMENTS/nrcseprd1316620.html.
- USDA Natural Resources Conservation Service (NRCS). 2016. The PLANTS Database (http://plants.usda.gov). National Plant Data Team, Greensboro, NC 27401-4901 USA.
- USDA NRCS. 2018. Web Soil Survey. Available at: http://websoilsurvey.nrcs.usda.gov/.
- U.S. Geological Survey (USGS). 1974. Geologic map of the Durango quandrangle, southwestern Colorado, Available at: https://ngmdb.usgs.gov/Prodesc/proddesc 9518.htm.
- Weber, William A., Wittmann, Ronald C., 2012. Colorado Flora: Western Slope, Fourth Edition. University Press of Colorado, Boulder, CO.

APPENDIX A Figures 1-4





679 East 2nd Ave. Unit E2, Durango, Colorado 81301 www.sme-env.com (970) 259-9595


Drawn by:	Rvwd. by:	Project No.:
SB	SM	240008
Date:	Rvsd. Date:	Scale:
6/30/2025	NA	1:21,000
N	0 825	1,650
7	Feet	6

ROAD VICINITY MAP

AQUATIC RESOURCES
DELINEATION
CASCADE VILLAGE TRACTS A1-B1
SAN JUAN COUNTY, CO

FIGURE
1

SURVEY LOCATION: Township 39 North, Range 9 West, NENW, SENW, NESW, and NWSE of Section 13; New Mexico Principal Meridian San Juan County, Colorado. SURVEY AREA CENTROID (NAD83): Latitude: 37.64793° Longitude: -107.81153°



ke City



679	East	2nd	Ave.	Unit E2,	Durang	0, 0	Colorado	81301
		www	v.sm	е-епу.со	m (970)	259	-9595	

Drawn by:	Rvwd. by:	Project No.:
SB	SM	240008
Date:	Rvsd. Date:	Scale:
6/30/2025	NA	1:24,000
N	0 1,0	00 2,000

Feet


TOPOGRAPHIC LOCATION MAP

USGS Topographic Quadrangle

Survey Area

AQUATIC RESOURCES DELINEATION CASCADE VILLAGE TRACTS A1-B1 SAN JUAN COUNTY, CO

FIGURE





679 East 2nd Ave.	Unit E2,	Durango,	Colorado	81301
www.sm	e-env.coi	m (970) 25	9-9595	

Rvwd. by:	Project No.:
SM	240008
Rvsd. Date:	Scale:
NA	1:7,500
0 310	620
	SM Rvsd. Date: NA

Feet

SOILS MAP

AQUATIC RESOURCES DELINEATION CASCADE VILLAGE TRACTS A1-B1 SAN JUAN COUNTY, CO **FIGURE**

3

GENERAL

Sures tradeonstare regardle SM. Insection CAD data provided Cfic Transpers.


4. The boundaries of WCU S were sures than doing a Frendbe Ri GNSS Research treatment among a consistency of Sures which links one yield SAC critical as WCU S are labeled. Note that WCU S community of Sures which links one yield SAC critical as WCU S are labeled. Note that WCU S community of Sac and the WCU S are labeled. Note that WCU S community of Sac and Sac are sures to some Determination procedure set both in the US Alma Cfice of a fragment within the sures are from dark WCU S boundaries, departed hereon, are subject to modification and an advanced vertication for SAC E1957, the Regional Supplement to the Corps of Engineers Wethin Definerion Manual Western completed life USAC.

Lorentz Section Supplement to the Corps of Engineers Wethin Definerion for None Table by according to the Corps of Engineers Wethin Definerion for None Table by according to the Corps of Engineers Wethin Definerion and Ard West Region II SACE Section and the Federal regular resources define the other than the Corps of Engineers Wethin Definerion Manual Ard West Region II SACE Section and the Federal regular resources define the other by the Engineers Wethin Definerion Manual Ard West Region II SACE Section and the Federal regular resources define the other by the Engineers were recovered and centroal locations. ClO and the Federal Region II SACE Section II SACE 1709.

If the Field Guide to the Identification of the Ordinary II is Water Matt GUI WALL in the Arial west frield Water United States USAGE 2008.

and Issandance were defined based on presence of histophina vegetation, inclusives, and indusbages that under normal conditions which weight and the mornal conditions did not never to surface water, the presidence of benefit weight and the processing of the OHEM.

AQUATIC RESOURCES DELINEATION TABLE Classification Acres Square Ft. Centroid Y Centroid X Open Water 0.240 10,440 37,64888 -107.81005 -107.80957 PEM Werland 37,64817 В 7.052 307,189 С PEM Wetland 0.070 3,051 37,64507 -107,80808 7.36 320,679





Drawn By:	Rowd, By:	Proj. No.:
SB	SM	240008
Date:	Rvsd. Date:	Scale:
7/2/2025	NA	1.3,800

Feet

AQUATIC RESOURCES DELINEATION MAP

AQUATIC RESOURCES DELINEATION CASCADE VILLAGE TRACTS A 1-B 1 SAN JUAN COUNTY, CO

FIGURE

APPENDIX B		
Photo Documentation		



Photo 1: View of driveway looking NE



Photo 3: Southern wetland south of PA



Photo 5: Looking North from Proposed driveway



Photo 2: Southern wetland area



Photo 4: Southern wetland connection



Photo 6: Standing water in north wetland





Photo 7: Looking east across the northern wetland



Photo 9: North end of survey area looking south



Photo 11: Surface water connection under US 550



Photo 8: Northern most portion of survey area



Photo 10: Upland area proposed driveway



Photo 12: Channel east of US 550



2025 Photographs Cascade Village Tracts A1-B1
San Juan County, Colorado

Photo Page 2

July 2025

APPENDIX C
Plant List

Appendix D: List of Dominant Plant Species Observed within the Survey Area.

Scientific Name*	Common Name	Wetland Indicator
TREES		
Picea pungens	Blue spruce	FAC
Populus tremuloides	Quaking aspen	FACU
SHRUBS		
Cornus sericea	Redosier dogwood	NL
Dasiphora fruticosa	Shrubby cinquefoil	FAC
Ribes montigenum	Gooseberry currant	NL
Salix artica	Arctic willow	NL
Salix monticola	Mountain willow	OBL
Symphoricarpos albus	Common snowberry	FACU
HERBS		
Achillea millefolium	Common Yarrow	FACU
Actaea rubra	Red baneberry	NL
Carex spp.	Carex species	N/A
Caltha leptosepala	White marsh marigold	OBL
Cirsium arvense	Canada Thistle	FAC
Equisetum arvense	Field horsetail	FAC
Fragaria vesca	Wild strawberry	NL
Iris missouriensis	Rocky mountain iris	FACW
Maianthemum stellatum	Starry false solomon's-seal	FAC
Medicago sativa	Alfalfa	UPL
Taraxacum officinale	Common dandelion	FACU
Trifolium pratense	Red clover	FACU
Vicia americana	American Vetch	FAC
Viola nephrophylla	Northern Bog Violet	FACW
GRAMINOIDS		
Bromus inermis	Smooth brome	FACU
Dactylis glomerata	Orchardgrass	FACU
Juncus balticus	Baltic Rush	FACW
Phalaris arundinacea	Reed canarygrass	FACW

[•] OBL: Almost always is a hydrophyte, rarely in uplands
• FAC: Commonly occurs as either a hydrophyte or non-hydrophyte
• NL (Not Listed): Generally indicates upland species
• N/A: Unable to identify to species due to time of year
• Scientify the District (NAVID)
• State of the United States, Canada, and Greenland (Kartesz 2009) and

National Wetland Plant List (NWPL).

** 2016 NWPL is regionalized along the 10 wetland delineation supplement regions. Wetland indicator status based on Western Mountains, Valleys, and Coast Region.

APPENDIX D	
Wetland Determination Data Forms	

U.S. Army Corps of Engineers

WETLAND DETERMINATION DATA SHEET – Western Mountains, Valleys, and Coast Region See ERDC/EL TR-10-3; the proponent agency is CECW-CO-R

OMB Control #: 0710-0024, Exp: 11/30/2024 Requirement Control Symbol EXEMPT: (Authority: AR 335-15, paragraph 5-2a)

Project/Site: Cascade Village Tracts A1-B1		City/Cou	nty: San Jua	an	Sampling Date:	6.18.25
Applicant/Owner: Charles McAlpine				State: CO	Sampling Point:	DP2W
Investigator(s): Elijah Vargas and Sean Moore		Section, T	ownship, Ra	nge: S 13; T 39 N; R 9	W	
Landform (hillside, terrace, etc.): Valley		Local relief (co	oncave, conv	/ex, none): concave	Slop	oe (%):5_
Subregion (LRR): LRR E Lat:			Long:	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	Datum:	
Soil Map Unit Name: Cryaquolls-Typic Cryaquents co	mplex, 1 to 5	percent slope	s	NWI classif	ication: PEM1D	
Are climatic / hydrologic conditions on the site typical	for this time o	f year?	Yes	No_x (If no, exp	lain in Remarks.)	
Are Vegetation, Soil, or Hydrology	significantly of	disturbed? A	re "Normal (Dircumstances" present?	Yes x_ No	o
Are Vegetation , Soil , or Hydrology				plain any answers in Ren		
SUMMARY OF FINDINGS – Attach site m	ap showin	g samplin	g point lo	cations, transects,	important feat	tures, etc.
Hydrophytic Vegetation Present? Yes X	No	Is the	Sampled A	rea		
Hydric Soil Present? Yes X	No	withi	n a Wetland	? Yes_X_	No	
Wetland Hydrology Present? Yes X	No					
Remarks:						
Area is in a severe drought						
VEGETATION – Use scientific names of	nlante					
VEGETATION - Ose scientific flames of	Absolute	Dominant	Indicator			
Tree Stratum (Plot size:)	% Cover	Species?	Status	Dominance Test worl	ksheet:	
1,	.07			Number of Dominant S	•	72 VAR
2.	. —	-		Are OBL, FACW, or F/	-	3(A)
3	-01 	7		Total Number of Domii Across All Strata:	nant Species	3 (B)
	800	=Total Cover		Percent of Dominant S	Species That	(0)
Sapling/Shrub Stratum (Plot size: 1 m	_)			Are OBL, FACW, or F		0.0%_(A/B)
1. Salix lutea	10	Yes	OBL_			
2. Dasiphora fruticosa		Yes	FAC	Prevalence Index wo		
3,				Total % Cover of: OBL species 10		7 by: 10
5.				FACW species 83		166
· ,	30	Total Cover		FAC species 20		60
Herb Stratum (Plot size: 1 m)				FACU species 2	x 4 =	8
Phalaris arundinacea	80	Yes	FACW	UPL species0		0
2. Carex sp.	3	No	FACW	Column Totals: 11		244 (B)
3. Taraxacum officinale 4.		No	_FACU_	Prevalence Index =	= B/A =	<u>'</u>
-				Hydrophytic Vegetati	on Indicators:	
6.				• • •	Hydrophytic Veget	ation
7.				X 2 - Dominance Te		
8.				X 3 - Prevalence Ind		
9.				4 - Morphological /	Adaptations (Provid s or on a separate	
10 11				5 - Wetland Non-V		/
	85	=Total Cover		l 	ophytic Vegetation ¹	(Explain)
Woody Vine Stratum (Plot size:	_)			Indicators of hydric so		
1				be present, unless dist	urbed or problema	tic.
2,	. ——			Hydrophytic		
% Bare Ground in Herb Stratum 0		=Total Cover		Vegetation Present? Yes	X No	
				resent: res		
Remarks:						

SOIL Sampling Point: DP2W Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.) Depth Matrix Redox Features (inches) Color (moist) % Color (moist) Type Loc2 % Texture Remarks 0-6 10YR 2/2 100 Loamy/Clayey 10YR 2/2 90 6-12 7.5YR 6/8 10 С PL Loamy/Clayey Prominent redox concentrations 12-20 10YR 2/1 50 5YR 6/8 50 С PL/M Loamy/Clayey Prominent redox concentrations ¹Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered or Coated Sand Grains. ²Location: PL=Pore Lining, M=Matrix. Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.) Indicators for Problematic Hydric Soils3: Histosol (A1) Sandy Gleyed Matrix (S4) 2 cm Muck (A10) (LRR A, E) Histic Epipedon (A2) Sandy Redox (S5) Iron-Manganese Masses (F12) (LRR D) Black Histic (A3) Stripped Matrix (S6) Red Parent Material (F21) Hydrogen Sulfide (A4) Loamy Mucky Mineral (F1) (except MLRA 1) Very Shallow Dark Surface (F22) 1 cm Muck (A9) (LRR D, G) Loamy Gleyed Matrix (F2) Other (Explain in Remarks) Depleted Below Dark Surface (A11) Depleted Matrix (F3) Thick Dark Surface (A12) X Redox Dark Surface (F6) 3Indicators of hydrophytic vegetation and Sandy Mucky Mineral (S1) Depleted Dark Surface (F7) wetland hydrology must be present, 2.5 cm Mucky Peat or Peat (S2) (LRR G) Redox Depressions (F8) unless disturbed or problematic. Restrictive Layer (if observed): Type: Depth (inches): **Hydric Soil Present?** No Remarks: **HYDROLOGY** Wetland Hydrology Indicators: Primary Indicators (minimum of one is required; check all that apply) Secondary Indicators (2 or more required) Surface Water (A1) Water-Stained Leaves (B9) (except Water-Stained Leaves (B9) (MLRA 1, 2 x High Water Table (A2) MLRA 1, 2, 4A, and 4B) 4A, and 4B) x Saturation (A3) Salt Crust (B11) x Drainage Patterns (B10) Water Marks (B1) Aquatic Invertebrates (B13) x Dry-Season Water Table (C2) Sediment Deposits (B2) Hydrogen Sulfide Odor (C1) Saturation Visible on Aerial Imagery (C9) Drift Deposits (B3) x Oxidized Rhizospheres on Living Roots (C3) x Geomorphic Position (D2) Algal Mat or Crust (B4) Presence of Reduced Iron (C4) Shallow Aquitard (D3) Iron Deposits (B5) Recent Iron Reduction in Tilled Soils (C6) X FAC-Neutral Test (D5) Surface Soil Cracks (B6) Stunted or Stressed Plants (D1) (LRR A) Raised Ant Mounds (D6) (LRR A) Inundation Visible on Aerial Imagery (B7) Other (Explain in Remarks) Frost-Heave Hummocks (D7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes Depth (inches): Water Table Present? Yes x Depth (inches): Saturation Present? Yes x 0 Depth (inches): Wetland Hydrology Present? Yes X No (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

U.S. Army Corps of Engineers

WETLAND DETERMINATION DATA SHEET – Western Mountains, Valleys, and Coast Region See ERDC/EL TR-10-3; the proponent agency is CECW-CO-R

OMB Control #: 0710-0024, Exp: 11/30/2024 Requirement Control Symbol EXEMPT: (Authority: AR 335-15, paragraph 5-2a)

Project/Site: Cascade Village Tracts A1-B1		City/Cour	nty: San Jua	an	Sampling Date:	6.18.25
Applicant/Owner: Charles McAlpine				State: CO	Sampling Point:	DP2U
Investigator(s): Elijah Vargas and Sean Moore		Section, T	ownship, Ra	nge: S 13; T 39 N; R 9	• W	
Landform (hillside, terrace, etc.): Valley		Local relief (co	ncave, conv	ex, none): concave	Slc	ope (%):5_
Subregion (LRR): LRR E Lat:			Long:		Datum:	
Soil Map Unit Name: Cryaquolls-Typic Cryaquents	complex, 1 to 5	percent slopes	3	NWI classi	ification: PEM1D	
Are climatic / hydrologic conditions on the site typic	al for this time o	f year?	Yes	No x (If no, ex	plain in Remarks.)	
Are Vegetation, Soil, or Hydrology	significantly	disturbed? A	re "Normal (Dircumstances" present?	? Yes <u>x</u> N	4o
Are Vegetation, Soil, or Hydrology				plain any answers in Re		
SUMMARY OF FINDINGS – Attach site			g point lo	cations, transects	, important fea	itures, etc.
Hydrophytic Vegetation Present? Yes	No X	Is the	Sampled A	rea		
Hydric Soil Present? Yes	No X		n a Wetland		No X	
Wetland Hydrology Present? Yes	No X					
Remarks:		1,				
Area is in a severe drought						
VEGETATION – Use scientific names of	of plants					
VEGETATION - Use scientific flatties of	Absolute	Dominant	Indicator			
Tree Stratum (Plot size:)	% Cover	Species?	Status	Dominance Test wo	rksheet:	
1.				Number of Dominant	•	
2	→ /,; ,			Are OBL, FACW, or F) .	0 (A)
3				Total Number of Dom Across All Strata:	inant Species	1 (B)
7	→ >:(=Total Cover		Percent of Dominant	Species That	
Sapling/Shrub Stratum (Plot size:)			Are OBL, FACW, or f	•	0.0%(A/B
1,						
2,				Prevalence Index we		. ,
3,1				Total % Cover o OBL species	f: Multipl 0 x 1 =	0
5.				· -	0 x2=	0
5		=Total Cover			0 x 3 =	0
Herb Stratum (Plot size: 1 m)				FACU species	40 x 4 =	160
Dactylis glomerata	30	Yes	FACU	UPL species	0 x 5 =	0
2. Trifolium pratense	5	No	FACU		10 (A)	160 (B)
3. Achillea millefolium		No_	FACU	Prevalence Index	= B/A =4.0)0
5.				Hydrophytic Vegeta	tion Indicators:	
6,					r Hydrophytic Vege	etation
7.				2 - Dominance To		
8.				3 - Prevalence In	dex is ≤3.0 ¹	
9.	_				Adaptations ¹ (Prov	
10					ks or on a separate	sheet)
11,	_			5 - Wetland Non-		1
Was do Villago Charles (District		=Total Cover			rophytic Vegetation	
Woody Vine Stratum (Plot size:				¹ Indicators of hydric s be present, unless dis	_	
1				Hydrophytic		
3		=Total Cover		Vegetation		
% Bare Ground in Herb Stratum 60				Present? Yes	No_X	<u>: </u>
Remarks:						

(inches) Color (moist)	SUIL		Sampling Point: DP2U
Color (moist) % Color (moist) % Type Loc ² Texture Remarks	Profile Description: (Describe to the	lepth needed to document the indicator or	confirm the absence of indicators.)
10-10	Depth Matrix	Redox Features	
10yr 3/2 100 10yr 3/2 10yr 3/2 100 10yr 3/2 10yr	(inches) Color (moist) %	Color (moist) % Type ¹ Loc ²	Texture Remarks
"Type: C-Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered or Coated Sand Grains. "Applications: (Applicable to all LRRs, unless otherwise noted.) Indicators (Applicable to all LRRs, unless otherwise noted.) Indicators (Applicable to all LRRs, unless otherwise noted.) Indicators for Problematic Hydric Solis? Histics (Ap) Sandy Redox (SS) Indicators (Applicable to Applicable to all LRRs, unless otherwise noted.) Indicators for Problematic Hydric Solis? Histic Epipedon (A2) Sandy Redox (SS) Red Parent Material (P21) Hydrogen Sulfide (A4) Loamy Mucky Mineral (F1) (except MLRA 1) Persy Shallow Dark Surface (F2) Loamy Michigan (P22) Other (Explain in Remarks) Depleted Matrix (F3) Person (F3) Indicators of hydrophytic vegetation and wetland hydrology must be present. 2.5 cm Mucky Peat or Peat (S2) (LRR G) Redox Dark Surface (F7) unless disturbed or problematic. Restrictive Layer (if observed): Type: Depth (inches): Redox (A12) Person (A3) Salt Crust (B11) Depth (Inches): Phydric Soil Present? Yes No Remarks: VYDROLOGY Water Table (A2)	0-10 10YR 3/2 100		
"Type: C-Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered or Coated Sand Grains. "Applications: (Applicable to all LRRs, unless otherwise noted.) Indicators (Applicable to all LRRs, unless otherwise noted.) Indicators (Applicable to all LRRs, unless otherwise noted.) Indicators for Problematic Hydric Solis? Histics (Ap) Sandy Redox (SS) Indicators (Applicable to Applicable to all LRRs, unless otherwise noted.) Indicators for Problematic Hydric Solis? Histic Epipedon (A2) Sandy Redox (SS) Red Parent Material (P21) Hydrogen Sulfide (A4) Loamy Mucky Mineral (F1) (except MLRA 1) Persy Shallow Dark Surface (F2) Loamy Michigan (P22) Other (Explain in Remarks) Depleted Matrix (F3) Person (F3) Indicators of hydrophytic vegetation and wetland hydrology must be present. 2.5 cm Mucky Peat or Peat (S2) (LRR G) Redox Dark Surface (F7) unless disturbed or problematic. Restrictive Layer (if observed): Type: Depth (inches): Redox (A12) Person (A3) Salt Crust (B11) Depth (Inches): Phydric Soil Present? Yes No Remarks: VYDROLOGY Water Table (A2)	10-20 10YR 3/2 100		· · · · · · · · · · · · · · · · · · ·
Hydric Soil Indicators (Applicable to all LRRs, unless otherwise noted.) Histoscol (A1) Sandy Gleyed Matrix (S4) Histoscol (A1) Sandy Redox (S5) Black Histic (A3) Sandy Redox (S5) Black Histic (A3) Schipped Matrix (S6) Black Histic (A3) Loamy Mucky Mineral (F1) (except MLRA 1) Loamy Mucky Mineral (F1) (except MLRA 1) Loamy Mucky Mineral (F2) Thy Charles Surface (A11) Depleted Below Dark Surface (A12) Sandy Mucky Mineral (F2) Depleted Below Dark Surface (A11) Depleted Matrix (F3) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Surface Mucky Peat or Peat (S2) (LRR G) Redox Dark Surface (F7) Restrictive Layer (if observed): Type: Depth (inches): Wetland Hydrology Indicators: Primary Indicators (ininimum of one is required; check all that apply) Surface Water (A1) Water Marks (B1) Water Table (A2) High Water Table (A2) MLRA 1, 2, 4A, and 4B) Saturation (A3) Salt Crust (B11) Water Marks (B1) Water Marks (B1) Water Marks (B1) Aquatic Invertebrates (B13) Drainage Paterns (B10) Drainage Paterns (B10) Drainage Paterns (B10) Drainage Paterns (B10) Surface Soli Cracks (B6) Inno Deposits (B3) Recent Iron Reduction in Tilled Soils (C6) Surface Soli Cracks (B6) Innuation Visible on Aerial Imagery (C9 Sources (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Wetland Hydrology Pres	10 11 10 11 100		
Hydric Soil Indicators (Applicable to all LRRs, unless otherwise noted.) Histoscol (A1) Sandy Gleyed Matrix (S4) Histoscol (A1) Sandy Redox (S5) Black Histic (A3) Sandy Redox (S5) Black Histic (A3) Schipped Matrix (S6) Black Histic (A3) Loamy Mucky Mineral (F1) (except MLRA 1) Loamy Mucky Mineral (F1) (except MLRA 1) Loamy Mucky Mineral (F2) Thy Charles Surface (A11) Depleted Below Dark Surface (A12) Sandy Mucky Mineral (F2) Depleted Below Dark Surface (A11) Depleted Matrix (F3) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Surface Mucky Peat or Peat (S2) (LRR G) Redox Dark Surface (F7) Restrictive Layer (if observed): Type: Depth (inches): Wetland Hydrology Indicators: Primary Indicators (ininimum of one is required; check all that apply) Surface Water (A1) Water Marks (B1) Water Table (A2) High Water Table (A2) MLRA 1, 2, 4A, and 4B) Saturation (A3) Salt Crust (B11) Water Marks (B1) Water Marks (B1) Water Marks (B1) Aquatic Invertebrates (B13) Drainage Paterns (B10) Drainage Paterns (B10) Drainage Paterns (B10) Drainage Paterns (B10) Surface Soli Cracks (B6) Inno Deposits (B3) Recent Iron Reduction in Tilled Soils (C6) Surface Soli Cracks (B6) Innuation Visible on Aerial Imagery (C9 Sources (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Wetland Hydrology Pres			· · · · · · · · · · · · · · · · · · ·
Hydric Soil Indicators (Applicable to all LRRs, unless otherwise noted.) Histoscol (A1) Sandy Gleyed Matrix (S4) Histoscol (A1) Sandy Redox (S5) Black Histic (A3) Sandy Redox (S5) Black Histic (A3) Schipped Matrix (S6) Black Histic (A3) Loamy Mucky Mineral (F1) (except MLRA 1) Loamy Mucky Mineral (F1) (except MLRA 1) Loamy Mucky Mineral (F2) Thy Charles Surface (A11) Depleted Below Dark Surface (A12) Sandy Mucky Mineral (F2) Depleted Below Dark Surface (A11) Depleted Matrix (F3) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Surface Mucky Peat or Peat (S2) (LRR G) Redox Dark Surface (F7) Restrictive Layer (if observed): Type: Depth (inches): Wetland Hydrology Indicators: Primary Indicators (ininimum of one is required; check all that apply) Surface Water (A1) Water Marks (B1) Water Table (A2) High Water Table (A2) MLRA 1, 2, 4A, and 4B) Saturation (A3) Salt Crust (B11) Water Marks (B1) Water Marks (B1) Water Marks (B1) Aquatic Invertebrates (B13) Drainage Paterns (B10) Drainage Paterns (B10) Drainage Paterns (B10) Drainage Paterns (B10) Surface Soli Cracks (B6) Inno Deposits (B3) Recent Iron Reduction in Tilled Soils (C6) Surface Soli Cracks (B6) Innuation Visible on Aerial Imagery (C9 Sources (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Wetland Hydrology Pres			
Hydric Soil Indicators (Applicable to all LRRs, unless otherwise noted.) Histoscol (A1) Sandy Gleyed Matrix (S4) Histoscol (A1) Sandy Redox (S5) Black Histic (A3) Sandy Redox (S5) Black Histic (A3) Schipped Matrix (S6) Black Histic (A3) Loamy Mucky Mineral (F1) (except MLRA 1) Loamy Mucky Mineral (F1) (except MLRA 1) Loamy Mucky Mineral (F2) Thy Charles Surface (A11) Depleted Below Dark Surface (A12) Sandy Mucky Mineral (F2) Depleted Below Dark Surface (A11) Depleted Matrix (F3) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Surface Mucky Peat or Peat (S2) (LRR G) Redox Dark Surface (F7) Restrictive Layer (if observed): Type: Depth (inches): Wetland Hydrology Indicators: Primary Indicators (ininimum of one is required; check all that apply) Surface Water (A1) Water Marks (B1) Water Table (A2) High Water Table (A2) MLRA 1, 2, 4A, and 4B) Saturation (A3) Salt Crust (B11) Water Marks (B1) Water Marks (B1) Water Marks (B1) Aquatic Invertebrates (B13) Drainage Paterns (B10) Drainage Paterns (B10) Drainage Paterns (B10) Drainage Paterns (B10) Surface Soli Cracks (B6) Inno Deposits (B3) Recent Iron Reduction in Tilled Soils (C6) Surface Soli Cracks (B6) Innuation Visible on Aerial Imagery (C9 Sources (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Wetland Hydrology Pres			
Hydric Soil Indicators (Applicable to all LRRs, unless otherwise noted.) Histoscol (A1) Sandy Gleyed Matrix (S4) Histoscol (A1) Sandy Redox (S5) Black Histic (A3) Sandy Redox (S5) Black Histic (A3) Schipped Matrix (S6) Black Histic (A3) Loamy Mucky Mineral (F1) (except MLRA 1) Loamy Mucky Mineral (F1) (except MLRA 1) Loamy Mucky Mineral (F2) Thy Charles Surface (A11) Depleted Below Dark Surface (A12) Sandy Mucky Mineral (F2) Depleted Below Dark Surface (A11) Depleted Matrix (F3) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Surface Mucky Peat or Peat (S2) (LRR G) Redox Dark Surface (F7) Restrictive Layer (if observed): Type: Depth (inches): Wetland Hydrology Indicators: Primary Indicators (ininimum of one is required; check all that apply) Surface Water (A1) Water Marks (B1) Water Table (A2) High Water Table (A2) MLRA 1, 2, 4A, and 4B) Saturation (A3) Salt Crust (B11) Water Marks (B1) Water Marks (B1) Water Marks (B1) Aquatic Invertebrates (B13) Drainage Paterns (B10) Drainage Paterns (B10) Drainage Paterns (B10) Drainage Paterns (B10) Surface Soli Cracks (B6) Inno Deposits (B3) Recent Iron Reduction in Tilled Soils (C6) Surface Soli Cracks (B6) Innuation Visible on Aerial Imagery (C9 Sources (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Wetland Hydrology Pres			
Hydric Soil Indicators (Applicable to all LRRs, unless otherwise noted.) Histoscol (A1) Sandy Gleyed Matrix (S4) Histoscol (A1) Sandy Redox (S5) Black Histic (A3) Sandy Redox (S5) Black Histic (A3) Schipped Matrix (S6) Black Histic (A3) Loamy Mucky Mineral (F1) (except MLRA 1) Loamy Mucky Mineral (F1) (except MLRA 1) Loamy Mucky Mineral (F2) Thy Charles Surface (A11) Depleted Below Dark Surface (A12) Sandy Mucky Mineral (F2) Depleted Below Dark Surface (A11) Depleted Matrix (F3) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Surface Mucky Peat or Peat (S2) (LRR G) Redox Dark Surface (F7) Restrictive Layer (if observed): Type: Depth (inches): Wetland Hydrology Indicators: Primary Indicators (ininimum of one is required; check all that apply) Surface Water (A1) Water Marks (B1) Water Table (A2) High Water Table (A2) MLRA 1, 2, 4A, and 4B) Saturation (A3) Salt Crust (B11) Water Marks (B1) Water Marks (B1) Water Marks (B1) Aquatic Invertebrates (B13) Drainage Paterns (B10) Drainage Paterns (B10) Drainage Paterns (B10) Drainage Paterns (B10) Surface Soli Cracks (B6) Inno Deposits (B3) Recent Iron Reduction in Tilled Soils (C6) Surface Soli Cracks (B6) Innuation Visible on Aerial Imagery (C9 Sources (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Wetland Hydrology Pres			
Hydric Soil Indicators (Applicable to all LRRs, unless otherwise noted.) Histoscol (A1) Sandy Gleyed Matrix (S4) Histoscol (A1) Sandy Redox (S5) Black Histic (A3) Sandy Redox (S5) Black Histic (A3) Schipped Matrix (S6) Black Histic (A3) Loamy Mucky Mineral (F1) (except MLRA 1) Loamy Mucky Mineral (F1) (except MLRA 1) Loamy Mucky Mineral (F2) Thy Charles Surface (A11) Depleted Below Dark Surface (A12) Sandy Mucky Mineral (F2) Depleted Below Dark Surface (A11) Depleted Matrix (F3) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Surface Mucky Peat or Peat (S2) (LRR G) Redox Dark Surface (F7) Restrictive Layer (if observed): Type: Depth (inches): Wetland Hydrology Indicators: Primary Indicators (ininimum of one is required; check all that apply) Surface Water (A1) Water Marks (B1) Water Table (A2) High Water Table (A2) MLRA 1, 2, 4A, and 4B) Saturation (A3) Salt Crust (B11) Water Marks (B1) Water Marks (B1) Water Marks (B1) Aquatic Invertebrates (B13) Drainage Paterns (B10) Drainage Paterns (B10) Drainage Paterns (B10) Drainage Paterns (B10) Surface Soli Cracks (B6) Inno Deposits (B3) Recent Iron Reduction in Tilled Soils (C6) Surface Soli Cracks (B6) Innuation Visible on Aerial Imagery (C9 Sources (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Wetland Hydrology Pres			·
Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.) Histosco (A1) Sandy Gleyed Matrix (S4) Histosco (A1) Sandy Redox (S5) Black Histic (A3) Sandy Redox (S5) Black Histic (A3) Stripped Matrix (S6) Red Parent Material (P21) Hydrogen Sulfide (A4) Loamy Mucky Mineral (F1) (except MLRA 1) Depleted Below Dark Surface (F22) Ten Muck (A9) (LRR D, G) Depleted Below Dark Surface (A11) Depleted Matrix (F3) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Surface William (S1) Depleted Dark Surface (F7) Restrictive Layer (if observed): Type: Depth (inches): Wetland Hydrology Indicators: Primary Indicators (ininimum of one is required: check all that apply) Surface Water (A1) Water Marks (B1) Water Table (A2) An and 4B) Water Marks (B1) Water Marks (B1) Water Marks (B1) Water Marks (B1) Surface Water (A2) Aquatic Invertebrates (B13) Dyn's Season Water Table (C2) Sadiment Deposits (B2) Hydrogen Sulfide Odor (C1) Drift Deposits (B3) Condizing Rinksopheres on Living Roots (C3) Surface Soil Cracks (B6) Innuation Visible on Aerial Imagery (C9 Surface Soil Cracks (B6) Innuation Visible on Aerial Imagery (C9 Surface Soil Cracks (B6) Innuation Visible on Aerial Imagery (C9 Surface Soil Cracks (B6) Innuation Visible on Aerial Imagery (C9) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No Depth (inches): No Depth (inc	Type: C=Concentration D=Depletion F	RM=Reduced Matrix CS=Covered or Coated S	Sand Grains ² Location: PL=Pore Lining M=Matrix
Histosol (A1) Sandy Gleyed Matrix (S4) 2 cm Muck (A10) (LRR A E) Histic Epipedon (A2) Sandy Redox (S5) Iron-Manganese Masses (F12) (LRR D) Black Histic (A3) Stripped Matrix (S6) Red Parent Material (F21) Hydrogen Sulfide (A4) Loamy Mucky Mineral (F1) (except MLRA 1) Very Shallow Dark Surface (F22) 1 cm Muck (A9) (LRR D, G) Loamy Gleyed Matrix (F3) Depleted Below Dark Surface (A12) Redox Dark Surface (F6) Sandy Mucky Mineral (S1) Depleted Matrix (F3) Thick Dark Surface (A12) Redox Dark Surface (F6) Sandy Mucky Mineral (S1) Depleted Dark Surface (F7) Wetland Hydrology must be present. Setrictive Layer (if observed): Type: Depth (inches): Hydric Soil Present? Yes No MIRA 1, 2, 4A, and 4B) Surface Water (A1) Water-Stained Leaves (B9) (except Matrix (F3)) Water Matrix (G1) Aquatic Invertebrates (B13) Driange Patterns (B10) Drift Deposits (B2) Hydrogen Sulfide Odor (C1) Drift Deposits (B3) Oxidized Rhizospheres on Living Roots (C3) Surface Soil Cracks (B8) Surface (F8) Surface Soil Cracks (B8) Surface of Reduced fron (C4) Shallow Aquitard (D3) Iron Deposits (B3) Surface of Reduced fron (C4) Shallow Aquitard (D3) Iron Deposits (B3) Surface (B8) Surface of Reduced fron (C4) Resent from Reduction in Tilled Soils (C6) Surface Soil Cracks (B8) Surface (B8) Surface Water Cracks (B8) Surface (B8)			
Histic Epipedon (A2) Black Histic (A3) Stripped Matrix (S6) Black Histic (A3) Stripped Matrix (S6) Hydrogen Sulfide (A4) Loamy Mucky Mineral (F1) (except MLRA 1) Loamy Mucky Mineral (F2) Loamy Gleyed Matrix (F2) Other (Explain in Remarks) Depleted Below Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Below Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Depleted Dark Surface (F7) Restrictive Layer (if observed): Type: Depth (inches): Hydric Soil Present? Wetland Hydrology Indicators: Primary Indicators (minimum of one is required: check all that apply) Surface Water (A1) Water-Stained Leaves (B9) (except High Water Table (A2) High Water Table (A2) High Water Table (A2) Saturation (A3) Salt Crust (B11) Water Marks (B1) Sediment Deposits (B2) Hydrogen Sulfide Odor (C1) Sediment Deposits (B2) Hydrogen Sulfide Odor (C1) Drift Deposits (B3) Oxidized Rhizospheres on Living Roots (C3) Algal Mat or Crust (B4) Presence of Reduced fron (C4) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (B8) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (B8) Surface Water Present? Ves No Depth (inches): Wetland Hydrology Present? Ves No		•	
Black Histic (A3) Stripped Matrix (S6) Red Parent Material (F21) Hydrogen Sulfide (A4) Learny Mucky Mineral (F1) (except MLRA 1) Loamy Gleyed Matrix (F2) Other (Explain in Remarks) Depleted Below Dark Surface (A12) Redox Dark Surface (F6) Sandy Mucky Mineral (S1) Depleted Dark Surface (F7) Loamy Gleyed Matrix (F3) Thick Dark Surface (A12) Redox Dark Surface (F7) Loamy Gleyed Matrix (F3) Sandy Mucky Mineral (S1) Depleted Dark Surface (F7) Loamy Gleyed Matrix (F3) Seath Surface (A12) Redox Depressions (F8) Redox Dark Surface (F7) Redox Depressions (F8) Restrictive Layer (if observed): Type: Depth (inches): Hydric Soil Present? Yes No Remarks: Wettand Hydrology Indicators: Primary Indicators (minimum of one is required, check all that apply) Surface Water (A1) Water-Stained Leaves (B9) (except MLRA 1, 2 4A, and 4B) Saturation (A3) Sait Crust (B11) Water Marks (B1) Aquatic Invertebrates (B13) Sediment Deposits (B2) Dirih Deposits (B2) Hydrogen Sulfide Odor (C1) South Robert (B2) Dirih Deposits (B2) Dirih Deposits (B3) Oxidized Rhizospheres on Living Roots (C3) Algal Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (B8) FAC-Neutral Test (D5) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Water Table Present? Yes No Depth (inches): Water Table Present? Yes No Depth (inches): Surface Water Bresent? Yes No Depth (inches): Surface Water Bresent? Yes No Depth (inches): Wetland Hydrology Present? Yes No Depth (inches):			
Hydrogen Sulfide (A4)			
1 cm Muck (A9) (LRR D, G) Depleted Below Dark Surface (A11) Depleted Below Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Depleted Dark Surface (F7) Sandy Mucky Mineral (S1) Depleted Dark Surface (F7) Location Committee (S2) (LRR G) Redox Depressions (F8) Restrictive Layer (if observed): Type: Depth (inches): Hydric Soil Present? Yes No Remarks: Hydric Soil Present? No Water-Stained Leaves (B9) (except MLRA 1, 2 4A, and 4B) Surface Water (A1) Water Table (A2) MLRA 1, 2, 4A, and 4B) Saturation (A3) Salt Crust (B11) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Oxidized Rhizospheres on Living Roots (C3) Drift Deposits (B3) Agal Mat or Crust (B4) Iron Deposits (B5) Recent Iron Reduction in Tilled Soils (C6) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (B8) Field Observations: Sufface Water Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No			· · · · · · · · · · · · · · · · · · ·
Depleted Below Dark Surface (A11) Thick Dark Surface (A12) Redox Dark Surface (F6) Sandy Mucky Mineral (S1) 2.5 cm Mucky Peat or Peat (S2) (LRR G) Redox Depressions (F8) Restrictive Layer (if observed): Type: Depth (inches): Wetland hydrology must be present, unless disturbed or problematic. Restrictive Layer (if observed): Type: Depth (inches): Wetland Hydrology Indicators: Primary Indicators (minimum of one is required: check all that apply) Surface Water (A1) Water Table (A2) MIRA 1, 2, 4A, and 4B) Saturation (A3) Salt Crust (B11) Sediment Deposits (B2) Hydrogen Sulfide Odor (C1) Sediment Deposits (B3) Oxidized Rhizospheres on Living Roots (C3) Algal Mat or Crust (B4) Iron Deposits (B3) Surface Soil Cracks (B6) Recent Iron Reduction in Tilled Soils (C6) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Ves No Depth (inches): Wetland Hydrology Indicators (2 or more required) Water Marks (B10) Water Marks (B10) Water Marks (B11) Secondary Indicators (2 or more required) Water Marks (B10) Water Marks (B10) Water Marks (B10) Water Marks (B10) Drainage Patterns (B10) Drainage Patterns (B10) Saturation Visible on Aerial Imagery (C9 Saturation Visible on Aerial Imagery (C9 Situnted or Stressed Plants (D1) (LRR A) Raised Ant Mounds (D6) (LRR A) Frost-Heave Hummocks (D7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No Includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:			· · · · · · · · · · · · · · · · · · ·
Thick Dark Surface (A12) Redox Dark Surface (F6) Surface (F7) Redox Dark Surface (F7) Redox Depleted Dark Surface (F7) Redox D			
Sandy Mucky Mineral (S1) Depleted Dark Surface (F7) wetland hydrology must be present, unless disturbed or problematic. Restrictive Layer (if observed): Type: Depth (inches): Wetland Hydrology Indicators:			³ Indicators of hydrophytic vegetation and
2.5 cm Mucky Peat or Peat (S2) (LRR G) Redox Depressions (F8) unless disturbed or problematic. Restrictive Layer (if observed): Type: Depth (inches): Hydric Soil Present? Wetland Hydrology Indicators: Primary Indicators (minimum of one is required: check all that apply) Surface Water (A1) Surface Water (A1) Water-Stained Leaves (B9) (except High Water Table (A2) MLRA 1, 2, 4A, and 4B) Saturation (A3) Salt Crust (B11) Drainage Patterns (B10) Drainage Patterns (B10) Drainage Patterns (B10) Dry-Season Water Table (C2) Sediment Deposits (B2) Hydrogen Sulfide Odor (C1) Saturation Visible on Aerial Imagery (C9 Drift Deposits (B3) Algal Mat or Crust (B4) Presence of Reduced Iron (C4) Surface Soil Cracks (B6) Surface Water Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No	Sandy Mucky Mineral (S1)		
Type: Depth (inches): Hydric Soil Present? Yes No Remarks: No			
Type: Depth (inches): Hydric Soil Present? Yes No No Remarks: Popth (inches): Hydric Soil Present? Yes No	Restrictive Layer (if observed):		
Netland Hydrology Indicators:			
Name			Hydric Soil Present? Yes No)
Primary Indicators (minimum of one is required; check all that apply) Surface Water (A1) Water-Stained Leaves (B9) (except High Water Table (A2) MLRA 1, 2, 4A, and 4B) Saturation (A3) Salt Crust (B11) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algal Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9) Saturation Visible on Aerial Imagery (C9) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9 Geomorphic Position (D2) Shallow Aquitard (D3) Frost-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A) Frost-Heave Hummocks (D7) Frost-Heave Hummocks (D7) Saturation Present? Yes No Depth (inches): Water Table Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No Includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	IYDROLOGY		
Primary Indicators (minimum of one is required; check all that apply) Surface Water (A1) Water-Stained Leaves (B9) (except High Water Table (A2) MLRA 1, 2, 4A, and 4B) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algal Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Drainage Patterns (B10) Drainage Patterns	Wetland Hydrology Indicators:		
High Water Table (A2) Saturation (A3) Salt Crust (B11) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algal Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Water Table (A2) MILRA 1, 2, 4A, and 4B) Salt Crust (B11) Aquatic Invertebrates (B13) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9 Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Sturface Soil Cracks (B6) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Water Table Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:		equired; check all that apply)	Secondary Indicators (2 or more required)
Saturation (A3) Salt Crust (B11) Water Marks (B1) Aquatic Invertebrates (B13) Dry-Season Water Table (C2) Sediment Deposits (B2) Hydrogen Sulfide Odor (C1) Saturation Visible on Aerial Imagery (C9 Drift Deposits (B3) Oxidized Rhizospheres on Living Roots (C3) Algal Mat or Crust (B4) Iron Deposits (B5) Recent Iron Reduction in Tilled Soils (C6) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Water Table Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	Surface Water (A1)	Water-Stained Leaves (B9) (excer	
Water Marks (B1) Sediment Deposits (B2) Hydrogen Sulfide Odor (C1) Saturation Visible on Aerial Imagery (C9 Drift Deposits (B3) Oxidized Rhizospheres on Living Roots (C3) Geomorphic Position (D2) Algal Mat or Crust (B4) Presence of Reduced Iron (C4) Shallow Aquitard (D3) Iron Deposits (B5) Recent Iron Reduction in Tilled Soils (C6) Surface Soil Cracks (B6) Stunted or Stressed Plants (D1) (LRR A) Raised Ant Mounds (D6) (LRR A) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Water Table Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	High Water Table (A2)	MLRA 1, 2, 4A, and 4B)	4A, and 4B)
Sediment Deposits (B2) Hydrogen Sulfide Odor (C1) Saturation Visible on Aerial Imagery (C9 Drift Deposits (B3) Oxidized Rhizospheres on Living Roots (C3) Geomorphic Position (D2) Algal Mat or Crust (B4) Presence of Reduced Iron (C4) Shallow Aquitard (D3) Iron Deposits (B5) Recent Iron Reduction in Tilled Soils (C6) FAC-Neutral Test (D5) Surface Soil Cracks (B6) Stunted or Stressed Plants (D1) (LRR A) Raised Ant Mounds (D6) (LRR A) Inundation Visible on Aerial Imagery (B7) Other (Explain in Remarks) Frost-Heave Hummocks (D7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Water Table Present? Yes No Depth (inches): Saturation Present? Yes No Depth (inches): Saturation Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	Saturation (A3)	Salt Crust (B11)	Drainage Patterns (B10)
Drift Deposits (B3) Oxidized Rhizospheres on Living Roots (C3) Algal Mat or Crust (B4) Presence of Reduced Iron (C4) Shallow Aquitard (D3) Iron Deposits (B5) Recent Iron Reduction in Tilled Soils (C6) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Water Table Present? Yes No Depth (inches): Saturation Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	Water Marks (B1)	Aquatic Invertebrates (B13)	Dry-Season Water Table (C2)
Algal Mat or Crust (B4)	Sediment Deposits (B2)	Hydrogen Sulfide Odor (C1)	Saturation Visible on Aerial Imagery (C9)
Iron Deposits (B5) Recent Iron Reduction in Tilled Soils (C6) FAC-Neutral Test (D5) Surface Soil Cracks (B6) Stunted or Stressed Plants (D1) (LRR A) Raised Ant Mounds (D6) (LRR A) Inundation Visible on Aerial Imagery (B7) Other (Explain in Remarks) Frost-Heave Hummocks (D7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Water Table Present? Yes No Depth (inches): Saturation Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:		Oxidized Rhizospheres on Living F	Roots (C3) Geomorphic Position (D2)
Surface Soil Cracks (B6) Stunted or Stressed Plants (D1) (LRR A) Raised Ant Mounds (D6) (LRR A) Inundation Visible on Aerial Imagery (B7) Other (Explain in Remarks) Frost-Heave Hummocks (D7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Water Table Present? Yes No Depth (inches): Saturation Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	Algal Mat or Crust (B4)	Presence of Reduced Iron (C4)	Shallow Aquitard (D3)
Inundation Visible on Aerial Imagery (B7) Other (Explain in Remarks) Frost-Heave Hummocks (D7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Water Table Present? Yes No Depth (inches): Saturation Present? Yes No Depth (inches): Uniques capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	Iron Deposits (B5)	Recent Iron Reduction in Tilled So	
Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes No Depth (inches): Water Table Present? Yes No Depth (inches): Saturation Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No Depth (inches): (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:			
Field Observations: Surface Water Present? Yes No Depth (inches): Water Table Present? Yes No Depth (inches): Saturation Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No Depth (inches): (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:			Frost-Heave Hummocks (D7)
Surface Water Present? Yes No Depth (inches): Water Table Present? Yes No Depth (inches): Saturation Present? Yes No Depth (inches): (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	Sparsely Vegetated Concave Surface	e (B8)	
Water Table Present? Yes No Depth (inches): Saturation Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	Field Observations:		
Saturation Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	-		27
(includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:			
Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:		No Depth (inches):	Wetland Hydrology Present? Yes No _>
Remarks:	Describe Recorded Data (stream gauge,	monitoring well, aerial photos, previous inspec	ctions), if available:
relians.	Pomarka:		
	Nomains.		

U.S. Army Corps of Engineers

WETLAND DETERMINATION DATA SHEET – Western Mountains, Valleys, and Coast Region See ERDC/EL TR-10-3; the proponent agency is CECW-CO-R

OMB Control #: 0710-0024, Exp: 11/30/2024 Requirement Control Symbol EXEMPT: (Authority: AR 335-15, paragraph 5-2a)

Project/Site: Cascade Village Tracts A1-B1		City/Cour	nty: San Jua	an	Sampling Date:	6.18.25
Applicant/Owner: Charles McAlpine				State: CO	Sampling Point:	DP1W
Investigator(s): Elijah Varas and Sean Moore		Section, T	ownship, Ra	nge: S 13; T 39 N; R 9	W	
Landform (hillside, terrace, etc.): Valley		— Local relief (co	oncave, conv	rex, none): concave	Slop	oe (%): 1-4
Subregion (LRR): LRR E Lat: 37.647	138		Long: -1	07.809159	Datum:	NAD 83
Soil Map Unit Name: Cryaquolls-Typic Cryaquents com		pecent slopes			ication: PEM1D	
Are climatic / hydrologic conditions on the site typical fo	r this time o	f vear?	Yes	No x (If no, exp	olain in Remarks.)	
Are Vegetation, Soil, or Hydrologys		•				0
Are Vegetation, Soil, or Hydrologyn				plain any answers in Rer		
SUMMARY OF FINDINGS – Attach site ma					,	tures, etc.
			Sampled A			
			n a Wetland		No	
						
Remarks:						
Area is experience a Severe drought						
VEGETATION - Use scientific names of pl	ants.					
WELL STEAL IN	Absolute	Dominant	Indicator	D	lb	
Tree Stratum (Plot size: *)	% Cover	Species?	Status	Dominance Test wor		
1. Populus tremuloides	$\frac{2}{3}$	Yes Yes	FACU FAC	Number of Dominant S Are OBL, FACW, or F	•	5 (A)
2. Picea pungens 3.			<u> </u>			
4				Total Number of Domi Across All Strata:	nant Species	6 (B)
· · · · · · · · · · · · · · · · · · ·		=Total Cover		Percent of Dominant S	Species That	
Sapling/Shrub Stratum (Plot size: *)				Are OBL, FACW, or F	•	3.3%(A/B)
Dasiphora fruticosa	15	Yes_	FAC			
2. Salix monticola	25	Yes	_OBL_	Prevalence Index wo		
3. Salix arctica	10	Yes	FAC	Total % Cover of		
4				OBL species 2		29
5				FACW species7		140
	50	=Total Cover		FACILITIES 3	4 x 3 = x 4 =	102 8
Herb Stratum (Plot size:*) 1. Phalaris arundinacea	60	Yes	FACW		x 5 =	0
2. Juncus balticus	10	No No	FACW	Column Totals: 13		279 (B)
3. Equisetum arvense	6	No	FAC	Prevalence Index	` ′	`
4. Carex sp.	10	No				
5. Typha latifolia	1	No	OBL	Hydrophytic Vegetat	ion Indicators:	
6. Caltha leptosepala	3	No	OBL	1 - Rapid Test for	Hydrophytic Veget	ation
7.				X 2 - Dominance Te	est is >50%	
8.				X 3 - Prevalence Inc		
9.					Adaptations ¹ (Provides or on a separate	
10						sneet)
11				5 - Wetland Non-\		(Evalain)
Wandu Vine Stratum (Diet sine)	90	=Total Cover			ophytic Vegetation ¹	
Woody Vine Stratum (Plot size:)				¹ Indicators of hydric se be present, unless dis		
1					Largod or problema	
		=Total Cover		Hydrophytic Vegetation		
% Bare Ground in Herb Stratum2					No	<u></u>
Remarks: * Sampled entire wetland plant community						

SOIL Sampling Point: DP1W Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.) Depth Matrix Redox Features Loc² (inches) Color (moist) % Color (moist) % Type Texture Remarks 0-10 10YR 3/2 90 7.5YR 5/8 10 PL Mucky Loam/Clay Prominent redox concentrations ¹Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered or Coated Sand Grains. ²Location: PL=Pore Lining, M=Matrix. Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.) Indicators for Problematic Hydric Soils3: Histosol (A1) Sandy Gleyed Matrix (S4) 2 cm Muck (A10) (LRR A, E) Histic Epipedon (A2) Sandy Redox (S5) Iron-Manganese Masses (F12) (LRR D) Black Histic (A3) Stripped Matrix (S6) Red Parent Material (F21) Hydrogen Sulfide (A4) X Loamy Mucky Mineral (F1) (except MLRA 1) Very Shallow Dark Surface (F22) 1 cm Muck (A9) (LRR D, G) Loamy Gleyed Matrix (F2) Other (Explain in Remarks) Depleted Below Dark Surface (A11) Depleted Matrix (F3) Thick Dark Surface (A12) X Redox Dark Surface (F6) ³Indicators of hydrophytic vegetation and Sandy Mucky Mineral (S1) Depleted Dark Surface (F7) wetland hydrology must be present, 2.5 cm Mucky Peat or Peat (S2) (LRR G) unless disturbed or problematic. x Redox Depressions (F8) Restrictive Layer (if observed): Type: Rock layer Depth (inches): 10 **Hydric Soil Present?** No Remarks: HYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is required; check all that apply) Secondary Indicators (2 or more required) x Surface Water (A1) Water-Stained Leaves (B9) (except Water-Stained Leaves (B9) (MLRA 1, 2 x High Water Table (A2) MLRA 1, 2, 4A, and 4B) 4A, and 4B) x Saturation (A3) Salt Crust (B11) x Drainage Patterns (B10) Water Marks (B1) Aquatic Invertebrates (B13) x Dry-Season Water Table (C2) Sediment Deposits (B2) Hydrogen Sulfide Odor (C1) Saturation Visible on Aerial Imagery (C9) Drift Deposits (B3) x Oxidized Rhizospheres on Living Roots (C3) x Geomorphic Position (D2) x Algal Mat or Crust (B4) Presence of Reduced Iron (C4) Shallow Aquitard (D3) Iron Deposits (B5) Recent Iron Reduction in Tilled Soils (C6) X FAC-Neutral Test (D5) Surface Soil Cracks (B6) Stunted or Stressed Plants (D1) (LRR A) Raised Ant Mounds (D6) (LRR A) x Inundation Visible on Aerial Imagery (B7) Other (Explain in Remarks) Frost-Heave Hummocks (D7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes Depth (inches): Water Table Present? Yes X Depth (inches): 0 Saturation Present? Yes Х No Depth (inches): 0 Wetland Hydrology Present? Yes X No (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

U.S. Army Corps of Engineers

WETLAND DETERMINATION DATA SHEET – Western Mountains, Valleys, and Coast Region See ERDC/EL TR-10-3; the proponent agency is CECW-CO-R

OMB Control #: 0710-0024, Exp: 11/30/2024 Requirement Control Symbol EXEMPT: (Authority: AR 335-15, paragraph 5-2a)

Project/Site: Cascade Village Tracts A1-B1		City/Cour	nty: San Jua	ın		Sampling Date	e: <u>6.18</u>	.25
Applicant/Owner: Charles McAlpine				State:	CO	Sampling Poin	t:D	P1U
Investigator(s): Elijah Varas and Sean Moore		Section, T	ownship, Ra	nge: S 13; T 3	39 N; R 9 V	V		
Landform (hillside, terrace, etc.): Valley		Local relief (co	oncave, conv	ex, none):		s	lope (%):	: _5
Subregion (LRR): LRR E Lat: 37.6	46804		Long: -1	07.809708		Datum	n: NAD	83
Soil Map Unit Name: Cryaquolls-Typic Cryaquents c	omplex, 1 to 5	pecent slopes		NV	NI classific	ation: None		
Are climatic / hydrologic conditions on the site typica				No x (If no, expla	ain in Remarks.)	
Are Vegetation, Soil, or Hydrology								
Are Vegetation, Soil, or Hydrology				plain any answe		-		-
SUMMARY OF FINDINGS – Attach site r							atures	i, etc.
Hydrophytic Vegetation Present? Yes	No X	Is the	Sampled A	rea				
	No X		n a Wetland		es	No_X		
	No X							
Remarks:								
Area is experience a Severe drought								
VEGETATION – Use scientific names of			4 45 4					
Tree Stratum (Plot size:)	Absolute % Cover	Dominant Species?	Indicator Status	Dominance 1	Test work	sheet:		
1				Number of Do				
2.				Are OBL, FA			1	(A)
3.				Total Numbe	r of Domin	ant Species		
4				Across All St	rata:	_	2	- ^(B)
No constitution of the following state of the state of th		=Total Cover		Percent of Do			FO 00/	(A/D)
Sapling/Shrub Stratum (Plot size:	_)			Are OBL, FA	CVV, or FA	U:	50.0%	- (A/B)
1		-		Prevalence I	ndex wor	ksheet:		
3,					Cover of:		ply by:	
4		* *		OBL species	0	x 1 =	0	
5.				FACW specie	es 0	x 2 =	0	_
		=Total Cover		FAC species			180	_
Herb Stratum (Plot size: 1 m)				FACU specie			128	
1. Bromus inermis	8	No	UPL	UPL species		x 5 =	40 348	- (D)
2. Dactylis glomerata	- 30	Yes Yes	FACU	Column Total	ls: <u>100</u> e Index =	`´ _	.48	_ ^(B)
Equisetum arvense Trifolium pratense	2	No	FACU FACU	rievaleno	e maex -	D/A - 3.	.40	-
5				Hydrophytic	Vegetatio	n Indicators:		
6.				1 - Rapid	Test for F	lydrophytic Veg	jetation	
7.				2 - Domii	nance Test	t is >50%		
8.					alence Inde			
9						daptations ¹ (Pro or on a separa		
10		-				· .	te sneet)	,
11	100	=Total Cover				ascular Plants¹ ohytic Vegetatio	n ¹ (Evol:	ain)
Woody Vine Stratum (Plot size:		- Folai Covei				I and wetland h		
1,	_′					i and welland n irbed or probler		must
2.				Hydrophytic				
÷		=Total Cover		Vegetation				
% Bare Ground in Herb Stratum 0				Present?	Yes_	No	<u>X</u>	
Remarks:								

OIL			Sampling Point:DP1
Profile Description: (Describe to the de	pth needed to document the indicator or	confirm the absen	ce of indicators.)
Depth Matrix	Redox Features		
(inches) Color (moist) %	Color (moist) % Type ¹ Loc ²	Texture	Remarks
0-6 10YR 5/4 100		Loamy/Clayey	
6-20 10YR 4/4 100		Loamy/Clayey	
		No. Zoumy, orayoy	**
	· · · · · · · · · · · · · · · · · · ·	···	
		//\·	-
· · · · · · · · · · · · · · · · ·		X	
		(//	
		74	
		27	
Type: C=Concentration, D=Depletion, RN	1=Reduced Matrix, CS=Covered or Coated S	and Grains. 2	_ocation: PL=Pore Lining, M=Matrix.
Hydric Soil Indicators: (Applicable to al	LRRs, unless otherwise noted.)	Indic	ators for Problematic Hydric Soils ³ :
Histosol (A1)	Sandy Gleyed Matrix (S4)	2	cm Muck (A10) (LRR A, E)
Histic Epipedon (A2)	Sandy Redox (S5)	Ir	on-Manganese Masses (F12) (LRR D
Black Histic (A3)	Stripped Matrix (S6)	F	Red Parent Material (F21)
Hydrogen Sulfide (A4)	Loamy Mucky Mineral (F1) (excep	t MLRA 1) \	ery Shallow Dark Surface (F22)
1 cm Muck (A9) (LRR D, G)	Loamy Gleyed Matrix (F2)		Other (Explain in Remarks)
Depleted Below Dark Surface (A11)	Depleted Matrix (F3)		
Thick Dark Surface (A12)	Redox Dark Surface (F6)	³ India	ators of hydrophytic vegetation and
Sandy Mucky Mineral (S1)	Depleted Dark Surface (F7)	V	etland hydrology must be present,
2.5 cm Mucky Peat or Peat (S2) (LRR	G) Redox Depressions (F8)	u	nless disturbed or problematic.
Restrictive Layer (if observed):			
Restrictive Layer (if observed): Type:			
Restrictive Layer (if observed): Type: Depth (inches): Remarks:		Hydric Soil Pres	sent? Yes No _
Type: Depth (inches): Remarks:		Hydric Soil Pres	sent? Yes No _
Type: Depth (inches): Remarks: IYDROLOGY Wetland Hydrology Indicators:			
Type: Depth (inches): Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is req	18.4 2.0	Seco	ndary Indicators (2 or more required)
Type: Depth (inches): Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is req Surface Water (A1)	Water-Stained Leaves (B9) (exce	Seco	ndary Indicators (2 or more required) Vater-Stained Leaves (B9) (MLRA 1, 2
Type: Depth (inches): Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is req Surface Water (A1) High Water Table (A2)	Water-Stained Leaves (B9) (excel MLRA 1, 2, 4A, and 4B)	Seco	ndary Indicators (2 or more required) Vater-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B)
Type: Depth (inches): Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is req Surface Water (A1) High Water Table (A2) Saturation (A3)	Water-Stained Leaves (B9) (excel MLRA 1, 2, 4A, and 4B) Salt Crust (B11)	Seco ot V E	ndary Indicators (2 or more required) Vater-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10)
Type: Depth (inches): Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is req Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1)	Water-Stained Leaves (B9) (excellent MLRA 1, 2, 4A, and 4B) Salt Crust (B11) Aquatic Invertebrates (B13)	Seco otV	ndary Indicators (2 or more required) Vater-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2)
Type: Depth (inches): Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is req Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2)	Water-Stained Leaves (B9) (excel MLRA 1, 2, 4A, and 4B) Salt Crust (B11) Aquatic Invertebrates (B13) Hydrogen Sulfide Odor (C1)	Seco bt	ndary Indicators (2 or more required) Vater-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (C
Type: Depth (inches): Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is req Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3)	Water-Stained Leaves (B9) (excel MLRA 1, 2, 4A, and 4B) Salt Crust (B11) Aquatic Invertebrates (B13) Hydrogen Sulfide Odor (C1) Oxidized Rhizospheres on Living R	Seco V	ndary Indicators (2 or more required) Vater-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (C
Type: Depth (inches): Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is req Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algal Mat or Crust (B4)	Water-Stained Leaves (B9) (excellent MLRA 1, 2, 4A, and 4B) Salt Crust (B11) Aquatic Invertebrates (B13) Hydrogen Sulfide Odor (C1) Oxidized Rhizospheres on Living Ference of Reduced Iron (C4)	Seco V Coots (C3) Seco	ndary Indicators (2 or more required) Vater-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (C Geomorphic Position (D2) Shallow Aquitard (D3)
Type: Depth (inches): Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is req Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algal Mat or Crust (B4) Iron Deposits (B5)	Water-Stained Leaves (B9) (excel MLRA 1, 2, 4A, and 4B) Salt Crust (B11) Aquatic Invertebrates (B13) Hydrogen Sulfide Odor (C1) Oxidized Rhizospheres on Living F Presence of Reduced Iron (C4) Recent Iron Reduction in Tilled Sc	Seco V Coots (C3) Soots (C3) Sils (C6) Seco	ndary Indicators (2 or more required) Vater-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (C Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5)
Type: Depth (inches): Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is req Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algal Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6)	Water-Stained Leaves (B9) (excel MLRA 1, 2, 4A, and 4B) Salt Crust (B11) Aquatic Invertebrates (B13) Hydrogen Sulfide Odor (C1) Oxidized Rhizospheres on Living F Presence of Reduced Iron (C4) Recent Iron Reduction in Tilled Sc Stunted or Stressed Plants (D1) (I	Seco V Coots (C3) Sils (C6) RR A) Seco	ndary Indicators (2 or more required) Vater-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (C Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A)
Type: Depth (inches): Remarks: Primary Indicators (minimum of one is required by Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algal Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (1)	Water-Stained Leaves (B9) (excel MLRA 1, 2, 4A, and 4B) Salt Crust (B11) Aquatic Invertebrates (B13) Hydrogen Sulfide Odor (C1) Oxidized Rhizospheres on Living F Presence of Reduced Iron (C4) Recent Iron Reduction in Tilled So Stunted or Stressed Plants (D1) (I	Seco V Coots (C3) Sils (C6) RR A) Seco	ndary Indicators (2 or more required) Vater-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (C Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5)
Type: Depth (inches): Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is reg Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algal Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (Sparsely Vegetated Concave Surface	Water-Stained Leaves (B9) (excel MLRA 1, 2, 4A, and 4B) Salt Crust (B11) Aquatic Invertebrates (B13) Hydrogen Sulfide Odor (C1) Oxidized Rhizospheres on Living F Presence of Reduced Iron (C4) Recent Iron Reduction in Tilled So Stunted or Stressed Plants (D1) (I	Seco V Coots (C3) Sils (C6) RR A) Seco	ndary Indicators (2 or more required) Vater-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (C Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A)
Type: Depth (inches): Remarks: Primary Indicators (minimum of one is required by Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algal Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (Sparsely Vegetated Concave Surface Field Observations:	Water-Stained Leaves (B9) (excel MLRA 1, 2, 4A, and 4B) Salt Crust (B11) Aquatic Invertebrates (B13) Hydrogen Sulfide Odor (C1) Oxidized Rhizospheres on Living Feresence of Reduced Iron (C4) Recent Iron Reduction in Tilled Scalar (D1) (IB) Other (Explain in Remarks) (B8)	Seco V Coots (C3) Sils (C6) RR A) Seco	ndary Indicators (2 or more required) Vater-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (C Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A)
Type: Depth (inches): Remarks: Primary Indicators (minimum of one is required by saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algal Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (Compared by Sparsely Vegetated Concave Surface Surface Water Present? Surface Water Present? Yes	Water-Stained Leaves (B9) (excel MLRA 1, 2, 4A, and 4B) Salt Crust (B11) Aquatic Invertebrates (B13) Hydrogen Sulfide Odor (C1) Oxidized Rhizospheres on Living Feresence of Reduced Iron (C4) Recent Iron Reduction in Tilled Scatter (B13) Stunted or Stressed Plants (D1) (IB17) Other (Explain in Remarks) No Depth (inches):	Seco V Coots (C3) Sils (C6) RR A) Seco	ndary Indicators (2 or more required) Vater-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (C Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A)
Type: Depth (inches): Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is req Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algal Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (incompared to the control of the control o	Water-Stained Leaves (B9) (excel MLRA 1, 2, 4A, and 4B) Salt Crust (B11) Aquatic Invertebrates (B13) Hydrogen Sulfide Odor (C1) Oxidized Rhizospheres on Living F Presence of Reduced Iron (C4) Recent Iron Reduction in Tilled Sc Stunted or Stressed Plants (D1) (I 37) Other (Explain in Remarks) No Depth (inches): Depth (inches):	Seco V Coots (C3)	ndary Indicators (2 or more required) Vater-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (C Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A) Frost-Heave Hummocks (D7)
Type: Depth (inches): Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is req Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algal Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (inches Sparsely Vegetated Concave Surface Field Observations: Surface Water Present? Water Table Present? Yes Saturation Present?	Water-Stained Leaves (B9) (excel MLRA 1, 2, 4A, and 4B) Salt Crust (B11) Aquatic Invertebrates (B13) Hydrogen Sulfide Odor (C1) Oxidized Rhizospheres on Living Feresence of Reduced Iron (C4) Recent Iron Reduction in Tilled Scatter (B13) Stunted or Stressed Plants (D1) (IB17) Other (Explain in Remarks) No Depth (inches):	Seco V Coots (C3)	ndary Indicators (2 or more required) Vater-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (C Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A)
Type: Depth (inches): Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is reg Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algal Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (inches Saturation Present? Water Table Present? Yes Saturation Present? Yes (includes capillary fringe)	Water-Stained Leaves (B9) (excel MLRA 1, 2, 4A, and 4B) Salt Crust (B11) Aquatic Invertebrates (B13) Hydrogen Sulfide Odor (C1) Oxidized Rhizospheres on Living Feresence of Reduced Iron (C4) Recent Iron Reduction in Tilled Scale Stunted or Stressed Plants (D1) (ISS) Other (Explain in Remarks) No Depth (inches): No Depth (inches):	Seco V Roots (C3) Sils (C6) RR A) Wetland Hydr	ndary Indicators (2 or more required) Vater-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (C Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A) Frost-Heave Hummocks (D7)
Type: Depth (inches): Remarks: IYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is reg Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algal Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (inches Saturation Present? Water Table Present? Yes Saturation Present? Yes (includes capillary fringe)	Water-Stained Leaves (B9) (excel MLRA 1, 2, 4A, and 4B) Salt Crust (B11) Aquatic Invertebrates (B13) Hydrogen Sulfide Odor (C1) Oxidized Rhizospheres on Living F Presence of Reduced Iron (C4) Recent Iron Reduction in Tilled Sc Stunted or Stressed Plants (D1) (I 37) Other (Explain in Remarks) No Depth (inches): Depth (inches):	Seco V Roots (C3) Sils (C6) RR A) Wetland Hydr	ndary Indicators (2 or more required) Vater-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (C Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A) Frost-Heave Hummocks (D7)

APPENDIX E
USDA NRSC Soils Report

Animas- Dolores Area, Colorado, Parts of Archuleta, Dolores, Hinsdale, La Plata, Montezuma, San Juan, and San Miguel Counties

Map Unit: 53—Cryaquolls-Typic Cryaquents complex, 1 to 5 percent slopes

Component: Cryaquolls (50%)

The Cryaquolls component makes up 50 percent of the map unit. Slopes are 1 to 5 percent. This component is on flood plains, valley floors. The parent material consists of alluvium derived from mixed sources. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is poorly drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is low. This soil is occasionally flooded. It is not ponded. A seasonal zone of water saturation is at 13 inches during May, June. Organic matter content in the surface horizon is about 4 percent. This component is in the R048AY241CO Mountain Meadow ecological site. Nonirrigated land capability classification is 6w. This soil meets hydric criteria.

Component: Typic Cryaquents (35%)

The Typic Cryaquents component makes up 35 percent of the map unit. Slopes are 1 to 5 percent. This component is on flood plains, valley floors. The parent material consists of alluvium derived from mixed sources. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is poorly drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is occasionally flooded. It is not ponded. A seasonal zone of water saturation is at 13 inches (depth from the mineral surface is 9 inches) during May, June. Organic matter content in the surface horizon is about 85 percent. Below this thin organic horizon the organic matter content is about 1 percent. This component is in the R048AY241CO Mountain Meadow ecological site. Nonirrigated land capability classification is 6w. This soil meets hydric criteria. There are no saline horizons within 30 inches of the soil surface.

Map Unit: 330 Needleton stony loam, 15 to 30 Percent Slopes

Component: Needleton (85%)

The Needleton component makes up 85 percent of the map unit. Slopes are 15 to 30 percent. This component is on mountain slopes. The parent material consists of slope alluvium derived from rhyolite and sandstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 85 percent. Below this thin organic horizon the organic matter content is about 1 percent. This component is in the F048AY918CO Spruce-Fir Woodland ecological site. Nonirrigated land capability classification is 7s. This soil does not meet hydric criteria. There are no saline horizons within 30 inches of the soil surface.

Map Unit: 51 Clayburn-Hourglass complex, 5 to 25 percent slopes

Component: Clayburn (55%)

The Clayburn component makes up 55 percent of the map unit. Slopes are 5 to 25 percent. This component is on mountain slopes. The parent material consists of slope alluvium derived from sandstone and shale. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is high. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 3 percent. This component is in the R048AY250CO Subalpine Loam ecological site. Nonirrigated land capability classification is 6e. This soil does not meet hydric criteria.

Component: Hourglass (35%)

The Hourglass component makes up 35 percent of the map unit. Slopes are 5 to 25 percent. This component is on mountain slopes. The parent material consists of slope alluvium derived from sandstone, limestone, and shale. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is high. Shrinkswell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 3 percent. This component is in the R048AY250CO Subalpine Loam ecological site. Nonirrigated land capability classification is 6e. This soil does not meet hydric criteria.

Map Unit: 338 Needleton -Snowdon-Rock outcrop complex, 30 to 80 percent slopes

Component: Needleton (45%)


The Needleton component makes up 45 percent of the map unit. Slopes are 30 to 80 percent. This component is on mountain slopes. The parent material consists of slope alluvium and colluvium derived from rhyolite, limestone and sandstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 85 percent. Below this thin organic horizon the organic matter content is about 1 percent. This component is in the F048AY918CO Spruce-Fir Woodland ecological site. Nonirrigated land capability classification is 7e. This soil does not meet hydric criteria. There are no saline horizons within 30 inches of the soil surface.


Component: Snowdon (30%)

The Snowdon component makes up 30 percent of the map unit. Slopes are 30 to 80 percent. This component is on structural benches, mountain slopes. The parent material consists of residuum and slope alluvium derived from rhyolite, limestone and sandstone. Depth to a root restrictive layer, bedrock, lithic, is 10 to 20 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is very low. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is low. This soil is not flooded. It is not

ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 85 percent. Below this thin organic horizon the organic matter content is about 2 percent. This component is in the F048AY918CO Spruce-Fir Woodland ecological site. Nonirrigated land capability classification is 7s. This soil does not meet hydric criteria. There are no saline horizons within 30 inches of the soil surface.

ATTACHMENT 3 Engineer Drawings





CERTIFICATE OF OUNIERS.

THAT CHAIN THESE PRESENTS

THAT CHAIN THESE PRESENTS

THAT CHAIN THE SEPRESENTS

THAT CHAIN THE SEPRESENTS

THAT CHAIN THE SEPRESENTS

THAT CHAIN THE SEPRESENTS

THAT SEPRESENTS

THE RANGEST CHAIN THE SEPRESENTS

THE RANGEST CHAIN THE SEPRESENTS

THE RANGEST CHAIN THE SEPRESENT SEPRESENTS

THE SEPRESENTS

TH

Debuggerent, Lichters R.v. a Charatab corporation, whose address 201 Debuggerent, Dr. Dva aga, Cubratab corporation, whose address 201 Debuggerent, Dr. Dva aga, Cubratab, 201001, beray Lichter, levyl and oren of 10.19 K. Hizvayli Rick as shown on the Resubshikum of a finishit Nacional Substitution of Conscious Village recorded in the Entire Control of the Control of Conscious Village recorded in the reput for the Substitution of Conscious Village recorded in the reput for the Substitution Control of Substitution (Substitution Village).

Inst Kinsel A. Rotacly and Jacot C. Rotacly whose address in 1924
Inst Waven Annother, Teas 2000, Leady the Regis and Excelled of the New and Rotacle.
Subsidies in a Constant Wiley recorded in the Office of the Sas Jan Scholey, on a Constant Wiley recorded in the Office of the Sas Jan Scholey, on a Constant Wiley recorded in the Office of the Sas Jan Scholey, on the Constant Scholey of the Sas Jan Scholey of t

hane N 19 O9 20 W. 20523 feet, hence N O9 53 36 E 76 49 feet, hence N 75 46 47 E 1566 feet to the westerly right-of-way of

However, and the ope of a non-tengent curve to the right with a determined of the control of the

New N. 13. 33. 95 W. 1844 feat aboy the westerly me of indifference is the individual formal formal features and indifference is the scale of the control of According to 105 27 OCT W. 70.65 feet along the easterly las of sad lisk to the southerly we of sad to 15k, the resolventy by 0.0 To 15k, and 198 OC DV 3.05056 fact along the southerly be of lots and 16k. Reception Number 136239 to the westerly We of sed Lot

FIRST AMENDMENT OF THE RESUBDIVISION THE TWILIGHT MEADOW SUBDIVISION LOCATED IN SECTION 13, T 39 N, R 9 W, N.M.P.M. AT CASCADE VILLAGE SAN JUAN COUNTY, COLORADO

There along the error of a traigent curve to the laft with a dolta angle induce along the error of a traigent curve to the laft, with a dolta angle and 17 19 10 00 and a relador and 19.64 of the for a closure of 47.48 feet that long chird bears in 60°T-20°W, 47.31 feet chain the wastery right-of-ray of indexiven hands and the error of the control of induced in 18.00°T-00°W, 3.510 feet chain the westery right-of-way inference with the interact of lond in 18.00°T-00°W, 3.510 feet chain the control of the first of the manual hands of the first of the first of the control of the first of The control of the co or instance victors in the pagent curve to the left with a delta angle and off or 0.00 for due to reason of 2000 clet for a destance of 3142 and 0.00 clot off and a destance of 3142 erect the long ratio above 18 0.00 for 0.01 for (2.22, 2.22, 3ice 5 b4 33 00° t, 80.00 Feet along the northerly right-of-way freedow Grole,

There casked the water to be residential replated and designated as the FRSI ARENDERIN OF THE RESIDENCIAL OF THE THILDOW SUBPRISON AT CASSADE VILLAGE. Could be a solution of the could be cou

velna cascment to Western Colorado Power Company, Book 175 Paga in classify for recording anaester, as a conditional by the VIII of the constitution o Right-of-way to Mounton States Telephone and Telegraph Book 152 no 412,

Figure 1.7.

Figure described to Colorado-Lite Factoric, Blook 222, Page 97, Page 17, Page 18, Page 17, Page 18, Page 17, Page 18, Page 18

usitioners statement in any and act in minopological processed by the or charter any direct investment and the control and that is not that it was not observed against it is to be the six of the control and or the control and control

Coles

Key Tation No. 18450

THE PLAT IS HEREBY EXECUTED BY THE FOLLOWING PARTIES!

Config of to floto $\frac{1}{2}$ is a solution of the solution of the solution of the solutions of the solutions of the solution of the solutions of the solutions

NOLETY BENETHAR FRANCE CLEAR SPETTY BOLLORIGHEST ESTATES, NO. a Colorado corporation Му соливавол ехривая

Dr. Howard Wents INCOME

found of its first or in the following the second first, freedom of material principal or in the first or in t

Noter Chan Interness thy commission express

by Aller Control of Pater Control of the Control of

GENERAL DEDICATION:
1, Dashed lines
2. The areas outside o

Distinct also accounted of the purity category being specificable least.

2. The areas of exploration of the purity declaration in a shown herein are unity declaration for the instablion manner and exploration of the and for the bedefit of delay declaration are appreciated to and for the bedefit of delay confined with the permetter of Clascotto Wagin on it may not a the properties of Clascotto Wagin on it may not such a supplied to the clascotto Wagin on it may be subjected for for force and interpretation of Clascotto Wagin on it may be subjected. The force and interpretation of Clascotto Wagin is an extension of the told for the wagin of the force and interpretation of subject to the control of the class of the analysis of properties and replacement of turity and design when the class of the analysis of species of the analysis of species of the analysis of species of the class of the analysis of species of the class of the analysis of species of the class of the c plat was approved by the Si

Allent Linety h April

The project was reviewed and approved by the Board of County Commissions of San Jones.

BOARD OF COUNTY COMMISSIONERS OF SAN JUAN COUNTY, COLORADO

Attest Conty Con Labour Er Cores + Children

VACATION STATEMENT.

In closury latter, compare history count to the autochment on headon

If the tells rescounts as hope on the linguit feath studies on the control

The tells are the statement of the control of the control

The tells are the statement of the control of the control


The tells are the statement of the control of the c

US West Commession he Call the sameting

ENGINEERING & SURVEYING
355 SOUTH CANNOT DAE NOT
DINKARD, CARNOT DAE NOT
DINKARD, CARNOT DAE NOT
DINKARD, CAROLO DA 1322


CASCADE MILAGE INVESTMENT VENTURE


Syra to 102. See on the State of the State o





REBNUN BNIWARD SOS [±]94M MARINE MUNICIPALITY OF THE PROPERTY OF THE PRO

R38MUN DVINVARO









ATTACHMENT 4 Species List- IPaC



United States Department of the Interior



FISH AND WILDLIFE SERVICE

Western Colorado Ecological Services Field Office 445 West Gunnison Avenue, Suite 240 Grand Junction, CO 81501-5711 Phone: (970) 628-7180 Fax: (970) 245-6933

In Reply Refer To: 07/03/2025 16:43:53 UTC

Project Code: 2025-0117716

Project Name: Cascade Village Condo

Subject: List of threatened and endangered species that may occur in your proposed project

location or may be affected by your proposed project

To Whom It May Concern:

The enclosed species list identifies threatened, endangered, proposed and candidate species, as well as proposed and final designated critical habitat, that may occur within the boundary of your proposed project and/or may be affected by your proposed project. The species list fulfills the requirements of the U.S. Fish and Wildlife Service (Service) under section 7(c) of the Endangered Species Act (ESA) of 1973, as amended (16 U.S.C. 1531 *et seq.*).

New information based on updated surveys, changes in the abundance and distribution of species, changed habitat conditions, or other factors could change this list. Please feel free to contact us if you need more current information or assistance regarding the potential impacts to federally proposed, listed, and candidate species and federally designated and proposed critical habitat (Colorado Ecological Services Field Office). Please note that under 50 CFR 402.12(e) of the regulations implementing section 7 of the ESA, the accuracy of this species list should be verified after 90 days. This verification can be completed formally or informally as desired. The Service recommends that verification be completed by visiting the IPaC website at regular intervals during project planning and implementation for updates to species lists and information. An updated list may be requested through the IPaC system by completing the same process used to receive the enclosed list.

The purpose of the ESA is to provide a means whereby threatened and endangered species and the ecosystems upon which they depend may be conserved. Under sections 7(a)(1) and 7(a)(2) of the ESA and its implementing regulations (50 CFR 402 et seq.), Federal agencies are required to utilize their authorities to carry out programs for the conservation of threatened and endangered species and to determine whether projects may affect threatened and endangered species and/or designated critical habitat.

A Biological Assessment is required for construction projects (or other undertakings having similar physical impacts) that are major Federal actions significantly affecting the quality of the human environment as defined in the National Environmental Policy Act (42 U.S.C. 4332(2) (c)). For projects other than major construction activities, the Service suggests that a biological evaluation similar to a Biological Assessment be prepared to determine whether the project may affect listed or proposed species and/or designated or proposed critical habitat. Recommended contents of a Biological Assessment are described at 50 CFR 402.12.

If a Federal agency determines, based on the Biological Assessment or biological evaluation, that listed species and/or designated critical habitat may be affected by the proposed project, the agency is required to consult with the Service pursuant to 50 CFR

402. In addition, the Service recommends that candidate species, proposed species and proposed critical habitat be addressed within the consultation. More information on the regulations and procedures for section 7 consultation, including the role of permit or license applicants, can be found in the "Endangered Species Consultation Handbook" at: https://www.fws.gov/sites/default/files/documents/endangered-species-consultation-handbook.pdf.

Project code: 2025-0117716

Projects and activities without a Federal nexus (e.g., without Federal funding, permit, or authorization) should be evaluated for the potential to "take" listed wildlife. Take does not apply to listed plants and to designated critical habitat. The term "take" means to harass, harm, pursue, hunt, shoot, wound, kill, trap, capture, or collect, or to attempt to engage in any such conduct (ESA Section 3. Definitions). Harm in the definition of "take" in the ESA means an act which actually kills or injures wildlife. Such act may include significant habitat modification or degradation where it actually kills or injures wildlife by significantly impairing essential behavioral patterns, including breeding, feeding or sheltering (50 CFR 17.3).

Gray Wolf: On November 8, 2023, the Service promulgated an ESA section 10(j) (i.e., experimental population) rule (10(j) rule) for gray wolf (*Canis lupus*) within the State of Colorado (88 FR 77014). For purposes of ESA section 7 consultation, we treat experimental populations as if they are proposed for listing, except on National Park Service and Service lands, where they are treated as threatened. Evaluations for proposed species are completed under the regulations for conferencing (50 CFR 402.10). Conferencing for species that are proposed for Federal listing, or for proposed critical habitat, is only required if a proposed action is likely to jeopardize the continued existence of a species or will result in destruction or adverse modification of proposed critical habitat. If an action agency determines that their action would not jeopardize the continued existence of the species, and/ or would not result in the destruction or adverse modification of critical habitat, and the Service concurs, the conferencing requirement is fulfilled.

Colorado River Fish/Depletions: Formal interagency consultation under section 7 of the ESA is required for projects that may lead to depletions of water from any system that is a tributary to the Colorado River. Federal agency actions resulting in water depletions to the Colorado River system may affect the endangered bonytail (*Gila elegans*), Colorado pikeminnow (*Ptychocheilus lucius*), razorback sucker (*Xyrauchen texanus*), and the threatened humpback chub (*Gila cypha*), and their designated critical habitats.

Water depletions include evaporative losses and consumptive use of surface or groundwater within the affected basin, often characterized as diversion minus return flows. Project elements that could be associated with depletions include, but are not limited to: ponds, lakes, and reservoirs (e.g., detention, recreation, irrigation, storage, stock watering, municipal storage, and power generation); drilling, hydraulic fracturing and completion of oil and gas wells; hydrostatic testing of pipelines; water wells; dust abatement; diversion structures; and water treatment facilities. Any actions that may result in water depletions should be identified. An analysis of the water depletion should include: an estimate of the amount and timing of the average annual water use (both historic and new uses) and methods of arriving at such estimates; location of water use or where diversion occurs, as specifically as possible; if and when the water will be returned to the system; and the intended use of the water. Depending on Project details, the Service may have more specific questions regarding the potential consumptive use of the water.

The Service, in accordance with the Upper Colorado River Endangered Fish Recovery Program (https://coloradoriverrecovery.org/uc/), adopted a *de minimis* policy, which states that water-related activities in the Upper Colorado River Basin that result in less than 10 acre-foot per year of depletions in flow have no effect on the Colorado River endangered fish species and their critical habitat, and thus do not require consultation for potential effects on those species and critical habitat. While no section 7 consultation is needed, the Service requests Federal agencies notify the Upper Colorado Fishes Coordinator of depletions between 0.1 and 10 acre-feet per year with the approximate location of the project (e.g., reference to the most proximate surface water or tributary), the water use (e.g., agricultural, oil and gas, energy), and the timing of and depletion

amount. Detention basins designed to detain runoff for less than 72 hours, and temporary withdrawals of water outside of critical habitat (e.g., for hydrostatic pipeline testing) that return all the water to the same drainage basin within 30 days, are considered to have no effect and do not require consultation.

Suckley's Cuckoo Bumble Bee: On December 17, 2024, Suckley's cuckoo bumble bee (*Bombus suckleyi*) (Suckley's) was proposed for listing as an endangered species (89 FR 102074). Suckley's is an obligate social parasite of social bumble bees in the genus *Bombus*. Suckley's cannot successfully reproduce without the availability of suitable host colonies. It is a semi-specialist parasite and confirmed to usurp nests of Western bumble bee (*Bombus occiddentalis*) and Nevada bumble bees (*Bombus nevadensis*) (Service 2024).

Based on the best available information, no Suckley's have been observed in Colorado since 2014 despite ongoing surveys. The Species Status Assessment (SSA) shows observations since 2018 occur only in northern latitudes, primarily in Canada (Service 2024), but the species may persist in high quality upper elevation habitats in western States. While Suckley's is proposed for listing, there is no prohibition of "take" under Section 9 of the ESA; therefore, projects without a federal nexus, do not need to engage with the Service to exempt take under the ESA. However, we encourage including conservation measures benefiting pollinators and pollinator habitat into projects. Examples include retaining suitable foraging (diversity and abundance of native floral resources), nesting (suitable host colony above or below ground), and overwintering habitat (loose substrates such as leaf litter, duff, rotting logs); maintaining habitat for host bumble bees by avoiding impacts to abandoned underground holes (rodent burrows); and revegetation efforts that include native seed mixes to promote an abundance and diversity of native floral resources. Additionally, we recommend supporting and conducting general bumble bee and pollinator surveys.

While the species is not currently known to occur in Colorado, we encourage proactive conservation actions to protect and conserve pollinators and pollinator habitat. Examples include retaining suitable foraging (diversity and abundance of native floral resources), nesting (suitable host colony above or below ground), and overwintering habitat (loose substrates such as leaf litter, duff, rotting logs); maintaining habitat for host bumble bees by avoiding impacts to abandoned underground holes (rodent burrows); and revegetation efforts that include native seed mixes to promote an abundance and diversity of native floral resources. Additionally, we recommend supporting and conducting general bumble bee and pollinator surveys.

Migratory Birds: In addition to responsibilities to protect threatened and endangered species under the Endangered Species Act (ESA), there are additional responsibilities under the Migratory Bird Treaty Act (MBTA) and the Bald and Golden Eagle Protection Act (BGEPA) to protect native birds from project-related impacts. Any activity resulting in take of migratory birds, including eagles, is prohibited unless otherwise permitted by the U.S. Fish and Wildlife Service (50 C.F.R. Sec. 10.12 and 16 U.S.C. Sec. 668(a)). For more information regarding these Acts, see https://www.fws.gov/program/migratory-bird-permit/what-we-do.

It is the responsibility of the project proponent to comply with these Acts by identifying potential impacts to migratory birds and eagles within applicable NEPA documents (when there is a federal nexus) or a Bird/Eagle Conservation Plan (when there is no federal nexus). Proponents should implement conservation measures to avoid or minimize the production of project-related stressors or minimize the exposure of birds and their resources to the project-related stressors. For more information on avian stressors and recommended conservation measures, see https://www.fws.gov/library/collections/threats-birds.

In addition to MBTA and BGEPA, Executive Order 13186: *Responsibilities of Federal Agencies to Protect Migratory Birds*, obligates all Federal agencies that engage in or authorize activities that might affect migratory birds, to minimize those effects and encourage conservation measures that will improve bird populations. Executive Order 13186 provides for the protection of both migratory birds and migratory bird habitat. For information regarding the implementation of Executive Order 13186, please visit https://www.fws.gov/partner/council-conservation-migratory-birds.

Project code: 2025-0117716

We appreciate your concern for threatened and endangered species. The Service encourages Federal agencies to include conservation of threatened and endangered species into their project planning to further the purposes of the Act. Please include the Consultation Code in the header of this letter with any request for consultation or correspondence about your project that you submit to our office.

Attachment(s):

- Official Species List
- USFWS National Wildlife Refuges and Fish Hatcheries
- Bald & Golden Eagles
- Migratory Birds
- Wetlands

OFFICIAL SPECIES LIST

This list is provided pursuant to Section 7 of the Endangered Species Act, and fulfills the requirement for Federal agencies to "request of the Secretary of the Interior information whether any species which is listed or proposed to be listed may be present in the area of a proposed action".

This species list is provided by:

Western Colorado Ecological Services Field Office 445 West Gunnison Avenue, Suite 240 Grand Junction, CO 81501-5711 (970) 628-7180

PROJECT SUMMARY

Project Code:

2025-0117716

Project Name:

Cascade Village Condo

Project Type:

Residential Construction

Project Description: condo

Project Location:

The approximate location of the project can be viewed in Google Maps: https:// www.google.com/maps/@37.64857995,-107.81129202247925,14z



Counties: San Juan County, Colorado

ENDANGERED SPECIES ACT SPECIES

There is a total of 10 threatened, endangered, or candidate species on this species list.

Species on this list should be considered in an effects analysis for your project and could include species that exist in another geographic area. For example, certain fish may appear on the species list because a project could affect downstream species. Note that 2 of these species should be considered only under certain conditions.

IPaC does not display listed species or critical habitats under the sole jurisdiction of NOAA Fisheries¹, as USFWS does not have the authority to speak on behalf of NOAA and the Department of Commerce.

See the "Critical habitats" section below for those critical habitats that lie wholly or partially within your project area under this office's jurisdiction. Please contact the designated FWS office if you have questions.

1. <u>NOAA Fisheries</u>, also known as the National Marine Fisheries Service (NMFS), is an office of the National Oceanic and Atmospheric Administration within the Department of Commerce.

Project code: 2025-0117716

07/03/2025 16:43:53 UTC

MAMMALS

NAME

C. l. r. r. l. t

STATUS

Canada Lynx Lynx canadensis

Threatened

Population: Wherever Found in Contiguous U.S.

There is final critical habitat for this species. Your location does not overlap the critical habitat.

Species profile: https://ecos.fws.gov/ecp/species/3652

Gray Wolf Canis lupus

Experimental

Population: CO

Population,

No critical habitat has been designated for this species. Species profile: https://ecos.fws.gov/ecp/species/4488

Non-Essential

New Mexico Meadow Jumping Mouse Zapus hudsonius luteus

Endangered

There is **final** critical habitat for this species. Your location does not overlap the critical habitat.

Species profile: https://ecos.fws.gov/ecp/species/7965

BIRDS

NAME

STATUS

Mexican Spotted Owl Strix occidentalis lucida

Threatened

There is **final** critical habitat for this species. Your location does not overlap the critical habitat,

Species profile: https://ecos.fws.gov/ecp/species/8196

Southwestern Willow Flycatcher Empidonax traillii extimus

Endangered

There is **final** critical habitat for this species. Your location does not overlap the critical habitat.

Species profile: https://ecos.fws.gov/ecp/species/6749

FISHES

NAME

STATUS

Colorado Pikeminnow Ptychocheilus lucius

Endangered

Population: Wherever found, except where listed as an experimental population

There is **final** critical habitat for this species. Your location does not everlan the critical habitat for the species.

There is **final** critical habitat for this species. Your location does not overlap the critical habitat. This species only needs to be considered under the following conditions:

 Water depletions in the upper Colorado River basin adversely affect this species and its critical habitat. Effects of water depletions must be considered even outside of occupied range.

Species profile: https://ecos.fws.gov/ecp/species/3531

Razorback Sucker Xyrauchen texanus

Endangered

There is **final** critical habitat for this species. Your location does not overlap the critical habitat. This species only needs to be considered under the following conditions:

 Water depletions in the upper Colorado River basin adversely affect this species and its critical habitat. Effects of water depletions must be considered even outside of occupied range.

Species profile: https://ecos.fws.gov/ecp/species/530

INSECTS

NAME	STATUS
Monarch Butterfly <i>Danaus plexippus</i> There is proposed critical habitat for this species. Your location does not overlap the critical habitat.	Proposed Threatened
Species profile: https://ecos.fws.gov/ecp/species/9743 Silverspot Speyeria nokomis nokomis No critical habitat has been designated for this species. Species profile: https://ecos.fws.gov/ecp/species/2813	Threatened
Suckley's Cuckoo Bumble Bee <i>Bombus suckleyi</i> Population: No critical habitat has been designated for this species. Species profile: https://ecos.fws.gov/ecp/species/10885	Proposed Endangered

CRITICAL HABITATS

THERE ARE NO CRITICAL HABITATS WITHIN YOUR PROJECT AREA UNDER THIS OFFICE'S JURISDICTION.

YOU ARE STILL REQUIRED TO DETERMINE IF YOUR PROJECT(S) MAY HAVE EFFECTS ON ALL ABOVE LISTED SPECIES.

USFWS NATIONAL WILDLIFE REFUGE LANDS AND FISH HATCHERIES

Any activity proposed on lands managed by the <u>National Wildlife Refuge</u> system must undergo a 'Compatibility Determination' conducted by the Refuge. Please contact the individual Refuges to discuss any questions or concerns.

REFUGE INFORMATION WAS NOT AVAILABLE WHEN THIS SPECIES LIST WAS GENERATED. PLEASE CONTACT THE FIELD OFFICE FOR FURTHER INFORMATION.

BALD & GOLDEN EAGLES

Bald and Golden Eagles are protected under the Bald and Golden Eagle Protection Act $\frac{2}{3}$ and the Migratory Bird Treaty Act (MBTA) $\frac{1}{3}$. Any person or organization who plans or conducts activities that may result in impacts to Bald or Golden Eagles, or their habitats, should follow appropriate regulations and consider implementing appropriate avoidance and minimization measures, as described in the various links on this page.

- 1. The Bald and Golden Eagle Protection Act of 1940.
- 2. The Migratory Birds Treaty Act of 1918.
- 3. 50 C.F.R. Sec. 10.12 and 16 U.S.C. Sec. 668(a)

There are Bald Eagles and/or Golden Eagles in your project area.

Measures for Proactively Minimizing Eagle Impacts

For information on how to best avoid and minimize disturbance to nesting bald eagles, please review the <u>National Bald Eagle Management Guidelines</u>. You may employ the timing and activity-specific distance recommendations in this document when designing your project/ activity to avoid and minimize eagle impacts. For bald eagle information specific to Alaska, please refer to <u>Bald Eagle Nesting and Sensitivity to Human Activity</u>.

The FWS does not currently have guidelines for avoiding and minimizing disturbance to nesting Golden Eagles. For site-specific recommendations regarding nesting Golden Eagles, please consult with the appropriate Regional <u>Migratory Bird Office</u> or <u>Ecological Services Field Office</u>.

If disturbance or take of eagles cannot be avoided, an <u>incidental take permit</u> may be available to authorize any take that results from, but is not the purpose of, an otherwise lawful activity. For assistance making this determination for Bald Eagles, visit the <u>Do I Need A Permit Tool</u>. For assistance making this determination for golden eagles, please consult with the appropriate Regional <u>Migratory Bird Office</u> or <u>Ecological Services Field Office</u>.

Ensure Your Eagle List is Accurate and Complete

If your project area is in a poorly surveyed area in IPaC, your list may not be complete and you may need to rely on other resources to determine what species may be present (e.g. your local FWS field office, state surveys, your own surveys). Please review the <u>Supplemental Information on Migratory Birds and Eagles</u>, to help you properly interpret the report for your specified location, including determining if there is sufficient data to ensure your list is accurate.

For guidance on when to schedule activities or implement avoidance and minimization measures to reduce impacts to bald or golden eagles on your list, see the "Probability of Presence Summary" below to see when these bald or golden eagles are most likely to be present and breeding in your project area.

NAME

BREEDING SEASON

Golden Eagle Aquila chrysaetos

This is not a Bird of Conservation Concern (BCC) in this area, but warrants attention because of the Eagle Act or for potential susceptibilities in offshore areas from certain types of development or activities.

https://ecos.fws.gov/ecp/species/1680

Breeds Dec 1 to Aug 31

PROBABILITY OF PRESENCE SUMMARY

The graphs below provide our best understanding of when birds of concern are most likely to be present in your project area. This information can be used to tailor and schedule your project activities to avoid or minimize impacts to birds. Please make sure you read "Supplemental Information on Migratory Birds and Eagles", specifically the FAQ section titled "Proper Interpretation and Use of Your Migratory Bird Report" before using or attempting to interpret this report.

Probability of Presence (⋈)

Green bars; the bird's relative probability of presence in the 10km grid cell(s) your project overlaps during that week of the year.

Breeding Season (


Yellow bars; liberal estimate of the timeframe inside which the bird breeds across its entire range.

Survey Effort (|)

Vertical black lines; the number of surveys performed for that species in the 10km grid cell(s) your project area overlaps.

No Data (-)

A week is marked as having no data if there were no survey events for that week.



Additional information can be found using the following links:

- Eagle Management https://www.fws.gov/program/eagle-management
- Measures for avoiding and minimizing impacts to birds https://www.fws.gov/library/collections/avoiding-and-minimizing-incidental-take-migratory-birds
- Nationwide avoidance and minimization measures for birds https://www.fws.gov/sites/default/files/documents/nationwide-standard-conservation-measures.pdf
- Supplemental Information for Migratory Birds and Eagles in IPaC https://www.fws.gov/media/supplemental-information-migratory-birds-and-bald-and-golden-eagles-may-occur-project-action

MIGRATORY BIRDS

The Migratory Bird Treaty Act (MBTA) ¹ prohibits the take (including killing, capturing, selling, trading, and transport) of protected migratory bird species without prior authorization by the Department of Interior U.S. Fish and Wildlife Service (Service).

- 1. The Migratory Birds Treaty Act of 1918.
- 2. The Bald and Golden Eagle Protection Act of 1940.
- 3. 50 C.F.R. Sec. 10.12 and 16 U.S.C. Sec. 668(a)

For guidance on when to schedule activities or implement avoidance and minimization measures to reduce impacts to migratory birds on your list, see the "Probability of Presence Summary" below to see when these birds are most likely to be present and breeding in your project area.

NAME	BREEDING SEASON
Black Swift <i>Cypseloides niger</i> This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/8878	Breeds Jun 15 to Sep 10
Broad-tailed Hummingbird Selasphorus platycercus This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/11935	Breeds May 25 to Aug 21
Cassin's Finch <i>Haemorhous cassinii</i> This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/9462	Breeds May 15 to Jul 15
Clark's Nutcracker <i>Nucifraga columbiana</i> This is a Bird of Conservation Concern (BCC) only in particular Bird Conservation Regions (BCRs) in the continental USA https://ecos.fws.gov/ecp/species/9421	Breeds Jan 15 to Jul 15
Evening Grosbeak Coccothraustes vespertinus This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/9465	Breeds May 15 to Aug 10
Flammulated Owl Psiloscops flammeolus This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/7728	Breeds May 10 to Aug 15
Golden Eagle Aquila chrysaetos This is not a Bird of Conservation Concern (BCC) in this area, but warrants attention because of the Eagle Act or for potential susceptibilities in offshore areas from certain types of development or activities. https://ecos.fws.gov/ecp/species/1680	Breeds Dec 1 to Aug 31
Olive-sided Flycatcher <i>Contopus cooperi</i> This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/3914	Breeds May 20 to Aug 31
Pinyon Jay <i>Gymnorhinus cyanocephalus</i> This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/9420	Breeds Feb 15 to Jul 15

NAME BREEDING SEASON

Virginia's Warbler Leiothlypis virginiae

Breeds May 1 to Jul 31

This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska.

https://ecos.fws.gov/ecp/species/9441

PROBABILITY OF PRESENCE SUMMARY

The graphs below provide our best understanding of when birds of concern are most likely to be present in your project area. This information can be used to tailor and schedule your project activities to avoid or minimize impacts to birds. Please make sure you read "Supplemental Information on Migratory Birds and Eagles", specifically the FAQ section titled "Proper Interpretation and Use of Your Migratory Bird Report" before using or attempting to interpret this report.

Probability of Presence (**)

Green bars; the bird's relative probability of presence in the 10km grid cell(s) your project overlaps during that week of the year.

Breeding Season ()


Yellow bars; liberal estimate of the timeframe inside which the bird breeds across its entire range.


Survey Effort (1)

Vertical black lines; the number of surveys performed for that species in the 10km grid cell(s) your project area overlaps.

No Data (-)

A week is marked as having no data if there were no survey events for that week.





Additional information can be found using the following links:

- Eagle Management https://www.fws.gov/program/eagle-management
- Measures for avoiding and minimizing impacts to birds https://www.fws.gov/library/collections/avoiding-and-minimizing-incidental-take-migratory-birds
- Nationwide avoidance and minimization measures for birds
- Supplemental Information for Migratory Birds and Eagles in IPaC https://www.fws.gov/media/supplemental-information-migratory-birds-and-bald-and-golden-eagles-may-occur-project-action

WETLANDS

Impacts to <u>NWI wetlands</u> and other aquatic habitats may be subject to regulation under Section 404 of the Clean Water Act, or other State/Federal statutes.

For more information please contact the Regulatory Program of the local <u>U.S. Army Corps of Engineers District</u>.

Please note that the NWI data being shown may be out of date. We are currently working to update our NWI data set. We recommend you verify these results with a site visit to determine the actual extent of wetlands on site.

FRESHWATER EMERGENT WETLAND

PEM1C

07/03/2025 16:43:53 UTC

Project code: 2025-0117716

• PEM1D

RIVERINE

R4SBC

Project code: 2025-0117716 07/03/2025 16:43:53 UTC

IPAC USER CONTACT INFORMATION

Agency: SME Environmental Inc.

Name: Nathan Kirker Address: 679 East 2nd Ave

City: Durango State: CO Zip: 81301

Email nkirker@sme-env.com

Phone: 9702599595

ATTACHMENT 5 Cultural Memo

Thank you for submitting a request to the Office of Archaeology and **Historic Preservation!**

If you have requested a cost estimate, we will be in touch once we review the details of your request. Otherwise, we will be in touch as soon as the your request has been completed. If you need to make changes to your request, please reply to this email. The details of your submission are below.

Select a Service File Search

Project Reference Cascade Village Tracts A1-B1

Do you need a cost estimate for this service?

No

Submission Date 06/30/2025

Select a Search Method

Search based on a mapped area

Upload the Search Area

SurveyArea.kmz

Select a Processing

Option

Standard processing: 20 business days

Requestor Name SANDER APLET

Organization or Agency

SME Environmental

Email sander@sme-env.com

Phone Number (720) 217-1694

Address No change to address Select your qualifications.

None of the above applies to me, I understand I will only receive non-sensitive data.

What is the reason for

this request?

Background research for a SHPO consultation, federal or state

permitting activity, or a due diligence project

Terms and Conditions Accepted

Accounts Payable The billing contact is different.

Billing Contact Sean Moore

Billing email <u>smoore@sme-env.com</u>

Billing phone (970) 259-9595

Billing address 679 2ND AVE Unit 8, DURANGO, Colorado, 81301

Terms and Conditions Accepted

Submission number S-999

APPENDIX C March 2025 USEPA Memo regarding "Adjacent Wetlands"



New Guidance on Adjacent Wetlands Under the Clean Water Act

Today the EPA and U.S. Army Corps of Engineers issued a <u>memorandum</u> that clarifies the definition of "adjacent wetlands" under the Clean Water Act (CWA) following the Supreme Court's ruling in Sackett v. EPA (2023). The March 12, 2025 guidance emphasizes that wetlands must have a "continuous surface connection" to a jurisdictional water to be considered adjacent and thus fall under CWA protection.

Key points include:

- Legal Basis: Sackett v. EPA (2023) reaffirmed that wetlands must physically abut a jurisdictional water, rejecting broader interpretations based on hydrologic or intermittent connections.
- New Definition: Wetlands separated by berms, dikes, uplands, or indirect hydrologic features (ditches, swales, pipes, etc.) no longer qualify as adjacent.
- Practical Implications: Field assessments must confirm direct physical contact between a wetland and a jurisdictional water. Previous guidance allowing broader interpretations is rescinded.
- Public Input & Future Steps: The agencies plan to open a public docket titled "WOTUS Notice:
 The Final Response to SCOTUS" for feedback and may issue further guidance.

Overall, the memorandum narrows the definition of adjacent wetlands, aligning with Supreme Court precedent and limiting CWA jurisdiction to wetlands that are physically indistinguishable from abutting waters. Click the link below to learn more about this important memorandum.

			Ä	

Grizzly Peak Water Sales and Distribution, LLC

1424 CR 223

Durango, CO 81301

970 759 1609

swwastewater@yahoo.com

June 20, 2025

To Whom It May Concern:

I am writing in my capacity as the Manager and ORC of Grizzly Peak Water Sales and Distribution, LLC, to confirm that our utility system has the capacity to serve an additional 66 new residential dwelling units, with significant capacity available beyond that number.

Grizzly Peak owns and operates the central water PWSID # CO0156300 and wastewater facilities Discharge permit # CO0039691 serving the Cascade development area. Our infrastructure was originally designed to support a substantially larger number of units than are currently in service, and the system continues to operate well within its engineered design parameters. Our storage, treatment, and distribution systems all have ample reserve capacity.

Grizzly Peak Water Sales and Distribution, LLC is a regulated utility in good standing with the State of Colorado Public Utilities Commission (PUC). We operate in compliance with applicable state regulations and utility service standards. Our facilities are subject to State inspections, and we submit to and pass all required regulatory reviews and inspections as mandated by the PUC.

If you have any questions or require additional documentation, please feel free to contact me directly.

Sincerely

David Marsa

Manager and ORC

Grizzly Peak Water Sales and Distribution, LLC

swwastewater@yahoo.com

TRAUTNER DEFOTE CHLLC

GEOTECHNICAL ENGINEERING, MATERIAL TESTING AND ENGINEERING GEOLOGY

GEOLOGIC HAZARDS ASSESSMENT PROPOSED CASCADE VILLAGE SOUTH TOWNHOME PROJECT DURANGO, SAN JUAN COUNTY, COLORADO

May 16, 2025

PREPARED FOR:

Lauren Davis, AIA, AICP Reynolds, Ash + Associates <u>ldavis@ra-ae.com</u> PROJECT NO. 58565GH

Table of Contents

1.0 REPORT INTRODUCTION	1
1.1 Background and Statute	
1.2 Current Scope of Development	
2.0 GEOLOGIC OVERVIEW	
2.1 Scope of Assessment	
2.2 Geologic Observations	
2.2.1 Regional Geology Discussion	
2.2.2 Local Geology Discussion	
2.2.3 Site Geology Discussion	
3.0 GEOLOGIC HAZARD DISCUSSION	
3.1 Avalanches	
3.2 Landslides	
3.2 Unstable and Potentially Unstable Slopes	10
3.4 Rockfall	1
3.4.1 Source Area 1 Rockfall Hazard Evaluation	12
3.4.2 Rockfall Mitigation Concepts	1.
3.4.3 Source Area 2 Rockfall Hazard Evaluation	
3.4 Expansive Soil and Rock	
3.5 Mud Flows, Debris Flows, Debris Fans and Flood	18
3.7 Radioactivity (Radon Issues)	2
3.8 Seismic Effects	2
3.9 Ground Subsidence	
4.0 CONCLUSIONS	23
5.0 LIMITATIONS	23

ATTACHMENT

Geotechnical Engineering Study, Proposed Cascade Village Townhomes South Project, January 27, 2025, Project No. 58656GE

1.0 REPORT INTRODUCTION

This report presents our Geologic Hazards Assessment for the proposed townhome development north of Purgatory Resort in the Cascade area near Durango in San Juan County, Colorado. This report was requested by Lauen Davis of Reynolds, Ash + Associates and was prepared in accordance with our proposal dated November 4, 2024, Proposal No. 24419P.

As outlined within our proposal for services for this project the client is responsible for appropriate distribution of this report to other design professionals and/or governmental agencies unless specific arrangements have been made with us for distribution.

The following outline provides a synopsis of the various portions of this report;

- ❖ Section 1.0 provides an introduction, background and statute and the scope of the proposed development.
- Section 2.0 provides a geologic setting overview.
- Section 3.0 provides our geologic hazard discussion.
- Sections 4.0 and 5.0 presents our conclusions and limitations.

This geologic hazard study presents our interpretation of the surface characteristics and geologic exposures at the project site. Our hazard assessment is based on our surface observations, a review of available literature, geologic mapping for the area, and on our experience in the area.

1.1 Background and Statute

There are three statutes that were adopted by the Colorado Legislature that are pertinent to geologic hazards and land use. "The Land Use Act" of 1970 established the basis for which later bills could be enforced. The Land Use Act mandated that decisions and authority to develop and enforce land use planning regulations should be conducted at local government levels. Senate Bill 35 was passed in 1972. This bill required that local county governments either adopt a land use planning regulations for subdivisions or follow a model set of regulations developed by the state. In 1974 the Colorado House amended the Land Use Act by adopting House Bill 1041.

House Bill 1041 provided legal definition of natural and geologic hazards. A natural hazard is considered any hazard from geologic conditions, wildfire, or flooding. A geologic hazard is defined as "a geologic phenomenon which is so averse to past, current, or foreseeable construction or land use as to constitute a significant hazard to public health and safety or to property". The geologic hazards identified and defined in HB 1041 include; avalanche, landslide, rockfall, mudflow and debris fans, unstable or potentially unstable slopes, seismic effects, radioactivity and ground subsidence. We have provided excerpts from "Guidelines and Criteria for Identification and Land Use Controls of Geologic Hazard and Mineral Resource Areas", 1974, Rogers, W.P. et al., Special Publication 6, Colorado Geological Survey, in Appendix A which provided legal and descriptive definitions of the geologic hazards outlined in House Bill 1041.

1.2 Current Scope of Development

The project area generally encompasses an approximate 10.5-acre parcel of land acres north of

Purgatory Resort in San Juan County, Colorado. The approximate coordinates of the site are 37.647462°, -107.809476°. The site location is shown on Figure 1.1 below.



Figure 1.1: Site Location Schematic. Adapted from Google Earth (Image Date 12/31/2020).

We understand conceptual plans include 33 to 37 residential townhomes on the site. A conceptual schematic prepared by CHC Engineers, LLC is provided below as Figure 1.2.




Figure 1.2: Conceptual Site Plan prepared by CHC Engineers, LLC.

2.0 GEOLOGIC OVERVIEW

This section provides an overview of our site reconnaissance and literature research for the project site. A description of the site assessment methodology is provided, followed by a discussion of

the regional, local and site-specific geology.

2.1 Scope of Assessment

We performed a geologic field reconnaissance of the site on November 17, 2021. The geologic reconnaissance included detailed observations of the site to evaluate the existence and potential significance of geologic hazards that may influence the proposed development. The general scope of our study included the following;

- Literature and map review of the site.
- Geologic field observations and measurements including a description of the site topography, geologic character and geomorphology.
- Identification and analysis of geologic hazards that may influence the project development and proposed lot layout.

This study focused on the following geologic hazards (these are the hazards defined by HB 1041):

- Avalanche; an evaluation and discussion of the site exposure to avalanche hazards.
- Landslides; identification of landslides in the site vicinity including recommendations for analysis of these features if they exist in areas that will influence the proposed development.
- Rockfall; observations of potential rockfall source areas and identification of areas which may be influenced by rockfall. Computer modeling analysis was performed to quantify hazard potential.
- Expansive soil and rock; an evaluation of the potential for expansive soil and rock was performed based solely on surface observations. A geotechnical engineering study is required to evaluate the extent of the site expansive soil conditions.
- Mudflow and debris fans; identification of areas of the site which may be influenced by debris flow activity.
- Unstable and potentially unstable slopes; identification of potentially unstable and unstable slope areas based on our geologic field reconnaissance and available maps. This is also based on surface observations and is more completely analyzed as part of a geotechnical engineering study.
- Radioactivity; literature review regarding the potential for hazards associated with radiation.
- Seismic effects; identification of local faults and recent activity based on the available literature and field observations.
- Ground subsidence; identification of subsidence prone areas and recent activity based on the available literature and field observations.

A discussion of the hazards as they pertain to the project is included in Section 10.5 of this report.

2.2 Geologic Observations

We have provided a brief discussion of the regional and local geology followed by a more specific discussion of the site geology below to provide background information prior to discussing the site-specific geologic hazard considerations.



2.2.1 Regional Geology Discussion

The site is located in the San Juan Mountains of southwestern Colorado. There are diverse geologic conditions in the area, all of which may have an influence on geologic hazard considerations and land use.

Geologic rock units in the area range from Pre-Cambrian Granite and Gneiss to late Cretaceous to early Tertiary sedimentary shale and sandstone units. Middle to late tertiary volcanic units are common in the Alpine regions of the area. Later quaternary glacial, eolian soils and soil deposits produced by weathering overly the rock units are common. The shale and sandstone rock units and associated soils produced from weathering of these materials are commonly encountered in developed areas.

During the middle to late Cretaceous approximately 80 to 66 million years ago a mountain building episode termed the "Laramide Orogeny" caused regional uplift of the area. The San Juan Dome was formed, the erosional remnant of which exists under the mountainous areas in the region. The San Juan Basin which has since filled with sediment was formed in the area south of the San Juan Mountains. This activity caused upwarping and deformation of the geologic units in the area. This uplift is evidenced nearly everywhere in the region. The sedimentary unit bedding planes all dip (tilt) generally toward the south, and the center of the San Juan Basin. The numerous hogback ridges and cuestas in the area are formed by steeply dipping sedimentary units.

There have been several glacial episodes which have occurred in the area. Glacial moraine and outwash terrace deposits are common in the area. The U-shaped valleys in the region are a testament to the erosional forces imposed by the glaciers.

The steeply dipping geologic units forming the ridges in the area are associated with numerous areas of active landslides and unstable slope areas. In areas where the bedding planes parallel the slope inclinations; translational landslide activity is common. In areas north of Durango, in the north Animas Valley, there are several rotational and multi-unit landslide complex areas where movement was initiated during glacial melt and saturated soil conditions. Many of these areas are located within and immediately adjacent to highly developed areas.

The soils produced by weathering of the sedimentary units in the area often have expansive characteristics, as do many of the eolian deposits. The glacial outwash and alluvial soil deposits are relatively benign, from a development and foundation design perspective. Historic floodplain deposits and wetland areas that are common in the river valleys often contain fine-grained sands and silts that may be unstable and have settlement concerns under foundation loading.

2.2.2 Local Geology Discussion

The Purgatory area is located along the west margin of the Animas River glacio-fluvial valley. Cascade Creek flows from the northwest toward the Animas River and captures Lime Creek on the way. Each of these three drainages were once glaciated. The area north and east of the project site was the confluence of these three glaciers. There are numerous steep gullies in these glacial valleys that flow into the creeks and rivers.



Geologic units in the area consists of Precambrian metasedimentary and igneous units as well as Paleozoic and Mesozoic sedimentary layers of sandstone, limestone, shale and conglomerate. The sedimentary units exposed in the area include the Permian Cutler Formation (Pc), the Permian-Pennsylvanian Hermosa/Rico/Molas Formations undifferentiated (PIPrm) and the Mississippian-Cambrian Leadville Limestone/Ouray Limestone/Elbert Formation/Ignacio Formation undifferentiated (MCli*). These units are generally south dipping and cliff forming. Precambrian Irving Formation (pCi), Twilight Gneiss/Schist (pCtw) and Electra Lake Gabbro (pCel) outcrop east of the site in the West Needle Mountains and along the Animas River. Tertiary volcanics cap the mountains to the north and west of the site. Rock units in the area are often overlain by Quaternary sediments from glacial, fluvial, eolian, mass wasting and colluvial processes that continue to shape the landscape. Quaternary surficial deposits in the site vicinity are mapped as Glacial Drift (Qd) and Alluvium (Qa). A vicinity geologic map is presented in Figure 3.




Figure 2.1: Steven, T.A., Lipman, P.W., Hail, W.J., Barker, Fred, and Luedke, R.G. Geologic map of the Durango quadrangle, southwestern Colorado. United States Geological Survey, Miscellaneous Investigations Series Map I-764, 1974. Map Scale 1:250,000.

2.2.3 Site Geology Discussion

The subject property is a generally north to south trending parcel that encroaches on a relatively steep hillside up to the west down to the Tacoma Flowline and into a relatively flat wetland area on the east side of the parcel. The site is mapped as Hermosa Group; however, within the site boundary we did not observe any formational outcrops. The site is primarily covered by colluvial, debris flow and likely glacially transported deposits in the flatter portion of the site. There are outcrops of Hermosa Group limestone and sandstone above the site, which are a source of potential rockfall debris. We completed a Geotechnical Engineering Study for the site in our report dated January 27, 2025, Project No. 58656GE. We encountered formational sandstone, shale and limestone throughout the site at depths ranging from about 4½ to 32½ feet. Based on these results, the depth to formational material should be assumed to be variable throughout the site. The overburden material on the west side of the site is primarily a mix of clay, sand, gravel, cobbles and boulder that a colluvial and debris flow related. The debris flow deposition is related to a drainage feature at the southwest corner of the project area and is discussed in greater detail in Section 3.5. The east side of the site has wetland soils that likely result from infill of the glacially carved site.

3.0 GEOLOGIC HAZARD DISCUSSION

This geologic hazard study presents our interpretation of the surface characteristics and geologic exposures at the project site. Our hazard assessment is based on our surface observations, a review of available literature, geologic mapping for the area, and on our experience in the area.

As discussed in the scope of service section above, we investigated for evidence that the following geologic hazards may influence the proposed project development;

- Avalanches
- Landslides
- Rockfall
- Expansive Soil and Rock
- Mudflows and Debris Fans
- Unstable or Potentially Unstable Slopes
- Radioactivity
- Seismic Effects
- Ground Subsidence

We have provided a brief discussion of the potential hazards, followed by the observed and predicted conditions.

3.1 Avalanches

Avalanches typically occur on slopes between 30 and 45 degrees in gradient where there is enough snow to cover low-lying vegetation. Avalanche paths generally consist of three parts:

- the starting zone; where avalanches initiate,
- the track; where avalanches reach maximum velocity, and
- the runout zone; where avalanches decelerate and deposit snow and debris.

Avalanche paths can be unconfined, channelized, or a combination of both. In Colorado many avalanche paths are confined by gullies and with the limits of regular/recent activity being defined by the forested areas adjacent to the path.

Trautner Geotech does not provide detailed avalanche studies or mitigation recommendations. We have provided the information above to aid the reader in a general understanding of avalanche hazards. Our commentary below is based our general geologic hazard experience and on our review of literature that is locally available in regard to avalanche hazards.



Basic avalanche hazard mapping is available from San Juan County and is provided below showing the approximate project extents in red.




Figure 3.1: San Juan County Avalanche Hazard Instaar, Engineer Mountain, Colorado, U.S. Geological Survey, June 2, 1976. Arrows represent avalanche pathways. Approximate project area outlined in red.

Based on review of the available mapping there is a potential avalanche path on the south end of the site that may affect some of the southern units. This is consistent with our field observations. We did not observe any recent evidence of large-scale avalanche activity; however, the central drainage feature in this area has relatively sparce tree cover which could be the result of periodic avalanche activity. A photograph of this feature from N. US Highway 550 is provided below.



Photograph 1: View of potential avalanche slide path at south end of site looking west from N. US Highway 550.

Based on our review of available mapping and our site reconnaissance, a conceptual hazard zone may result in impacts to the southern 8 to 10 proposed townhome units as shown below.




Figure 3.2: Conceptuel avalanche hazard zone schematic. Limits of avalanche area should be considered approximately and for general reference purposes only.

The schematic above should be considered approximate and is not suitable for design purposes. This schematic should only be used for conceptual planning purposes. We do not provide detailed avalanche hazard mapping including deposition depths, velocities and runout zones. If the owner is concerned about avalanche risk at the project site and is considering development at the southern

end of the project area, we recommend that an avalanche consultant be contacted.

3.2 Landslides

"Landslide" is a term to describe active slope movement. It is often used in a broad sense to describe any unstable slope or soil movement. A generalized depiction of a typical landslide is shown below.



Landslides may be relatively small slumps or may be larger scale slope failures. Mitigation of active landslides is often difficult and always costly. Evaluation of active landslide areas must include detailed subsurface investigation, laboratory analysis of the soils and detailed engineering analysis/computer modeling as the basis for mitigation design. The subsurface investigation typically includes placement of monitor well (piezometers) and often inclinometers at select locations on the project site.

We performed a site reconnaissance of the project area to identify potential mass movements within or adjacent to the project area. No evidence of large mass movement events in recent history were observed within the project area; however, we did observe suspected shallow surface creep evidenced by geotropism within trees throughout site slopes.



Photograph 2: Typical geotropism (aka tree pistol-butting) along slopes above the site.

We anticipate significant excavations on steeper slopes throughout the site for home sites and infrastructure. Our Geotechnical Engineering Study, which is included as an attachment to this report, provided a limited slope stability analysis along multiple cross sections at the site and may be referenced for slope stability concerns.

Concentrated or poor drainage resulting in saturated soils conditions could reduce the soil strength over the overburden colluvial debris throughout the development. This could increase the risk of future slope failures in steeper slopes. Additional analysis and recommendations are provided below in the Unstable or Potentially Unstable Slopes section of this report.

3.2 Unstable and Potentially Unstable Slopes

As a general standard, any slope with a gradient of 30 degrees or greater is considered potentially unstable, although flatter slopes can be potentially unstable depending on the soil characteristics and subsurface water conditions. Any slope that exhibits evidence of prior movement is considered unstable. Mechanisms of movement in unstable slopes include falls, topples, slides, spreads, and flows. These mechanisms can all be categorized as other hazards discussed in this report. We previously discussed slides and spreads as "landslides" (Section 3.2), falls and topples as "rockfall" (Section 3.4) and flows as "mudflow, debris flow, and debris fans" (Section 3.5). Unstable slope areas may be distinguished from other geologic hazards by the lack of associated

Project No. 58565GH May 16, 2025

definable features; however, the physical processes are analogous. As discussed in Section 3.2 it is a critical concern for construction in potentially unstable and unstable slope areas not to alter the landscape in a way which will increase the potential for movement.

Based on schematic plans, we anticipate cuts into slopes that are greater than 30 percent. Our Geotechnical Engineering Study provided a limited slope stability analysis for existing slope and conceptual cut slopes at the site. Based on the results of the limited analysis, we anticipate marginally stable to stable natural slopes and marginally stable to potentially unstable cut slopes will be encountered across the site. Temporary or permanent excavation shoring will likely be necessary in some locations. We recommend site-specific stability analyses for individual cuts once grading plans have been established.

3.4 Rockfall

Rockfall hazard exists wherever rock has the potential to dislodge and move downhill by forces of gravity. This process is usually associated with a weathering of formational material. Freeze-thaw cycles and availability of free water promote rockfall; therefore, spring is the most active season for rockfall. The steep topography and fractured rock outcrops that are common to this region make rockfall a common hazard.

Rockfall can occur without warning and can be destructive to both life and property. Rockfall frequency is very difficult to predict, but modeling techniques allow us to estimate the trajectory and intensity of rockfall events. Simulation of rockfall events to provide an analysis of the potential destructive properties are typically performed using field mapping and observations in addition to computer modeling analysis.


Outcrops of the Hermosa Group sandstone and limestone above the site are potential source areas for rockfall hazard into the proposed development areas. Two main source areas were identified, one at the north end of the site and one at the south end of the site. The general source areas are identified below.



Figure 3.2: Location of Rockfall Source Areas.

3.4.1 Source Area 1 Rockfall Hazard Evaluation

The source area at the north end of the site consists of an approximate 50 foot tall cliff exposure of the Hermosa Group sandstone. The source area is roughly 300 to 350 feet up slope from the proposed northern townhome units. The source area was observed to be highly fractured. Evidence of recent rockfall activity along the slope below the source area was observed during our site reconnaissance. A photograph of the source area is provided below.



Photograph 1: View of Source Area 1.

We conducted our rockfall analysis using the RocScience RocFall® 2020 (RocFall) rockfall modeling software to predict rockfall behavior at the subject property. The RocFall program is a tool to predict rockfall behavior and to assist in the design of rockfall protection measures. We created a topographic profile using field measurements with a Brunton compass, GPS, range finder and measuring tape. The topographic profile was input into the RocFall model. We utilized RocFall to simulate the existing conditions at the subject property. The RocFall model's input parameters such as surface roughness, vegetation, tangential and normal and dynamic and rolling friction coefficients were manipulated to approximate the existing conditions. Once we were satisfied that we had simulated the existing conditions, we performed numerous iterations of theoretical rockfall with the program while varying sizes and shapes of rocks to model the rockfall behavior at the proposed development. The approximate analysis profile is shown in Figure 3.3

below which also includes the approximate hazard zone. We have also included our RocFall analysis profile as Figure 3.4.



Figure 3.3: Approximate Location of Rockfall Analysis Profile and approximate hazard zone.




Figure 3.4: Topographic profile used in RocFall analysis.

Based on our site observations and analysis, rocks have the potential to move from the source area down to the assumed edge of building sites (X = 150 feet). The approximate hazard zone includes the northern eight townhome units on the current site development plan. This location was chosen as a likely location for rockfall mitigation fencing; however, it must be understood that rockfall impact energy and bounce heigh will vary at different locations along the slope profile. Below, we have provided graphical representation of the estimated bounce heights and total kinetic energy values for various sizes and shapes of rocks observed calculated along the slope. As shown, bounce heights and energy values vary greatly at different points along the slope; however, most rocks were shown reach the development area as shown below on the Distribution of Rock Path End Locations, Figure 3.5.




Figure 3.5: Distribution of Rock Path End Locations.

At the analysis point, we estimated total kinetic energy of about 200,000 foot-pounds (approximately 270 kilojoules). Bounce heights were highly variable in the model which is fairly typical. Highest values were up to about 19 feet; however of the 130 rocks analyzed that reach the analysis point, 117 (90%) of those rocks have a bounce height of 10 feet or less with the majority (79 rocks) with a bounce height of 1 foot or less.




Figure 3.6: Bounce Height distribution table at analysis point (X=150)




Figure 3.7: Total Kinetic Energy distribution table at analysis point (X=150)

Our rockfall analysis included "typical" design rocks based on our site observations of recent rockfall debris and fracture patterns within the source area rock. These rocks represent most typical or likely rockfall debris within the hazard zone. However, larger rocks outside of the normal range are possible. One rock over 10 feet in diameter was observed at the base of the slope; however, it is unclear whether this rock was related to a rockfall event or transported by other means. Our analysis does not include non-typical rocks as these are considered to be very rare an unlikely events. However, it should be noted that larger atypical rocks may not be mitigatable by conventional mitigation methods discussed later this this report.

3.4.2 Rockfall Mitigation Concepts

Based on the evaluation above, the proposed townhomes below Source Area 1 are within a potential rockfall hazard zone and additional mitigation is warranted. This section provides mitigation concepts and alternatives for hazard reduction at the site. Typical mitigation concepts include:

- Avoidance of the areas influenced by the hazard,
- Scaling or in-place stabilization of rocks prone to movement, and,
- Design and construction of arrest barriers, typically:
 - Rockfall mitigation fencing, and/or
 - Earthen trough and berms
 - Rigid Architectural Barriers

Often a select combination of one or more of these types of mitigation are included in rockfall hazard mitigation. We have provided a brief discussion of these concepts including how they pertain to this project.

Avoidance - Although avoidance of a particular hazard, such as rockfall is always the best option, this is not always possible due to property boundary, topographic, or other constraints imposed by a particular project site. Often slight changes in structure location, orientation, and/or elevation can influence the exposure to or severity of rockfall hazards. It must be understood that there are many variables that go into rockfall hazard prediction and relatively small changes in the model input parameters can alter the results;

Project No. 58565GH May 16, 2025

therefore, the owner/developer should consider what, if any, factors of safety to consider in structure placement.

Scaling or In-place Stabilization of Rocks Prone to Movement - A relatively common mitigation for rockfall includes scaling, movement of rocks downslope prior to construction, and/or in-place stabilization. These efforts are largely conducted with hand labor and hand tools. Some in-place stabilization can be developed by the use of rock bolts or other aggressive means requiring the use of pneumatic drilling equipment and other techniques. Blasting is also a form of scaling. Often larger rocks may be blasted, with hand-scaling or in-place stabilization performed on the smaller rocks produced from the blasting effort. Due to the magnitude of rock source areas above the site, scaling and/or in-place stabilization is not likely a feasible alternative for the project site.

Rockfall Mitigation Arrest Barriers

There are numerous types of arrest barriers commonly included in rockfall mitigation. Perhaps the most common types being;

- Earthen trough and berm configurations, and
- Flexible rockfall mitigation fencing
- Architectural Design Strategies

Earthen Trough and Berm Configurations

Earthen trough and berms and flexible rockfall mitigation fencing are common mitigation strategies utilized in the area. However, due to the steepness of the slope above the site and limited property line setbacks, these strategies were determined not to be feasible alternatives for the site. We can provide more details regarding an earthen berm/trough upon request.

Flexible Rockfall Mitigation Fencing

Rockfall mitigation fencing has been used successfully within the Southwest Colorado area for many projects. Rockfall mitigation fencing is typically designed by an engineer or contractor with experience in rockfall mitigation. Many manufacturers of rockfall fencing have design capabilities and may utilize information provided in reports such as this to develop a design that is based on the impact energies estimated through the use of computer modeling, such as our RocFall analysis. Rockfall fence design is typically based on an impact energy, or total kinetic energy, and a maximum bounce height. The energy from a rockfall event and the bounce height can vary greatly based on the size of rock and location along the slope. For the purposes of this investigation, we have assumed a rockfall mitigation fence will likely be located along the slope at a location on the west property boundary (x=150). Based on our analysis, maximum impact energies at this location will be approximately 270 kilojoules for the typical rocks analyzed. Typical bounce heights were 10 feet or less; however, less common higher bounce heights were also modelled.

However, anisotropies in the model and variations in the slope can alter the estimated impact energies and bounce heights. Larger rocks are possible with higher impact energies. Appropriate factors of safety should be added by the designer, as necessary. We recommend a minimum fence design of 500 kilojoules with a minimum height to 10 feet to accommodate typical rockfall events. If higher factors of safety are desired to accommodate less typical, but still possible, events a more robust fence system may be considered. Further, our estimated energy and bounce height only applies to one location along the slope and variations will occur at different locations. Once the final residence and fence location has been chosen, we should be contacted to re-evaluate our analysis.



Project No. 58565GH May 16, 2025

Flexible rockfall fencing is available from two main manufacturers, Geobrugg and Maccaferri. Fence heights and impact energy ratings vary per the manufacturer and necessary design configurations. We do not provide design of rockfall mitigation fencing systems; however, we are available to assist the design team, as necessary.

Architectural Design Strategies

Architectural design strategies are commonly included on structures that are located within rockfall hazard area of low to moderate probability or as an additional protective measure against potential rockfall events. Typical design concepts include locating high occupancy rooms with the structure away from the up-slope side of the proposed structure where rockfall impacts are likely to occur. Low occupancy rooms such as laundry, utility or storage areas, and hallways are best located on the side of the structure where impacts associated with rockfall activity are likely to occur. Windows on the upslope side should be avoided, if possible. Windows should be generally of smaller size, where necessary, and they should be placed as high as possible. Architectural design strategies may be prudent for this project; however, due to the impact energies and bounce heights calculated, these strategies are not likely feasible as a first defense against rockfall impacts.

Rigid Concrete Barriers

Rigid concrete barriers can be utilized successfully in some cases; however, there are some limitations. The impact energies associated with rockfall events are often too great to accommodate reasonable structural design strategies relative to rigid barriers. Rigid barriers can also propagate much of the impact energy into the structure resulting in potential for severe structural damage to both the interior and exterior of the structure. Separation of the barrier can result in less damage propagated to the habitable portion of the structure. The owner, designer and structural engineer should evaluate the feasibility of a rigid barrier for the impact energies and bounce heights associated with potential rockfall events at the site.

3.4.3 Source Area 2 Rockfall Hazard Evaluation

The southern source area (Source Area 2) is located nearly twice as high on the slope as Source Area 1 and is located above the southern portion of the of the project area as shown on Figure 3.2 above. The approximate analysis profile is shown in Figure 3.8 below. We have also provided our RocFall profile which is provided below as Figure 3.9.



Figure 3.8: Approximate RocFall Analysis Profile.




Figure 3.9: Topographic profile used in RocFall analysis.

Based on our site observations and analysis, rocks have the potential to move from the source area down the slope; however, no rocks were modeled to impact the building sites. This analysis is consistent with the observed conditions in the field. Based on our observations and analysis, it is our opinion that the site is not located within a rockfall hazard zone and no mitigation or additional analysis is considered warranted at this time below Source Area 2.

3.4 Expansive Soil and Rock

Uplift associated with swelling soils typically occurs only where the foundation support soils have been exposed to water; therefore, the uplift may impose shear stresses in the foundation system. The magnitude of the imposed shear stress is related to the swell pressure of the support soil, but is difficult to estimate. Properly designed and constructed foundation systems have the ability to distribute the forces associated with swelling of the support soil. We performed a Geotechnical Engineering Study concurrently with this geologic hazard assessment. Geotechnical considerations related to expansive soils can be found under our attached Geotechnical Engineering Study.

3.5 Mud Flows, Debris Flows, Debris Fans and Flood

Mud flows and debris flows initiate in drainage basins during significant precipitation when large concentrations of sediment become entrained and flow down-slope, often carrying boulders and organic debris within a matrix of clay and water. Debris fans are areas where debris flows or mud flows deposit material that spreads out in a fan-like shape at the mouth of channels where the smaller, steeper channels meet larger, low gradient stream valleys. Debris flows and mud flows contain larger concentrations of entrained solids than floods and move with high energy down steep slopes, thus they can be very destructive. Historically, debris flows are more threatening to property than to life. Debris flows differ from mud flows in that they contain larger material (debris) the size and weight of which is mostly limited by availability and channel size, not the

Project No. 58565GH May 16, 2025

ability of the flow to transport. Because of this they tend to be more destructive and so debris flows will be the focus of this report.

Debris flows have return periods similar to floods, and often flooding occurs in conjunction with debris flow events. There are four conditions that must be present within a basin in order for it to be susceptible to debris flow (Mears, 1977).

- Sufficient loose sediment/debris
- Sufficient clay content of sediment
- Sufficient gradient of the channel and slopes
- Low ratio of available water to available debris

If all of these conditions are met, a precipitation event of sufficient intensity and/or duration can trigger a debris flow. Processes of damming and pooling can serve to increase the likelihood and/or magnitude of a debris flow event relative to the precipitation event that triggers it. Stream drainage basins that have been denuded of vegetation due to fire are particularly prone to debris flow activity. When present, these conditions combine to facilitate debris flows by increasing viscosity, strength, entrainment, and energy of captured precipitation. Otherwise, if the conditions are not met, the same precipitation event would instead trigger a flood.

Debris flows transport boulders and debris along the upper surfaces of flow (Mears, 1977). This means that the greatest impacts from debris flows occur along this upper surface elevation which can be several feet above ground level. Channelization of debris flows is not always a given, particularly at the debris fan below the mouth of the drainage. Debris flows can vacate a channel by a process known as avulsion, in which a previous debris deposit can block and divert subsequent flow. Debris flows also exhibit confined flow on unconfined surfaces due to shearing off of material from the margins leaving behind lateral levee deposits and thereby creating its own channel as it flows. These factors dictate that the entirety of a debris fan surface is susceptible to flow hazards that can exist several feet above the ground. Often development and proposed development that is affected by debris flow hazard is located on these debris fans.

Based on our site reconnaissance, and review of available literature, the southern portion of the site is located within a potential debris flow hazard area. The hazard area is generally located in the same drainage feature as the avalanche hazard risk area identified in Section 3.1 above which is not uncommon. Basic geologic hazard mapping is available from San Juan County and is provided below showing the approximate project extents in red.




Figure 3.10: San Juan County Geologic Hazard Map Instaar, Engineer Mountain, Colorado, U.S. Geological Survey, June 2, 1976. Approximate project area outlined in red.

We performed a site reconnaissance of the potential debris flow area and outlined some approximate boundaries of the potential hazard zone. It must be noted that the schematic provided below should be considered appropriate and does not constitute a full engineering debris flow analysis including extent, deposition depths and flow velocities, which may be required for development in this area. There are engineering firms who specialize in these analyses.

We did not observe any recent debris flow activity within the hazard zone; however, the site represents a classic debris flow zone with debris fan. The hazard zone originates within a channel up slope, just north of another cliff band south of the site. The channel flows into a wide debris fan with hummocky terrain characterized by abundant boulders that are imbedded in the historic deposition area. A schematic showing the approximate extent of the debris fan is provided below. A similar number of units are potentially affected by the debris flow hazard as was affected by the avalanche hazard. Roughly the southern 10 units are affected. If development is planned in this area a debris flow specialist should be consulted.



Figure 3.11: Debris flow and fan hazard area outlined on the site schematic.

3.7 Radioactivity (Radon Issues)

Many soils and formational materials in western Colorado produce radon gas. Radon is a radioactive gas that forms from the natural breakdown of uranium in soil, rock and water. There are no known sources of radioactivity on the site. However, according to the San Juan Basin Public Health Department, the average radon level in La Plata County homes exceed 4pCi/L. The Environmental Protection Agency recommends radon mitigation in homes with levels higher than 4 pCi/L. Radon tends to accumulate in poorly ventilated areas below ground level; however, radon may accumulate inside any above- or below-grade construction. According to the EPA, elevated radon levels in buildings can be reduced by several methods, including pressurization of the building using a heating, ventilating and air-conditioning system, sealing of cracks in foundation walls and floor slabs which may allow entry of radon, and using active soil depressurization (ASD) systems. If radon gas is a concern in the completed structures, as specialist in radon mitigation should be consulted.

3.8 Seismic Effects

Seismic effects manifest in the form of earthquakes and volcanic activity. Seismic effects are evidenced in the geologic record by faulting and jointing of formational materials. Earthquakes experienced by humans in recent history have been monitored, recorded, and compiled in databases; locally the "Colorado Geological Survey's Colorado Late Cenozoic Fault, Fold and Earthquake Database". Earthquakes cause damage by ground shaking, surface rupture and other deformation, liquefaction, and Tsunamis. The orogenic history of the region (refer to Section 3) was accompanied with a multitude of seismic effects. These seismic effects have since largely subdued. Colorado is considered to be outside of the high risk area of the western US (Nuhfer et al., 1993). The modern seismic environment in the region is relatively benign, however not insignificant. Several formidable events have been recorded in the Dulce, New Mexico area south

Project No. 58565GH May 16, 2025

of Pagosa Springs. Mitigation of seismic effects is typically included in the structural design and requirements are based on zoning.

The most recent earthquake activity in the region of the project site occurred along the Ridgway Fault on November 21, 2006 with a magnitude of 3.3 on the Richter scale and a Modified Mercalli Intensity of III. The Ridgway fault is defined by a 1,500 foot high fault-line scarp, but there is no observable surface rupture in middle to late Quaternary deposits indicating no recent activity that has manifested at the ground surface. Although this fault is considered to be potentially active, the recent activity on the fault, such as the 2006 event mentioned above as well as the November 19, 1989 event with a magnitude of 3.0, are low intensity, non-destructive

events. Other seismic activity in the region occurred in Ouray, CO on November 22, 1989 with a magnitude of 2.9 on the Richter scale, and in the Telluride vicinity in 1894. Based on newspaper accounts from this time it was rated as IV on the Modified Mercalli Scale. This information was obtained from the Colorado Geologic Survey, Earthquake and Late Cenozoic Map Server.

Although seismic activity has occurred in recent history, the low magnitude and lack of proximity to plate boundaries indicate that there is a low hazard related to seismicity at the project site. Due to the low seismic effect hazard at this site we do not feel that mitigation practices outside of that which is required by building codes is necessary.

3.9 Ground Subsidence

Ground subsidence is the process by which ground level rapidly drops. This drop is often related to an undermining of the material present at the surface, but may also occur from tectonic processes and hydrocompaction (a process related to increased water content of soils). Undermining of material is caused by solubility, karst topography, fluid withdrawal, and mining. Subsidence due to undermining is often termed a "sinkhole"; descriptive of the manifestation of the subsidence at the surface as the once overlying material collapses into a void beneath. Mined localities are particularly susceptible to ground subsidence because of the unnatural state in which they are fashioned (Coduto, 1999).

Mine sites in the region likely present the highest risk areas for ground subsidence. No known mine adits or subsidence prone materials exist at or under the project site. There is no evidence of ground subsidence at the project site. Very low strength wetland soils encountered at the site may also pose a risk of ground subsidence specifically in the vicinity of Borings TB-10, -11 and -12 in our Geotechnical Engineering Study as shown below.



Figure 3.10: Locations of Exploratory Borings.

Structures located in wetland areas on the east side of the main access road have low strength soils which are prone to settlement under foundation loads. Therefore, as noted our earlier study, these structures should be supported with deep foundation systems supported by the underlying formational materials. Typical shallow foundation systems are not suitable for support in these areas.

4.0 CONCLUSIONS

Based on our site observations and analysis, geologic hazards should be considered a major driving factor as to the feasibility of the proposed development. As discussed in Section 3, there are multiple considerations regarding geologic hazards, specifically avalanche, rockfall, potentially unstable slopes, and debris flow characterization. Additional analysis will likely be required regarding avalanche and debris flow unless development can be avoided in the southern portion of the site.

5.0 LIMITATIONS

This study has been conducted based on the engineering geology standards of care in this area at the time this report was prepared. We make no warranty as to the analysis contained in this report,

Project No. 58565GH May 16, 2025

either expressed or implied. The information presented in this report is based on our understanding of the proposed subdivision that was provided to us and on the data obtained from our field study.

The analysis presented above are intended to be used only for this project site and the proposed construction which was provided to us. The analysis presented above are not suitable for adjacent project sites, or for proposed construction that is different than that outlined for this study.

This report does not provide an environmental assessment nor does it provide environmental recommendations such as those relating to Radon or mold considerations. If recommendation relative to these or other environmental topics are needed and environmental specialist should be contacted.

The findings of this report are valid as of the present date. However, changes in the conditions of the property can occur with the passage of time. The changes may be due to natural processes or to the works of man, on the project site or adjacent properties. In addition, changes in applicable or appropriate standards can occur, whether they result from legislation or the broadening of knowledge. Therefore, the recommendations presented in this report should not be relied upon after a period of two years from the issue date without our review.

We are available to review and tailor our recommendations as the project progresses and additional information which may influence our recommendations becomes available.

Please contact us if you have any questions, or if we may be of additional service.

Respectfully, TRAUTNER GEOTECH

Jason A. Deem, P.G.

Principal Engineering Geologist

Reviewed by: TRH

ATTACHMENT

Geotechnical Engineering Study, Proposed Cascade Village Townhomes South Project

January 27, 2025

Project No. 58656GE



GEOTECHNICAL ENGINEERING, MATERIAL TESTING AND ENGINEERING GEOLOGY

GEOTECHNICAL ENGINEERING STUDY PROPOSED CASCADE VILLAGE TOWNHOMES SOUTH PROJECT SAN JUAN COUNTY, COLORADO

January 27, 2025

PREPARED FOR:

LAUREN DAVIS, AIA, AICP

REYNOLDS ASH + ASSOCIATES ARCHITECTURE & ENGINEERING 564 E. 2nd AVE., SUITE 201 DURANGO, CO 81301 p. 970-259-7494

e. Idavis@ra-ae.com w. www.ra-ae.com

PROJECT NO. 58656GE

Table of Contents

1.0 REPORT INTRODUCTION	
1.1 Proposed Construction	2
2.0 FIELD STUDY	2
2.1 Site Description and Initial Geological Hazard Discussion	2
2.2 Subsurface Soil and Water Conditions	
3.0 LABORATORY STUDY	5
4.0 FOUNDATION RECOMMENDATIONS	7
4.1 Shallow Foundation System Concepts	7
4.1.1 Spread Footings	8
4.1.2 General Shallow Foundation Considerations	12
4.2 Deep Foundation System Concepts	13
4.2.1 Helical Piers Error!	Bookmark not defined.
4.2.2 Driven Piles	
4.2.3 Grade Beams	14
5.0 RETAINING STRUCTURES	15
6.0 LIMITED SLOPE STABILITY ANALYSIS	16
7.0 SUBSURFACE DRAIN SYSTEM	27
8.0 CONCRETE FLATWORK	29
8.1 Interior Concrete Slab-on-Grade Floors	29
8.1.1 Capillary and Vapor Moisture Rise	30
8.1.2 Slab Reinforcement Considerations	31
8.2 Exterior Concrete Flatwork Considerations	31
8.3 General Concrete Flatwork Comments	32
9.0 PAVEMENT SECTION THICKNESS DESIGN RECOMMENDATIONS	33
9.1 Traffic Estimates	
9.2 Asphalt Pavement Design Recommendations	34
9.3 General Asphalt Pavement Recommendations	
9.4 Portland Cement Concrete Pavement Recommendations	
10.0 CONSTRUCTION CONSIDERATIONS	37
10.1 Fill Placement Recommendations	
10.1.1 Subgrade Soil Stabilization	38
10.1.2 Embankment Fill on Slopes	38
10.1.2 Natural Soil Fill	40
10.1.3 Granular Compacted Structural Fill	40
10.1.4 Deep Fill Considerations	41
10.2 Excavation Considerations	41
10.2.1 Excavation Cut Slopes	42
10.3 Utility Considerations.	42
10.4 Exterior Grading and Drainage Comments	43
10.5 Landscaping Considerations	43
10.6 Soil Sulfate and Corrosion Issues	44
10.7 Radon Issues	45
10.8 Mold and Other Biological Contaminants	45
11.0 CONSTRUCTION MONITORING AND TESTING	45
12.0 CONCLUSIONS	46
13.0 LIMITATIONS	46
FIELD STUDY RESULTS	Appendix A
Log of Test Borings	_ -
LABORATORY TEST RESULTS	Appendix B
Sieve and Atterberg Limit Test Results	
Swell-Consolidation Test Results	
Direct Shear Test Results	
California Bearing Ration Test Results	



1.0 REPORT INTRODUCTION

This report presents our geotechnical engineering recommendations for the proposed Cascade Village Townhomes South project located south of Cascade Village in San Juan County, Colorado. This report was requested by Ms. Lauren Davis, AIA, AICP, Reynolds, Ash, and Associates and was prepared in accordance with our proposal dated November 4, 2024, Proposal No. 24419P.

As outlined within our proposal for services for this project the client is responsible for appropriate distribution of this report to other design professionals and/or governmental agencies unless specific arrangements have been made with us for distribution.

Geotechnical engineering is a discipline which provides insight into natural conditions and site characteristics such as; subsurface soil and water conditions, soil strength, swell (expansion) potential, consolidation (settlement) potential, and often slope stability considerations. The information provided by the geotechnical engineer is utilized by many people including the project owner, architect or designer, structural engineer, civil engineer, the project builder and others. The information is used to help develop a design and subsequently implement construction strategies that are appropriate for the subsurface soil and water conditions, and slope stability considerations. We are available to discuss any aspect of this report with those who are unfamiliar with the recommendations, concepts, and techniques provided below.

This geotechnical engineering report is the beginning of a process involving the geotechnical engineering consultant on any project. It is imperative that the geotechnical engineer be consulted throughout the design and construction process to verify the implementation of the geotechnical engineering recommendations provided in this report. Often the design has not been started or has only been initiated at the time of the preparation of the geotechnical engineering study. Changes in the proposed design must be communicated to the geotechnical engineer so that we have the opportunity to tailor our recommendations as needed based on the proposed site development and structure design.

The following outline provides a synopsis of the various portions of this report;

- Sections 1.0 provides an introduction and an establishment of our scope of service.
- Sections 2.0 and 3.0 of this report present our geotechnical engineering field and laboratory studies
- Sections 4.0 and 5.0 presents our geotechnical engineering design parameters and recommendations which are based on our engineering analysis of the data obtained.
- Section 6.0 presents our limited slope stability study.
- Section 7.0 presents our subsurface foundation drain recommendations.
- Section 8.0 presents our concrete flatwork recommendations.
- Section 9.0 presents our pavement section thickness design.
- Section 10.0 provides a brief discussion of construction sequencing and strategies which may influence the geotechnical engineering characteristics of the site. Ancillary information such as some background information regarding soil corrosion and radon considerations is also presented as general reference.
- Section 11.0 provides our general construction monitoring and testing recommendations.
- Sections 12.0 and 13.0 provides our conclusions and limitations.



The data used to generate our recommendations are presented throughout this report and in the attached figures.

All recommendations provided within this report must be followed in order to achieve the intended performance of the foundation system and other components that are supported by the site soil.

1.1 Proposed Construction

We reviewed a conceptual site plan prepared by CHC Engineers, LLC, at the time of this report. We understand that the proposed project will consist of designing and constructing 33 duplex townhome structures that are supported by steel reinforced concrete foundation systems. We assume relatively light foundation loadings, typical of the proposed type of construction.

We anticipate grading for some of the structures along the western portion of the site will need to include up to 15-foot restrained excavation cuts, and the grading for the remaining structures are assumed to be relatively minor with cuts of approximately 5 to 6 feet below the adjacent ground surface.

As discussed in our proposal for services, the project will require temporary and/or permanent shoring. Trautner Geotech does not provide shoring design or observations of shoring systems. A shoring design engineer will need to be consulted to provide a stamped/sealed engineering design for the project shoring needs. The selected shoring design engineer will need to perform their own slope stability analyses based on the project excavations in conjunction with their shoring design. The selected shoring design engineer will need to take the appropriate steps to verify that the actual exposed subsurface conditions including soil strength characteristics, subsurface water characteristics and fracture patterns within the formational materials are consistent with their shoring design. It is imperative that the selected shoring design engineer and structural engineer work closely to coordinate the shoring design with the structural design of the project.

When final building locations, grading and loading information have been developed, we should be notified to re-evaluate the recommendations presented in this report.

2.0 FIELD STUDY

2.1 Site Description and Initial Geological Hazard Discussion

The project site is located at the south end of Cascade Village. The ground surface ranges from relatively steep slopes down to the east along the western portion of the property to relatively flat ground on the eastern portion of the site. The Tacoma Water Line running north to south bisects the property.

Due to the approximately 2 to 3 feet of snow on the ground at the time of our field study, we could not perform our geological hazard study for the site. We will need to wait until spring or early summer once the snow melts to further assess the geological hazards potentially impacting the site. Based on our initial observations, we feel the following geological hazards may exist;

- Debris flow/alluvial fan deposits in the southern portion of the site.
- Rockfall potential along portions of the western side of the site.
- Avalanche potential along portions of the western side of the site.
- Ground subsidence in wetland areas of the eastern side of the site.

Our geological hazard study will not provide detailed debris flow or avalanche hydrologic calculations and mapping. If required, we can provide recommendations for additional assessment.

2.2 Subsurface Soil and Water Conditions

We advanced sixteen test borings in the vicinity of the proposed structures and five shallow test borings in the vicinity of the proposed roadways. A schematic showing the approximate boring locations is provided below as Figure 1. The logs of the soils encountered in our test borings are presented in Appendix A.



Figure 1: Locations of Exploratory Borings. Adapted from a site plan prepared by CHC Engineers LLC.

The schematic presented above was prepared using notes and field measurements obtained during our field exploration and is intended to show the approximate test boring locations for reference purposes only.

The subsurface conditions encountered in our test borings consisted of various combinations of silty, sandy, lean clay with organics, (CL), clayey gravel and cobbles with boulders (GC), and formational material encountered at various depths. Formational shale, sandstone or limestone was encountered at depths that ranged from 6.5 to 32.5 feet. Practical auger refusal or termination of the test borings occurred within 2 to 3 feet into the formational material.

We encountered high organic content soils/peat to depths of 21.5 feet in TB-11, 8 feet in TB-12, and 4.5 feet in TB-13. Based on the laboratory consolidation, we suspect this area will experience high consolidation under any new loading from either structures or man-placed fill.

We encountered free subsurface water in some of our test borings at the time of the advancement. The ground water depths are tabulated below.

Test Boring	Ground Water
Number	Depth (feet)
TB-8	16
TB-9	18
TB-10	10
TB-11	2
TB-12	2
TB-13	2
TB-16	4

We suspect that the subsurface water elevation and soil moisture conditions will be influenced by snow melt and/or precipitation and local irrigation.

The logs of the subsurface soil conditions encountered in our test borings are presented in Appendix A. The logs present our interpretation of the subsurface conditions encountered in the test borings at the time of our field work. Subsurface soil and water conditions are often variable across relatively short distances. It is likely that variable subsurface soil and water conditions will be encountered during construction. Laboratory soil classifications of samples obtained may differ from field classifications.

3.0 LABORATORY STUDY

The laboratory study included tests to estimate the strength, swell and consolidation potential of the soils tested. We performed the following tests on select samples obtained from the test borings. The laboratory test results are provided in Appendix B.

- Moisture Content and Dry Density
- Sieve Analysis (Gradation)
- Atterberg Limits, Liquid Limit, Plastic Limit and Plasticity Index
- Swell Consolidation Tests
- Direct Shear Strength Test



- Moisture Content Dry Density Relationship Test
- California Bearing Ratio Test

A synopsis of some of our laboratory data for some of the samples tested is tabulated below.

Sample Designation	Percent Passing #200 Sieve	Atterberg Limits LL/PI	Moisture Content (percent)	Dry Density (PCF)	Measured Swell Pressure (PSF)	Swell or Consolidation Potential	Phi (°)	Cohesion (PSF)
TB-1 @ 3'	•	-	8.2	112.7	4,000*	6.0 (% under 100 psf load)	:+0	æ
TB-2 @ 2'	523	ŝ	12.9	86.8	3,370*	6.0 (% under 100 psf load)	-	μ
TB-2 @ 5-9'	30.8	23/10	6.1	2	3 0	9 3	·	:
TB-3 @ 3.5'	3€ 7	-	10.0	112.8	5,000*	7.6 (% under 100 psf load)	-	*
TB-4 @ 5-9'	7 4)	¥	9.2	*	:=:	(4)	30	100
TB-5 @ 3.5-8.5'	31.2	22/8	6.3	语	120	2 .		ā
TB-6 @ 8.5'	*	Ti.	6.4	140.7	0	-0.8 (% under 500 psf load) 0.3	•	Ê
TB-7 @ 2*	(5)	=	12.7	125.7	350	(% under 100 psf load)	(3)	5
TB-8 @ 3.5'	180	Ħ	5.4	128.6	720	1.2 (% under 100 psf load)	32	8
TB-8 @ 14-19`	\$ 2 .0		8.3	iff	20	(2)	30	85
TB-9 @ 3.5'	. 5 0	Te	7.8	119.8	1,860*	0.8 (% under 500 psf load)	•	3
TB-9 @ 5-9'	46.5	32/13	15.8	-	9	*	3	Ē
TB-10 @ 3.5'	120	ш	10.7	111.0	360	1.1 (% under 100 psf load)	(*)	말
TB-10 @ 4.5- 8.5'	40.7	38/16	26.0	2	-	26	(S)	¥
TB-11 @ 4'	(4).	æ	93**	7.0**	0	-0.1** (% under 100 psf load) 0.2	(4 8	¥
TB-14 @ 3.5'	520	-	5.3	127.0	270	(% under 100 psf load)	120	=
TB-15 @ 0-3.5'	63.4	42/22	33.7	2	47	*		¥
TB-15 @ 3.5'	= 3	٥	23.4	103.2	0	-0.2 (% under 100 psf load) -0.1	7 4 0	ä
TB-16 @ 3.5'	= 0	2	26.0	99.3	0	-0.1 (% under 100 psf load)		